

PIC16F1934/1936/1937 and PIC16LF1934/1936/1937 Family Silicon Errata and Data Sheet Clarification

The PIC16F1934/1936/1937 and PIC16LF1934/1936/1937 family devices that you have received conform functionally to the current Device Data Sheet (DS41364**D**), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in Table 1. The silicon issues are summarized in Table 2.

The errata described in this document will be addressed in future revisions of the PIC16F1934/1936/1937 and PIC16LF1934/1936/1937 silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of Table 2 apply to the current silicon revision (A6).

Data Sheet clarifications and corrections start on page 8, following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB[®] IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate web site (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with MPLAB ICD 2 or PICkitTM 3:

- Using the appropriate interface, connect the device to the MPLAB ICD 2 programmer/ debugger or PICkitTM 3.
- 2. From the main menu in MPLAB IDE, select <u>Configure>Select Device</u>, and then select the target part number in the dialog box.
- 3. Select the MPLAB hardware tool (<u>Debugger>Select Tool</u>).
- Perform a "Connect" operation to the device (<u>Debugger>Connect</u>). Depending on the development tool used, the part number and Device Revision ID value appear in the **Output** window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC16F1934/1936/1937 and PIC16LF1934/1936/1937 silicon revisions are shown in Table 1.

TABLE 1: SILICON DEVREV VALUES

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾					
Part Number	Device ID.	A2	А3	A5	A6		
PIC16F1934	10 0011 010x xxxx	2	3	5	6		
PIC16LF1934	10 0100 010x xxxx	2	3	5	6		
PIC16F1936	10 0011 011x xxxx	2	3	5	6		
PIC16LF1936	10 0100 011x xxxx	2	3	5	6		
PIC16F1937	10 0011 100x xxxx	2	3	5	6		
PIC16LF1937	10 0100 100x xxxx	2	3	5	6		

Note 1: The Device ID is located in the last configuration memory space.

2: Refer to the "PIC16F193X/LF193X and PIC16F194X/LF194X Memory Programming Specification" (DS41397) for detailed information on Device and Revision IDs for your specific device.

TABLE 2: SILICON ISSUE SUMMARY

		Item		Affe	cted F	Revisio	ons ⁽¹⁾
Module	Feature	Number	Issue Summary	A2	А3	A5	A6
EEPROM	Memory Endurance	1.1	Erase/Write Endurance Limited.	Х	Х	Х	
EEPROM	Writes	1.2	Min. VDD for Writes.	Х	Х	Χ	Χ
Prog. Mem.	Endurance	2.1	Erase/Write Endurance Limited.	Х	Χ	Χ	
Prog. Mem.	Writes	2.2	Min. VDD for Writes.	Х	Х	Χ	Χ
CCP	PWM Dead Band Delay	3.1	Unpredictable Waveforms.	Х	Х	Χ	Χ
CCP	ECCP2 Switching	3.2	PWM Outputs.	Х	Х	Χ	Χ
CCP	ECCP2 Changing Direction	3.3	Outputs will Improperly go Active.	Х	Х	Χ	Х
CCP	Capture mode	3.4	Capture will be triggered.	Х	Χ	Χ	Х
CCP	ECCPx Dead Time Delay	3.5	Dead Band Delay.	Х	Х	Χ	Χ
CCP	PWM with Pulse Steering	3.6	PWM Output.	Х	Х	Χ	Χ
CCP	Capture mode	3.7	Capture will be triggered.	Х	Χ	Χ	Х
BOR	Threshold	4.1	Voltage Level.	Х			
ADC	ADC Conversion	5.1	ADC Conversion may not complete.	Х	Χ	Χ	
Oscillator	HS Oscillator	6.1	HS Oscillator min. VDD.	Х	Χ	Χ	Х
Enhanced Capture Compare PWM (ECCP)	Enhanced PWM	7.1	PWM 0% Duty Cycle Direction Change.	Х	Х	Х	Х
Enhanced Capture Compare PWM (ECCP)	Enhanced PWM	7.2	PWM 0% Duty Cycle Port Steering.	Х	Х	X	Х
Timer1	Timer0 Gate Source	8.1	Toggle Mode works Improperly.	Х	Х	Χ	Х
Timer1	Timer1 Gate Toggle mode	8.2	T1 Gate Flip-Flop does not clear.	Х	Х	Х	Х
LDO	Minimum VDD above 85°C	9.1	Minimum operating VDD for the PIC16F193X devices at TA > 85°C.	Х	Х	Х	Х

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

Silicon Errata Issues

Note:

This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (A6).

1. Module: Data EE Memory

1.1 Data EE Memory Endurance

The typical write/erase endurance of the Data EE Memory is limited to 10k cycles.

Work around

Use error correction method that stores data in multiple locations.

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Χ	Χ			

1.2 Data EE Write at Min. VDD

The minimum voltage required for a Data EE write operation is 2.0 volts.

Work around

None.

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Χ	Χ	Χ		

2. Module: Program Flash Memory (PFM)

2.1 Program Flash Memory Endurance

The typical write/erase endurance of the PFM is limited to 1k cycles when VDD is above 3.0 volts. Endurance degrades when VDD is below 3V.

Work around

Use an error correction method that stores data in multiple locations.

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Х	Х			

2.2 Program Flash Memory writes at Min. VDD

The minimum voltage required for a PFM write operation is 2.0V.

Work around

None.

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Х	Χ	Х		

3. Module: Capture Compare PWM (CCP)

3.1 Dead Band Delay

With the ECCP configured for PWM half-bridge mode and a dead-band delay greater than or equal to the PWM duty cycle; unpredictable wave forms will result.

Work around

Make sure the dead-band delay is always less than the PWM duty cycle.

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Χ	Χ	Χ		

3.2 ECCP2 Switching Between Single, Half-Bridge and Full-Bridge PWM modes

Switching PWM mode during the current PWM cycle by modifying the P2M[1:0] bits in the CCP2CON register will cause the PWM outputs to switch immediately and not on the start of the next PWM cycle.

Work around

None.

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Χ	Χ	Χ		

3.3 ECCP2 Changing Direction in Full-Bridge PWM modes

When changing direction the active and modulated outputs will improperly go active at the same time and the dead time does not occur which can lead to large shoot-through currents.

Work around

None.

A2	А3	A5	A6		
Χ	Х	Х	Х		

3.4 Capture mode Selected while CCPx Pin is Held High

If the module is configured to capture on the first rising edge and the CCPx pin is high at this time, a capture will be triggered.

Work around

Clear the CCP interrupt flag (CCPxIF = 0) immediately after configuring the module for a capture event.

Affected Silicon Revisions

A2	А3	A5	A6		
Х	Х	Х	Х		

3.5 ECCPx Dead Time Delay in Half-Bridge mode

In Half-Bridge mode the dead band delay is 1 Tosc longer than calculated for the first PWM cycle and 1.5 Tosc for following cycles.

Work around

None.

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Χ	Χ	Χ		

3.6 PWM with Pulse Steering

Disabling a PWM output during a PWM cycle will cause the output to end one Tosc time earlier than expected.

Work around

None.

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Χ	Χ	Χ		

3.7 Capture mode Selected while CCPx Pin is Held Low

If the module is configured to capture on the first falling edge and the CCPx pin is low at this time, a capture will be triggered.

Work around

Clear the CCP interrupt flag (CCPxIF = 0) immediately after configuring the module for a capture event.

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Χ	Χ	Χ		

4. Module: Brown-Out Reset (BOR)

4.1 Brown-Out Threshold

Configuring the BOR for 2.5V operation, the reset will typically occur at 2.7V.

Work around

None.

A2	А3	A5	A6		
Х					

5. Module: ADC

5.1 Analog-to-Digital Conversion

An ADC conversion may not complete under these conditions:

- When Fosc is greater than 8 MHz and it is the clock source used for the ADC converter.
- The ADC is operating from its dedicated internal FRC oscillator and the device is not in Sleep mode (any Fosc frequency).

When this occurs, the ADC Interrupt Flag (ADIF) does not get set, the GO/DONE bit does not get cleared, and the conversion result does not get loaded into the ADRESH and ADRESL result registers.


Work around

Method 1: Select the system clock, Fosc, as the ADC clock source and reduce the Fosc frequency to 8 MHz or less when performing ADC conversions.

Method 2: Select the dedicated FRC oscillator as the ADC conversion clock source and perform all conversions with the device in Sleep.

Method 3: This method is provided if the application cannot use Sleep mode and requires continuous operation at frequencies above 8 MHz. This method requires early termination of an ADC conversion. Provide a fixed time delay in software to stop the A-to-D conversion manually, after all 10 bits are converted, but before the would conversion complete automatically. The conversion is stopped by clearing the GO/ DONE bit in software. The GO/ DONE bit must be cleared during the last ½ TAD cycle, before the would conversion have completed automatically. Refer to Figure 1 for details.

FIGURE 1: INSTRUCTION CYCLE DELAY CALCULATION EXAMPLE



In Figure 1, 88 instruction cycles (TcY) will be required to complete the full conversion. Each TAD cycle consists of 8 TcY periods. A fixed delay is provided to stop the A/D conversion after 86 instruction cycles and terminate the conversion at the correct time as shown in the figure above.

Note:

The exact delay time will depend on the TAD divisor (ADCS) selection. The TCY counts shown in the timing diagram above apply to this example only. Refer to Table 3 for the required delay counts for other configurations.

EXAMPLE 1: CODE EXAMPLE OF INSTRUCTION CYCLE DELAY

ADCON0,	ADGO	;	Start ADC conversion
		;	Provide 86
			instruction cycle
			delay here
ADCON0,	ADGO	;	Terminate the
			conversion manually
ADRESH,	W	;	Read conversion
			result
	ADCON0,	ADCONO, ADGO ADCONO, ADGO ADRESH, W	; ADCONO, ADGO ;

For other combinations of FOSC, TAD values and Instruction cycle delay counts, refer to Table 3.

TABLE 3: INSTRUCTION CYCLE DELAY COUNTS BY TAD SELECTION

TAD	Instruction Cycle Delay Counts				
Fosc/64	172				
Fosc/32	86				
Fosc/16	43				

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Х	Х			

6. Module: Oscillator

6.1 HS Oscillator

The HS oscillator requires a minimum voltage of 3.0 volts (at 65°C or less) to operate at 20 MHz.

Work around

None.

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Χ	Χ	Χ		

7. Module: Enhanced Capture Compare PWM (ECCP)

7.1 Enhanced PWM

When the PWM is configured for Full-Bridge mode and the duty cycle is set to 0%, writing the PxM<1:0> bits to change the direction has no effect on PxA and PxC outputs.

Work around

Increase the duty cycle to a value greater than 0% before changing directions.

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Χ	Χ	Χ		

7.2 Enhanced PWM

In PWM mode, when the duty cycle is set to 0% and the STRxSYNC bit is set, writing the STRxA, STRxB, STRxC and the STRxD bits to enable/ disable steering to port pins has no effect on the outputs.

Work around

Increase the duty cycle to a value greater than 0% before enabling/disabling steering to port pins.

A2	А3	A5	A6		
Χ	Χ	Χ	Χ		

8. Module: Timer1

8.1 Timer1 Gate Toggle mode with Timer0 as Gate Source

Timer1 Gate Toggle mode provides unexpected results when Timer0 overflow is selected as the Timer1 gate source. We do not recommend using Timer0 overflow as the Timer1 gate source while in Timer1 Gate Toggle mode or when Toggle mode is used in conjunction with Timer1 Gate Single-Pulse mode.

Work around

None.

Affected Silicon Revisions

A2	А3	A5	A6		
Χ	Х	Х	Х		

8.2 Timer1 Gate Toggle mode

When Timer1 Gate Toggle mode is enabled, it is possible to measure the full-cycle length of a Timer1 gate signal. To perform this function, the Timer1 gate source is routed through a flip-flop that changes state on every incrementing edge of the gate signal. Timer1 Gate Toggle mode is enabled by setting the T1GTM bit of the T1GCON register. When working properly, clearing either the T1GTM bit or the TMR1ON bit would also clear the output value of this flip-flop, and hold it clear. This is done in order to control which edge is being measured. The issue that exists is that clearing the TMR1ON bit does not clear the output value of the flip-flop and hold it clear.

Work around

Clear the T1GTM bit in the T1GCON register to clear and hold clear the output value of the flip-flop.

Affected Silicon Revisions

A2	А3	A5	A6		
Х	Χ	Χ	Χ		

9. Module: LDO

9.1 Minimum VDD above 85°C

The minimum voltage required for the PIC16F193X devices is 3.5 volts for temperatures above 85°C.

Note:	This	issue	only	applies	to	the
	PIC16	F193X	devices	operatin	ig in	the
	Exten	ded to	emperatu	ge.	The	
	PIC16	LF193	devices	are not a	ffecte	d.

Work around

None.

A2	А3	A5	A6		
Χ	Х	Х	Х		

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS41364**D**):

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

1. Module: Electrical Specifications

In Table 29-2, Oscillator Parameters, the HFINTOSC and MFINTOSC internal calibrated oscillator frequency tolerances should be +/- 3.0%, when VDD is equal to, and above 2.5V and when temperatures are equal to, and above 60°C, yet still equal to, or below 85°C, as shown below.

TABLE 29-2: OSCILLATOR PARAMETERS


Standard Operating Conditions (unless otherwise stated) Operating Temperature $-40^{\circ}\text{C} \le \text{TA} \le +125^{\circ}\text{C}$								
Param No.	Sym.	Characteristic	Freq. Tolerance	Min.	Тур†	Max.	Units	Conditions
OS08	HFosc	Internal Calibrated HFINTOSC Frequency ⁽²⁾	±2% ±3.0%		16.0 16.0		MHz MHz	$ 0^{\circ}C \leq TA \leq \textbf{+60°C}, \ VDD \geq 2.5V \\ \textbf{60°C} \leq \textbf{TA} \leq \textbf{85°C}, \ \textbf{VDD} \geq \textbf{2.5V} $
			±5%	_	16.0	_	MHz	-40°C ≤ TA ≤ +125°C
OS08A	MFosc	Internal Calibrated MFINTOSC Frequency ⁽²⁾	±2% ±3.0%	_	500 500	_	kHz kHz	$0^{\circ}C \le TA \le +60^{\circ}C$, VDD $\ge 2.5V$ $60^{\circ}C \le TA \le 85^{\circ}C$, VDD $\ge 2.5V$
			±5%	_	500	_	kHz	-40°C ≤ TA ≤ +125°C
OS10*	Tiosc st	HFINTOSC Wake-up from Sleep Start-up Time	_	_	5	8	μS	
		MFINTOSC Wake-up from Sleep Start-up Time	_	_	20	30	μS	

- * These parameters are characterized but not tested.
- † Data in "Typ" column is at 3.0V, 25°C unless otherwise stated. These parameters are for design guidance only and are not tested.
- Note 1: Instruction cycle period (TcY) equals four times the input oscillator time base period. All specified values are based on characterization data for that particular oscillator type under standard operating conditions with the device executing code. Exceeding these specified limits may result in an unstable oscillator operation and/or higher than expected current consumption. All devices are tested to operate at "min" values with an external clock applied to the OSC1 pin. When an external clock input is used, the "max" cycle time limit is "DC" (no clock) for all devices.
 - 2: To ensure these oscillator frequency tolerances, VDD and VSS must be capacitively decoupled as close to the device as possible. $0.1~\mu F$ and $0.01~\mu F$ values in parallel are recommended.
 - 3: By design.

2. Module: Electrical Specifications

In Figure 29-3, HFINTOSC Frequency Accuracy Over Device VDD and Temperature, the oscillator accuracy should be +/- 3.0% when VDD is equal to, and above 2.5V and when temperatures are equal to, and above 60°C, yet still equal to, or below 85°C, as shown below.

FIGURE 29-3: HFINTOSC FREQUENCY ACCURACY OVER DEVICE VDD AND TEMPERATURE



APPENDIX A: DOCUMENT

REVISION HISTORY

Rev A Document (9/2009)

Initial release of this document.

Rev B Document (1/2010)

Added silicon revision A5.

Rev C Document (5/2010)

Added Modules 5, 6, 7 and 8.

Data Sheet Clarifications: Added Modules 1 and 2.

Rev D Document (6/2010)

Added Silicon Revision A6.

Rev E Document (7/2010)

Revised Module 5.1; Added Module 8.2; Other minor corrections.

Rev F Document (9/2010)

Added Module 9, LDO.

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the
 intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our
 knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data
 Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC³² logo, rfPIC and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniscient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICtail, REAL ICE, rfLAB, Select Mode, Total Endurance, TSHARC, UniWinDriver, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2010, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

Printed on recycled paper.

ISBN: 978-1-60932-559-6

QUALITY MANAGEMENT SYSTEM

CERTIFIED BY DNV

ISO/TS 16949:2002

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



Worldwide Sales and Service

AMERICAS

Corporate Office

2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support:

http://support.microchip.com

Web Address: www.microchip.com

Atlanta

Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455

Boston

Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088

Chicago Itasca. IL

Tel: 630-285-0071 Fax: 630-285-0075

Cleveland

Independence, OH Tel: 216-447-0464 Fax: 216-447-0643

Dallas

Addison, TX Tel: 972-818-7423 Fax: 972-818-2924

Detroit

Farmington Hills, MI Tel: 248-538-2250 Fax: 248-538-2260

Kokomo

Kokomo, IN Tel: 765-864-8360 Fax: 765-864-8387

Los Angeles

Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608

Santa Clara

Santa Clara, CA Tel: 408-961-6444 Fax: 408-961-6445

Toronto

Mississauga, Ontario,

Canada

Tel: 905-673-0699 Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office

Suites 3707-14, 37th Floor Tower 6, The Gateway Harbour City, Kowloon

Hong Kong Tel: 852-2401-1200

Fax: 852-2401-3431

Australia - Sydney

Tel: 61-2-9868-6733 Fax: 61-2-9868-6755

China - Beijing

Tel: 86-10-8528-2100 Fax: 86-10-8528-2104

China - Chengdu

Tel: 86-28-8665-5511 Fax: 86-28-8665-7889

China - Chongqing

Tel: 86-23-8980-9588 Fax: 86-23-8980-9500

China - Hong Kong SAR

Tel: 852-2401-1200 Fax: 852-2401-3431

China - Nanjing

Tel: 86-25-8473-2460 Fax: 86-25-8473-2470

China - Qingdao

Tel: 86-532-8502-7355 Fax: 86-532-8502-7205

China - Shanghai

Tel: 86-21-5407-5533 Fax: 86-21-5407-5066

China - Shenyang

Tel: 86-24-2334-2829 Fax: 86-24-2334-2393

China - Shenzhen

Tel: 86-755-8203-2660 Fax: 86-755-8203-1760

China - Wuhan

Tel: 86-27-5980-5300 Fax: 86-27-5980-5118

China - Xian

Tel: 86-29-8833-7252 Fax: 86-29-8833-7256

China - Xiamen

Tel: 86-592-2388138 Fax: 86-592-2388130

China - Zhuhai Tel: 86-756-3210040

Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore

Tel: 91-80-3090-4444 Fax: 91-80-3090-4123

India - New Delhi

Tel: 91-11-4160-8631 Fax: 91-11-4160-8632

India - Pune

Tel: 91-20-2566-1512 Fax: 91-20-2566-1513

Japan - Yokohama

Tel: 81-45-471- 6166 Fax: 81-45-471-6122

Korea - Daegu

Tel: 82-53-744-4301 Fax: 82-53-744-4302

Korea - Seoul

Tel: 82-2-554-7200 Fax: 82-2-558-5932 or 82-2-558-5934

Malaysia - Kuala Lumpur

Tel: 60-3-6201-9857 Fax: 60-3-6201-9859

Malaysia - Penang

Tel: 60-4-227-8870 Fax: 60-4-227-4068

Philippines - Manila

Tel: 63-2-634-9065 Fax: 63-2-634-9069

Singapore

Tel: 65-6334-8870 Fax: 65-6334-8850

Taiwan - Hsin Chu

Tel: 886-3-6578-300 Fax: 886-3-6578-370

Taiwan - Kaohsiung Tel: 886-7-213-7830

Fax: 886-7-330-9305

Taiwan - Taipei

Tel: 886-2-2500-6610 Fax: 886-2-2508-0102

Thailand - Bangkok

Tel: 66-2-694-1351 Fax: 66-2-694-1350

EUROPE

Austria - Wels

Tel: 43-7242-2244-39 Fax: 43-7242-2244-393 Denmark - Copenhagen

Tel: 45-4450-2828 Fax: 45-4485-2829

France - Paris

Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79

Germany - Munich

Tel: 49-89-627-144-0 Fax: 49-89-627-144-44

Italy - Milan

Tel: 39-0331-742611 Fax: 39-0331-466781

Netherlands - Drunen

Tel: 31-416-690399 Fax: 31-416-690340

Spain - Madrid

Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 **UK - Wokingham**

Tel: 44-118-921-5869 Fax: 44-118-921-5820

08/04/10