

PIC16F62X Rev. A Silicon/Data Sheet Errata


The PIC16F62X (Rev. A) parts you have received conform functionally to the Device Data Sheet (DS40300C), except for the anomalies described below.

Microchip intends to address all issues listed here in future revisions of the PIC16F62X silicon.

1. Module: I/O Ports


A read of the PORTB Data Direction Register (TRISB) returns the Data Direction state on the port pins themselves and not the contents of the TRISB register latch.

FIGURE 5-8: BLOCK DIAGRAM OF RB0/INT PIN




PIC16F62X

FIGURE 5-9: BLOCK DIAGRAM OF RB1/RX/DT PIN



- Note 1:** Port/Peripheral select signal selects between port data and peripheral output.
- Note 2:** Peripheral OE (output enable) is only active if peripheral select is active.

FIGURE 5-10: BLOCK DIAGRAM OF RB2/TX/CK PIN



PIC16F62X

FIGURE 5-11: BLOCK DIAGRAM OF THE RB3/CCP1 PIN





FIGURE 5-12: BLOCK DIAGRAM OF RB4/PGM PIN



PIC16F62X

FIGURE 5-13: BLOCK DIAGRAM OF RB5 PIN






FIGURE 5-14: BLOCK DIAGRAM OF RB6/T1OSO/T1CKI PIN



PIC16F62X

FIGURE 5-15: BLOCK DIAGRAM OF THE RB7/T10SI PIN



2. Module: Comparator Mode 1

Mode 1 allows AN2 to drive the (+) inputs of both comparators. AN1 continues to drive the (-) input of Comparator 2, but AN0 and AN3 can be switched into the (-) input of Comparator 1. The state of the CIS bit chooses which input is to be connected to the comparator. When CIS = 0, AN0 is attached and the comparator functions correctly. When CIS = 1, AN3 is not completely connected to the comparator, resulting in incorrect behavior.

Mode 2 is also a Multiplex mode using the CIS bit. This mode functions correctly.

All other modes are unaffected by this Errata.

3. Module: Low Voltage Programming Mode

The high voltage override for low voltage programming does not operate as specified in the programming specification. In the Low Voltage Programming (LVP) mode, the device can be programmed without using 12V on VPP (pin 4). However, when high voltage programming is used while the part has low voltage programming enabled, the Low Voltage mode is not overridden. If RB4 goes high for any reason during high voltage programming with LVP enabled, the programming will be interrupted.

Work around

Pull RB4 (pin 10) to ground during the initial programming to prevent programming interruptions. Once LVP has been disabled, it remedies this issue with RB4.

4. Module: CCP (Compare Mode)

The CCP1 output latch, observed on RB3/CCP1/P1A, can change unexpectedly when the CCP module is changed from a set output on match (CCP1CON<3:0> = "1000") to clear output on match (CCP1CON<3:0> = "1001") or vice versa. This condition will occur following a CCP Reset at the beginning of the third iteration of the following sequence.

- CCPR1<3:0> is changed from "1001" to "1000" or vice versa.
- The TMR1H:TMR1L register pair matches the CCP1R1H:CCPR1L register pair.

Step 1 of the third iteration will cause the CCP1 output latch to immediately and erroneously change to the inverse of the CCPR1<0> bit. This gives the appearance of an inverted CCP response to the third and subsequent compare match events.

The apparent inverted response will persist until the CCP1CON<3> bit is cleared (exiting Compare mode). Interrupts always occur correctly on the match condition. The error is only in the state of the CCP1 output latch.

Work around

Option 1

Use the CCP toggle output on Compare Match mode (CCP1CON<3.0> = "0010").

Option 2

Since the problem occurs after two changes to the Compare and Match mode, it is only necessary to reset the CCP1CON register before the third change is made. To remain backwards compatible with earlier versions of the CCP module, always reset the CCP1CON register when changing from the clear output on Match mode to the set output on Match mode, as described in the following steps.

1. Ensure the RB3 data latch is set to '0'.
2. Clear the CCP1CON register (`clrf CCP1CON`).
3. Set the CCP1CON<3:0> bits to "1000" for set output on match.

5. Module: MCLR/RA5 in LVP Mode

When the PIC16F62X device has LVP enabled, MCLR is always enabled, regardless of the CONFIG register settings.

PIC16F62X

Clarifications/Corrections to the Data Sheet:

In the Device Data Sheet (DS40300C), the following clarifications and corrections should be noted.

1. Module: Special Function Registers (T1SYNC, Register T1CON)

In Table 3-1, "Special Function Registers Summary Bank 0", bit T1SYNC, in Register T1CON (address 10h), should be asserted logic low (i.e., **T1SYNC**) as shown in bold below.

2. Module: Special Function Registers (ADEN, Register RCSTA)

In Table 3-1, "Special Function Registers Summary Bank 0", bit ADEN, in Register RCSTA (address 18h), is misspelled. The correct spelling should be **ADDEN**, as shown in bold below.

This misspelling also appears in Register 12-2. Tables 12-2, 12-6, 12-7, 12-8, 12-9, 12-10, 12-11 and 12-12. Figures 12-8, 12-9, 12-10 and 12-11. Sections 12.2.2, 12.3.1 and 12.3.1.1.

TABLE 3-1: SPECIAL REGISTERS SUMMARY BANK 0

Address	Name	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0	Value on POR Reset	Value on all other Resets ⁽¹⁾
Bank 0											
10h	T1CON	—	—	T1CKPS1	T1CKPS0	T1OSCEN	T1SYNC	TMR1CS	TMR1ON	--00 0000	--uu uuuu
18h	RCSTA	SPEN	RX9	SREN	CREN	ADDEN	FERR	OERR	RX9D	0000 -00x	0000 -00x


Legend: x = unknown, u = unchanged, - = unimplemented locations, read as '0', α = value depends on condition, shaded = unimplemented

Note 1: Other (non power-up) Resets include $\overline{\text{MCLR}}$ Reset, Brown-out Reset and Watchdog Timer Reset during normal operation.

3. Module: I/O Ports (RA5/ $\overline{\text{MCLR}}$ /VPP)

Figure 5-5, "Block Diagram of the RA5/ $\overline{\text{MCLR}}$ /VPP Pin", is incorrect. The following diagram should be used instead.

FIGURE 5-5: BLOCK DIAGRAM OF THE RA5/ $\overline{\text{MCLR}}$ /VPP PIN



PIC16F62X

4. Module: Comparator

Example 9-1, "Initializing Comparator Module", is incorrect. The following code example should be used instead.

EXAMPLE 9-1: INITIALIZING COMPARATOR MODULE

```
BCF          INTCON,GIE      ; Turn OFF Global Interrupts
BCF          INTCON,PEIE     ; Turn OFF Peripheral Interrupts
CLRF        PORTA           ; Init Port A
MOVLW       0X03             ; Init comparator mode
MOVWF       CMCON            ; CM<2:0> = 011
BSF         STATUS,RP0       ; Select BANK 1
MOVLW       0x07             ; Initialize Port A Direction
MOVWF       TRISA            ; Set RA<2:0> as Inputs
                                ; RA<4:3> as outputs
                                ; TRIS<5> always reads '0'

BCF         STATUS,RP0       ; Select BANK 0
CALL        DELAY10          ; Wait 10us for comparator output to become valid
                                ; See Table 17-1 Parameter 301

MOVF        CMCON,F          ; Read CMCON to end change condition
BCF         PIR1,CMIF        ; Clear pending interrupts
BSF         STATUS,RP0       ; Select BANK 1
BSF         PIE1,CMIE        ; Enable Comparator Interrupts
BCF         STATUS,RP0       ; Select BANK 0
BSF         INTCON,PEIE      ; Enable Peripheral Interrupts
BSF         INTCON,GIE       ; Global Interrupt Enable

; Insert Your code...

; Helper function is the Delay for 10us routine show below.

DELAY10          ; burns 8 cycles + the call for 10 cycles or 10us at 4Mhz
    goto $+1      ; goto the next instruction and burn 2 cycles
    call retlbl   ; goto the next instruction and burn 2 more cycles
retlblreturn; go back and burn 2 cycles (actually done 2x for 4 cycles consumed)
```

5. Module: Data EEPROM Memory

Examples 13-1, “Data EEPROM Read”, 13-2, “Data EEPROM Write”, and 13-3, “Write Verify”, are incorrect. The EEPROM registers are all located in Bank 1. The examples show the registers in Bank 0 and Bank 1. The following code examples should be used instead.

EXAMPLE 13-1: DATA EEPROM READ

```
BSF    STATUS, RP0    ; Bank 1
MOVLW  CONFIG_ADDR   ;
MOVWF  EEADR          ; Address to write
BSF    EECON1, RD     ; EE Read
MOVF   EEDATA, W      ; W = EEDATA
BCF    STATUS, RP0    ; Bank 0
```

EXAMPLE 13-2: DATA EEPROM WRITE

```
    ; set up the data and the address
BSF    STATUS, RP0    ; Bank 1
MOVLW  CONFIG_ADDR   ;
MOVWF  EEADR          ; Address to write
MOVLW  CONFIG_DATA   ;
MOVWF  EEDATA         ; Data to write

    ; perform the write
    ; operation
BSF    EECON1, WREN   ; Enable Write
BCF    INTCON, GIE    ; Disable INTs
MOVLW  055h           ;
MOVWF  EECON2         ; Write 55
MOVLW  0AAh           ;
MOVWF  EECON2         ; Write AA
BSF    EECON1, WR     ; Set WR bit
BCF    STATUS, RP0    ; Bank 0
```

EXAMPLE 13-3: WRITE VERIFY

```
    ; after the write is complete (i.e. in the
    ; write interrupt)
BSF    STATUS, RP0    ; Bank 1
MOVF   EEDATA, W      ; load the last
    ; written value into W
BSF    EECON1, RD     ; start a read
;
; Is the value written (in W Reg) and
; read (in EEDATA) the same?
;
SUBWF  EEDATA, W      ; the EEDATA has fresh
    ; data
BTFS   STATUS, Z      ; Is the Zero flag set?
GOTO   WRITE_ERR     ; NO, Write Error
    ; YES, Good Write
    ; continue program
```

PIC16F62X

6. Module: Timer1 Module

In Section 7.0, “Timer1 Module”, in Register 7-1, bit TMR1ON, “Timer1 On” should read as shown in bold below:

REGISTER 7-1: T1CON: TIMER1 CONTROL REGISTER (ADDRESS: 10h)

U-0	U-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	
—	—	T1CKPS1	T1CKPS0	T1OSCEN	$\overline{T1SYNC}$	TMR1CS	TMR1ON	
bit 7								bit 0

bit 7-6 **Unimplemented:** Read as ‘0’

bit 5-4 **T1CKPS1/T1CKPS0:** Timer1 Input Clock Prescale Select bits

11 = 1:8 prescale value
 10 = 1:4 prescale value
 01 = 1:2 prescale value
 11 = 1:1 prescale value

bit 3 **T1OSCEN:** Timer1 Oscillator Enable Control bit

1 = Oscillator is enabled
 0 = Oscillator is shut off⁽¹⁾

bit 2 **T1SYNC:** Timer1 External Clock Input Synchronization Control bit

TMR1CS = 1

1 = Do not synchronize external clock input
 0 = Synchronize external clock input

TMR1CS = 0

This bit is ignored. Timer1 uses the internal clock when TRM1CS = 0.

bit 1 **TMR1CS:** Timer1 Clock Source Select bit

1 = External clock from pin RB6/T1OSO/T1CKI (on the rising edge)
 0 = Internal clock (Fosc/4)

bit 0 **TMR1ON:** Timer1 On bit

1 = Enables Timer1
 0 = Disables Timer1

Note 1: The oscillator inverter and feedback resistor are turned off to eliminate power drain.

Legend:

R = Readable bit	W = Writable bit	U = Unimplemented bit, read as ‘0’
-n = Value at POR	‘1’ = Bit is set	‘0’ = Bit is cleared x = Bit is unknown

REVISION HISTORY

Rev A Document (6/00)

Original errata document.

Rev B Document (11/00)

Issue 3 (CCP Compare Mode), Table 1 and 2 were added (page 2).

Under the Clarifications/Corrections Section, Item 1, Table 15-12 was updated with additional information (page 3).

Rev C Document (6/01)

Issues 2 and 3 were added.

Under Clarifications/Corrections, Items 2 and 3 were changed and Item numbers were renumbered accordingly.

Rev D Document (9/01)

Item 3 was rewritten (page 9).

Under the Clarifications/Corrections to the Data Sheet Section, the following items were changed:

Item 2, Tables 17.1 and 17.2, were updated with minor changes.

Item 6 was added.

Rev E Document (2/02)

Under Clarifications/Corrections to the Data Sheet, added Module 3: I/O Ports (RA5/MCLR/VPP).

Rev G Document (05/19/05)

Under Clarifications/Corrections to the Data Sheet, Added Module 6: Timer1 Module.

PIC16F62X

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip's products as critical components in life support systems is not authorized except with express written approval by Microchip. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELoQ, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, PowerSmart, rPIC, and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


AmpLab, FilterLab, Migratable Memory, MXDEV, MXLAB, PICMASTER, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, dsPICDEM, dsPICDEM.net, dsPICworks, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Linear Active Thermistor, MPASM, MPLIB, MPLINK, MPSIM, PCKIT, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, rLAB, rPICDEM, Select Mode, Smart Serial, SmartTel, Total Endurance and WiperLock are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2005, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==

Microchip received ISO/TS-16949:2002 quality system certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona and Mountain View, California in October 2003. The Company's quality system processes and procedures are for its PICmicro® 8-bit MCUs, KEELoQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta
Alpharetta, GA
Tel: 770-640-0034
Fax: 770-640-0307

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo
Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

San Jose
Mountain View, CA
Tel: 650-215-1444
Fax: 650-961-0286

Toronto
Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8676-6200
Fax: 86-28-8676-6599

China - Fuzhou
Tel: 86-591-8750-3506
Fax: 86-591-8750-3521

China - Hong Kong SAR
Tel: 852-2401-1200
Fax: 852-2401-3431

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Shunde
Tel: 86-757-2839-5507
Fax: 86-757-2839-5571

China - Qingdao
Tel: 86-532-502-7355
Fax: 86-532-502-7205

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-2229-0061
Fax: 91-80-2229-0062

India - New Delhi
Tel: 91-11-5160-8631
Fax: 91-11-5160-8632

Japan - Kanagawa
Tel: 81-45-471- 6166
Fax: 81-45-471-6122

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Penang
Tel: 011-604-646-8870
Fax: 011-604-646-5086

Philippines - Manila
Tel: 011-632-634-9065
Fax: 011-632-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Kaohsiung
Tel: 886-7-536-4818
Fax: 886-7-536-4803

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Taiwan - Hsinchu
Tel: 886-3-572-9526
Fax: 886-3-572-6459

EUROPE

Austria - Weis
Tel: 43-7242-2244-399
Fax: 43-7242-2244-393

Denmark - Ballerup
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Massy
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Ismaning
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

England - Berkshire
Tel: 44-118-921-5869
Fax: 44-118-921-5820