

PIC18F47J13 Family Silicon Errata and Data Sheet Clarification

The PIC18F47J13 Family devices that you have received conform functionally to the current Device Data Sheet (DS39974A), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).

The errata described in this document will be addressed in future revisions of the PIC18F47J13 Family silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (A1).

Data Sheet clarifications and corrections start on page 5, following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip’s programmers, debuggers, and emulation tools, which are available at the Microchip corporate web site (www.microchip.com).

TABLE 1: SILICON DEVREV VALUES

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾		
		A1		
PIC18F47J13	2CFh	01h		
PIC18F46J13	2CDh			
PIC18F27J13	2CBh			
PIC18F26J13	2C9h			
PIC18LF47J13	2DFh			
PIC18LF46J13	2DDh			
PIC18LF27J13	2DBh			
PIC18LF26J13	2D9h			

Note 1: The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format “DEVID DEVREV”.

2: Refer to the “*PIC18F2XJXX/4XJXX Family Flash Microcontroller Programming Specification*” (DS39687) for detailed information on Device and Revision IDs for your specific device.

For example, to identify the silicon revision level using MPLAB IDE in conjunction with MPLAB ICD 2 or PICKIT™ 3:

1. Using the appropriate interface, connect the device to the MPLAB ICD 2 programmer/debugger or PICKIT 3.
2. From the main menu in MPLAB IDE, select Configure>Select Device, and then select the target part number in the dialog box.
3. Select the MPLAB hardware tool (Debugger>Select Tool).
4. Perform a “Connect” operation to the device (Debugger>Connect). Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC18F47J13 Family silicon revisions are shown in [Table 1](#).

PIC18F47J13 FAMILY

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾		
				A1		
CTMU	Constant Current Source	1.	Band gap must be manually enabled before using the CTMU.	X		
Oscillator Configurations	PLL	2.	PLL can not be enabled unless the 8 or 4 MHz INTOSC option is set.	X		
ADC	A/D	3.	ANx pin may output a pull-up pulse during acquisition.	X		
MSSP	I ² C™ Mode	4.	If a Stop condition occurs in the middle of an address or data reception, there will be issues with the SCL clock stream and RCEN bit.	X		
MSSP	I ² C Slave Reception	5.	In I ² C slave reception, the module may have problems receiving correct data.	X		
EUSART	Enable/Disable	6.	If interrupts are enabled, disabling and re-enabling the module requires a 2 Tcy delay.	X		

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

Silicon Errata Issues

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (A1).

1. Module: Charge Time Measurement Unit (CTMU)

When using the CTMU, the constant current source may not output if the internal band gap reference is not enabled.

Work around

Before using the CTMU, the internal band gap reference module should be manually enabled by setting the VBGEN bit to '1' (ANCON1<7> = 1).

Affected Silicon Revisions

A1							
X							

2. Module: Phase Locked Loop (PLL)

When OSCCON<6:4> are configured to settings other than a 4 MHz or 8 MHz INTOSC postscaler, the PLEN bit (OSCTUNE<6>) is forced to '0', even if firmware tries to set the PLEN bit. This may prevent firmware from enabling the PLL.

Work around

Before attempting to set the PLEN bit, configure OSCCON<6:4> to 0b110 or 0b111 to select the 4 MHz or 8 MHz INTOSC postscaler.

Affected Silicon Revisions

A1							
X							

3. Module: Analog-to-Digital Converter (ADC)

At the beginning of sample acquisition, one or more small pull-up pulses (approximately 25 ns long) may output to the currently selected ANx analog channel. These pulses can lead to a positive offset error when the analog signal voltage is near Vss and the external analog signal driver is unable to dissipate the added pull-up voltage before the A/D conversion occurs.

Work around

Do one or more of the following:

- Use the "0 TAD" A/D acquisition time setting to start the next sample acquisition period immediately following an A/D conversion completion.
This allows the external analog signal driver more time to dissipate the pull-up pulses that occur when the sample acquisition is started.
- Use a longer A/D acquisition time setting to provide time for the external analog signal driver to dissipate the pull-up pulse voltage.
- Use low-impedance, active analog signal drivers to reduce the time needed to dissipate the pull-up pulse voltage.
- Experiment with external filter capacitor values to avoid allowing the pull-up voltage offset to affect the final voltage that gets converted.

Small filter capacitor values (or none at all) will allow time for the external analog signal driver to dissipate the pull-up voltage quickly. Alternately, large filter capacitor values will prevent the short pull-up pulses from increasing the final voltage, enough to cause A/D conversion error.

Affected Silicon Revisions

A1							
X							

PIC18F47J13 FAMILY

4. Module: Master Synchronous Serial Port (MSSP)

In Master I²C Receive mode, if a Stop condition occurs in the middle of an address or data reception, the SCL clock stream will continue endlessly and the RCEN bit of the SSPxCON2 register will remain set improperly. When a Start condition occurs after the improper Stop condition, nine additional clocks will be generated followed by the RCEN bit going low.

Work around

Use low-impedance pull-ups on the SDA line to reduce the possibility of noise glitches that may trigger an improper Stop event. Use a time-out event timer to detect the unexpected Stop condition, and subsequently, the stuck RCEN bit. Clear the stuck RCEN bit by clearing the SSPEN bit of SSPxCON1.

Affected Silicon Revisions

A1							
X							

5. Module: Master Synchronous Serial Port

When configured for I²C™ slave reception, the MSSP module may not receive the correct data, in extremely rare cases. This occurs only if the Serial Receive/Transmit Buffer register (SSPxBUF) is not read after the SSP1IF interrupt (PIR1<3>) has occurred, but before the first rising clock edge of the next byte being received.

Work around

The issue can be resolved in either of these ways:

- Prior to the I²C slave reception, enable the clock stretching feature. This is done by setting the SEN bit (SSPxCON2<0>).
- Each time the SSPxIF is set, read the SSPxBUF before the first rising clock edge of the next byte being received.

Affected Silicon Revisions

A1							
X							

6. Module: Enhanced Universal Synchronous Asynchronous Receiver Transmitter (EUSART)

In rare situations, when interrupts are enabled, unexpected results may occur if:

- The EUSART is disabled (SPEN bit (RCSTAx<7>) = 0)
- The EUSART is re-enabled (RCSTAx<7> = 1)
- A two-cycle instruction is executed immediately after setting SPEN, CREN or TXEN = 1

Work around

Add a 2 T_{cy} delay after any instruction that re-enables the EUSART module (sets SPEN, CREN or TXEN = 1).

See [Example 1](#).

Affected Silicon Revisions

A1							
X							

EXAMPLE 1: RE-ENABLING A EUSART MODULE

```

;Initial conditions: SPEN = 0 (module disabled)
;To re-enable the module:
;Re-Initialize TXSTAx, BAUDCONx, SPBRGx, SPBRGHx registers (if needed)
;Re-Initialize RCSTAx register (if needed), but do not set SPEN = 1 yet

;Now enable the module, but add a 2-Tcy delay before executing any two-cycle
;instructions
bsf    RCSTA1, SPEN           ;or RCSTA2 if EUSART2
nop                    ;1 Tcy delay
nop                    ;1 Tcy delay (two total)
    
```

PIC18F47J13 FAMILY

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS39974A):

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

1. Module: Guidelines for Getting Started with PIC18FJ Microcontrollers

Section “2.4 Voltage Regulator Pins (VCAP/VDDCORE)” has been replaced with a new and more detailed section. The entire text follows:

2.4 Voltage Regulator Pins (VCAP/VDDCORE)

On “F” devices, a low-ESR ($< 5\Omega$) capacitor is required on the VCAP/VDDCORE pin to stabilize the voltage regulator output voltage. The VCAP/VDDCORE pin must not be connected to VDD and must use a capacitor of 10 μF connected to ground. The type can be ceramic or tantalum. Suitable examples of capacitors are shown in [Table 2-1](#). Capacitors with equivalent specifications can be used.

Designers may use [Figure 2-3](#) to evaluate ESR equivalence of candidate devices.

It is recommended that the trace length not exceed 0.25 inch (6 mm). Refer to [Section 30.0 “Electrical Characteristics”](#) for additional information.

On “LF” devices, the VCAP/VDDCORE pin must be tied to a voltage supply at the VDDCORE level. Refer to [Section 30.0 “Electrical Characteristics”](#) for information on VDD and VDDCORE.

Note that the “LF” versions of these devices are provided with the voltage regulator permanently disabled; they must always be provided with a supply voltage on the VDDCORE pin.

FIGURE 2-3 FREQUENCY vs. ESR PERFORMANCE FOR SUGGESTED VCAP




TABLE 2-1 SUITABLE CAPACITOR EQUIVALENTS

Make	Part #	Nominal Capacitance	Base Tolerance	Rated Voltage	Temp. Range
TDK	C3216X7R1C106K	10 μF	$\pm 10\%$	16V	-55 to 125°C
TDK	C3216X5R1C106K	10 μF	$\pm 10\%$	16V	-55 to 85°C
Panasonic	ECJ-3YX1C106K	10 μF	$\pm 10\%$	16V	-55 to 125°C
Panasonic	ECJ-4YB1C106K	10 μF	$\pm 10\%$	16V	-55 to 85°C
Murata	GRM32DR71C106KA01L	10 μF	$\pm 10\%$	16V	-55 to 125°C
Murata	GRM31CR61C106KC31L	10 μF	$\pm 10\%$	16V	-55 to 85°C

PIC18F47J13 FAMILY

2.4.1 CONSIDERATIONS FOR CERAMIC CAPACITORS

In recent years, large value, low-voltage, surface mount ceramic capacitors have become very cost effective in sizes up to a few tens of microfarad. The low-ESR, small physical size and other properties make ceramic capacitors very attractive in many types of applications.

Ceramic capacitors are suitable for use with the internal voltage regulator of this microcontroller. However, some care is needed in selecting the capacitor to ensure that it maintains sufficient capacitance over the intended operating range of the application.


Typical low-cost, 10 μ F ceramic capacitors are available in X5R, X7R and Y5V dielectric ratings (other types are also available, but are less common). The initial tolerance specifications for these types of capacitors are often specified as $\pm 10\%$ to $\pm 20\%$ (X5R and X7R), or $-20\%/+80\%$ (Y5V). However, the effective capacitance that these capacitors provide in an application circuit will also vary based on additional factors, such as the applied DC bias voltage and the temperature. The total in-circuit tolerance is, therefore, much wider than the initial tolerance specification.

The X5R and X7R capacitors typically exhibit satisfactory temperature stability (ex: $\pm 15\%$ over a wide temperature range, but consult the manufacturer's data sheets for exact specifications). However, Y5V capacitors typically have extreme temperature tolerance specifications of $+22\%/ -82\%$. Due to the extreme temperature tolerance, a 10 μ F nominal rated Y5V type capacitor may not deliver enough total capacitance to meet minimum internal voltage regulator stability and transient response requirements. Therefore, Y5V capacitors are not recommended for use with the internal voltage regulator if the application must operate over a wide temperature range.

In addition to temperature tolerance, the effective capacitance of large value ceramic capacitors can vary substantially, based on the amount of DC voltage applied to the capacitor. This effect can be very significant, but is often overlooked or is not always documented.

A typical DC bias voltage vs. capacitance graph for 16V, 10V and 6.3V rated capacitors is shown in Figure 2-4.

FIGURE 2-4 DC BIAS VOLTAGE vs. CAPACITANCE CHARACTERISTICS



When selecting a ceramic capacitor to be used with the internal voltage regulator, it is suggested to select a high-voltage rating, so that the operating voltage is a small percentage of the maximum rated capacitor voltage. For example, choose a ceramic capacitor rated at 16V for the 2.5V core voltage. Suggested capacitors are shown in Table 2-1.

PIC18F47J13 FAMILY

2. Module: Reset

Register 20-1 and Register 20-5 incorrectly define the SSPxSTAT Reset state as '1111 1111'. The correct Reset state of the SSPxSTAT is '0000 0000'.

3. Module: Electrical Characteristics

Changes, shown in bold, have been made to the D060, D061 and D063 rows in [Section 30.4, DC Characteristics: PIC18F47J13 Family \(Industrial\)](#). The updated table is shown below:

30.4 DC Characteristics: PIC18F47J13 Family (Industrial)

DC Characteristics		Standard Operating Conditions (unless otherwise stated) Operating temperature $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$ for Industrial				
Param No.	Characteristic	Typ	Max	Units	Temp.	Conditions
D060	Input Leakage Current (I _{IL}) ^(1,2)					
	I/O Ports without 5.5V Tolerance	±5	±200	nA	+25°C	V _{SS} ≤ V _{PIN} ≤ V _{DD} Pin at high-impedance
		±15	±500	nA	+85°C	
	I/O Ports with 5.5V Tolerance	±5	±200	nA	+25°C	V _{SS} ≤ V _{PIN} ≤ 5.5 V, Pin at high-impedance
±15		±500	nA	+85°C		
D061	$\overline{\text{MCLR}}$	±5	±200	nA	+25°C	V _{SS} ≤ V _{PIN} ≤ V _{DD}
		±15	±500	nA	+85°C	
D063	OSC1	±5	±200	nA	+25°C	V _{SS} ≤ V _{PIN} ≤ V _{DD}
		±15	±500	nA	+85°C	

Note 1: The leakage current on the $\overline{\text{MCLR}}$ pin is strongly dependent on the applied voltage level. The specified levels represent normal operating conditions. Higher leakage current may be measured at different input voltages.

2: Negative current is defined as current sourced by the pin.

PIC18F47J13 FAMILY

4. Module:

The code in [EXAMPLE 20-2: 512-BYTE SPI MASTER MODE Init AND TRANSFER](#) does not set up the PPS registers correctly to map the SPI2 pins out to the RB<0:2> pins. The corrected code example, with changes in bold, is shown below.

EXAMPLE 20-2: 512-BYTE SPI MASTER MODE Init AND TRANSFER

```
                                ;For this example, let's use RP5(RB2) for SCK2,
                                ;RP4(RB1) for SDO2, and RP3(RB0) for SDI2

                                ;Let's use SPI master mode, CKE = 0, CKP = 0,
                                ;without using slave select signalling.

InitSPIPins:
    movlb    0x0F                ;Select bank 15, for access to ODCON3 register
    bcf     ODCON3, SPI2OD       ;Let's not use open drain outputs in this example

    bcf     LATB, RB2            ;Initialize our (to be) SCK2 pin low (idle).
    bcf     LATB, RB1            ;Initialize our (to be) SDO2 pin to a known state
    bcf     TRISB, RB1           ;Make SDO2 output, and drive low
    bcf     TRISB, RB2           ;Make SCK2 output, and drive low (idle state)
    bsf     TRISB, RB0           ;SDI2 is an input, make sure it is tri-stated

                                ;Now we should unlock the PPS registers, so we can
                                ;assign the MSSP2 functions to our desired I/O pins.

    movlb    0x0E                ;Select bank 14 for access to PPS registers
    bcf     INTCON, GIE          ;I/O Pin unlock sequence will not work if CPU
                                ;services an interrupt during the sequence

    movlw   0x55                 ;Unlock sequence consists of writing 0x55
    movwf   EECON2               ;and 0xAA to the EECON2 register.
    movlw   0xAA
    movwf   EECON2
    bcf     PPSCON, IOLOCK       ;We may now write to RPINRx and RPORx registers
    bsf     INTCON, GIE          ;May now turn back on interrupts if desired

    movlw   0x03                 ;RP3 will be SDI2
    movwf   RPINR21              ;Assign the SDI2 function to pin RP3
    movlw   0x0A                 ;Let's assign SDO2 output to pin RP4
    movwf   RPOR4                 ;RPOR4 maps output signals to RP4 pin
    movlw   0x0B                 ;0x0B is SCK2 output
    movwf   RPOR5                 ;Assign SCK2 output signal to the RP5 (RB2) pin
    movlw   0x05                 ;SCK2 needs to be configured as an input on the
                                ;same pin
    movwf   RPINR22              ;SCK2 input function taken from RP5 pin
    movlb    0x0F                ;Done with PPS registers, bank 15 has other SFRs

InitMSSP2:
    clrf    SSP2STAT             ;CKE = 0, SMP = 0 (sampled at middle of bit)
    movlw   b'00000000'         ;CKP = 0, SPI Master mode, Fosc/4
    movwf   SSP2CON1            ;MSSP2 initialized
    bsf     SSP2CON1, SSPEN      ;Enable the MSSP2 module

InitSPIDMA:
    movlw   b'00111010'         ;Full duplex, RX/TXINC enabled, no SSCON
    movwf   DMACON1             ;DLYINTEN is set, so DLYCYC3:DLYCYC0 = 1111
    movlw   b'11110000'         ;Minimum delay between bytes, interrupt
    movwf   DMACON2             ;only once when the transaction is complete
```


PIC18F47J13 FAMILY

EXAMPLE 20-2: 512-BYTE SPI MASTER MODE Init AND TRANSFER (CONTINUED)

```
                                ;Somewhere else in our project, lets assume we have
                                ;allocated some RAM for use as SPI receive and
                                ;transmit buffers.

;    udata    0x500
;DestBuf    res    0x200    ;Reserve 0x500-0x6FF for use as our SPI
;           ;           ;receive data buffer in this example
;SrcBuf     res    0x200    ;Reserve 0x700-0x8FF for use as our SPI
;           ;           ;transmit data buffer in this example

PrepareTransfer:
    movlw    HIGH(DestBuf)    ;Get high byte of DestBuf address (0x05)
    movwf    RXADDRH         ;Load upper four bits of the RXADDR register
    movlw    LOW(DestBuf)     ;Get low byte of the DestBuf address (0x00)
    movwf    RXADDRL         ;Load lower eight bits of the RXADDR register

    movlw    HIGH(SrcBuf)     ;Get high byte of SrcBuf address (0x07)
    movwf    TXADDRH         ;Load upper four bits of the TXADDR register
    movlw    LOW(SrcBuf)     ;Get low byte of the SrcBuf address (0x00)
    movwf    TXADDRL         ;Load lower eight bits of the TXADDR register

    movlw    0x01            ;Lets move 0x200 (512) bytes in one DMA xfer
    movwf    DMABCH          ;Load the upper two bits of DMABC register
    movlw    0xFF           ;Actual bytes transferred is (DMABC + 1), so
    movwf    DMABCL          ;we load 0x01FF into DMABC to xfer 0x200 bytes

BeginXfer:
    bsf      DMACON1, DMAEN   ;The SPI DMA module will now begin transferring
                                ;the data taken from SrcBuf, and will store
                                ;received bytes into DestBuf.

;Execute whatever                                ;CPU is now free to do whatever it wants to
                                                ;and the DMA operation will continue without
                                                ;intervention, until it completes.

                                                ;When the transfer is complete, the SSP2IF flag in
                                                ;the PIR3 register will become set, and the DMAEN bit
                                                ;is automatically cleared by the hardware.
                                                ;The DestBuf (0x500-0x7FF) will contain the received
                                                ;data. To start another transfer, firmware will need
                                                ;to reinitialize RXADDR, TXADDR, DMABC and then
                                                ;set the DMAEN bit.
```

PIC18F47J13 FAMILY

APPENDIX A: DOCUMENT REVISION HISTORY

Rev A Document (6/2010)

Initial release of this document. Added silicon issues 1 (Charge Time Measurement Unit – CTMU), 2 (Phase Locked Loop – PLL), 3 (Analog-to-Digital Converter – ADC), 4 (Master Synchronous Serial Port – MSSP), 5 (Master Synchronous Serial Port – MSSP) and 6 (Enhanced Universal Synchronous Asynchronous Receiver Transmitter (EUSART)).

Rev B Document 10/2010)

Added data sheet clarification issues 1 (Guidelines For Getting Started with PIC18FJ Microcontrollers) and 2 (Reset).

Rev C Document 11/2010

Added data sheet clarification issue 3 (Electrical Characteristics).

Rev D Document 1/2011

Added data sheet clarification issue 4 (Code Example).

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC³² logo, rPIC and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniscient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICTail, REAL ICE, rLAB, Select Mode, Total Endurance, TSHARC, UniWinDriver, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2011, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN:978-1-60932-849-8

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC[®] MCUs and dsPIC[®] DSCs, KEELOQ[®] code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.

**QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==**



MICROCHIP

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Cleveland
Independence, OH
Tel: 216-447-0464
Fax: 216-447-0643

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo
Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara
Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto
Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Chongqing
Tel: 86-23-8980-9588
Fax: 86-23-8980-9500

China - Hong Kong SAR
Tel: 852-2401-1200
Fax: 852-2401-3431

China - Nanjing
Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian
Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Xiamen
Tel: 86-592-2388138
Fax: 86-592-2388130

China - Zhuhai
Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444
Fax: 91-80-3090-4123

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Yokohama
Tel: 81-45-471- 6166
Fax: 81-45-471-6122

Korea - Daegu
Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur
Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang
Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-6578-300
Fax: 886-3-6578-370

Taiwan - Kaohsiung
Tel: 886-7-213-7830
Fax: 886-7-330-9305

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham
Tel: 44-118-921-5869
Fax: 44-118-921-5820

08/04/10