

PIC18F87J11 Family Silicon Errata and Data Sheet Clarification

The PIC18F87J11 family devices that you have received conform functionally to the current Device Data Sheet (DS39778D), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).

The errata described in this document will be addressed in future revisions of the PIC18F87J11 family silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (A6).

Data Sheet clarifications and corrections start on page 5, following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers and emulation tools, which are available at the Microchip corporate web site (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with MPLAB ICD 2 or PICKIT™ 3:

1. Using the appropriate interface, connect the device to the MPLAB ICD 2 programmer/debugger or PICKIT™ 3.
2. From the main menu in MPLAB IDE, select *Configure>Select Device*, and then select the target part number in the dialog box.
3. Select the MPLAB hardware tool (*Debugger>Select Tool*).
4. Perform a "Connect" operation to the device (*Debugger>Connect*). Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC18F87J11 family silicon revisions are shown in [Table 1](#).

TABLE 1: SILICON DEVREV VALUES

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾					
		A1	A2	A4	A5	A6	C1
PIC18F66J11	444h	1h	2h	4h	5h	6h	10h
PIC18F66J16	446h						
PIC18F67J11	448h						
PIC18F86J11	44Eh						
PIC18F86J16	450h						
PIC18F87J11	452h						

Note 1: The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format "DEVID DEVREV".

2: Refer to the "PIC18F6XJXX/8XJXX Flash Microcontroller Programming Specification" (DS39644) for detailed information on Device and Revision IDs for your specific device.

PIC18F87J11 FAMILY

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Num	Issue Summary	Affected Revisions ⁽¹⁾					
				A1	A2	A4	A5	A6	C1
MSSPx	I ² C™ Slave Reception	1.	When configured for I ² C slave reception, the MSSPx module may not receive the correct data if the SSPxBUF register is not read within a window after an SSPxIF interrupt occurs.	X	X	X	X	X	X
Oscillator Configuration	PLL	2.	When Phase Lock Loop (PLL) is enabled, if the PLL input frequency is higher than 8 MHz, there may be problems accessing the RAM.	X	X				
Voltage Regulator	VDDCORE	3.	If VDDCORE drops below approximately 2.45V while the on-chip core voltage regulator is enabled and operating in Voltage Tracking mode, the REGSLP bit (WDTCON <7>) will be automatically cleared.	X					
SRAM	Read/Write	4.	Any read or write access to SRAM will increase the current consumption of the device – varying with how often the SRAM is accessed.	X					
Low-Voltage Detect	LVDSTAT	5.	The LVDSTAT VDDCORE status bit is not implemented in the cited revision of silicon.	X					
MSSPx	I ² C™ Master mode	6.	In Master mode, the first clock may become narrower than the configuration width if the slave performs a clock stretch and release.	X	X	X	X	X	X
EUSART	Synchronous Mode	7.	The TRMT bit may not indicate when the TSR register is empty.	X	X	X	X	X	X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

Silicon Errata Issues

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (A6).

1. Module: Master Synchronous Serial Port (MSSPx)

When configured for I²C™ slave reception, the MSSPx module may not receive the correct data, in extremely rare cases. This occurs only if the Serial Receive/Transmit Buffer Register (SSPxBUF) is not read within a window after the SSPxIF interrupt (PIRx<3>) has occurred.

Work around

The issue can be resolved in either of these ways:

- Prior to the I²C slave reception, enable the clock stretching feature.

This is done by setting the SEN bit (SSPxCON2<0>).

- Each time the SSPxIF is set, read the SSPxBUF before the first rising clock edge of the next byte being received.

Affected Silicon Revisions

A1	A2	A4	A5	A6	C1		
X	X	X	X	X	X		

2. Module: Oscillator Configurations (PLL)

When Phase Lock Loop (PLL) is enabled, if the PLL input frequency is higher than 8 MHz, there may be problems accessing the RAM.

Work around

Limit the PLL input frequency from 4 MHz to 8 MHz. This will cause the system clock to operate from 16 MHz to 32 MHz.

If it is necessary to run the device above 32 MHz, do not enable PLL and use the EC mode.

Affected Silicon Revisions

A1	A2	A4	A5	A6	C1		
X	X						

3. Module: Voltage Regulator

If VDDCORE drops below approximately 2.45V while the on-chip core voltage regulator is enabled, and operating in Voltage Tracking mode, the REGSLP bit (WDTCON <7>) will be automatically cleared. The REGSLP bit cannot be set again by firmware until VDDCORE rises back above the 2.45V approximate threshold.

Additionally, the REGSLP bit retains its previous state upon all Resets except POR.

Work around

None.

Affected Silicon Revisions

A1	A2	A4	A5	A6	C1		
X							

PIC18F87J11 FAMILY

4. Module: SRAM

Any access to SRAM, either in the form of read or write operations, will increase the current consumption of the device, depending on how often the SRAM is accessed. A small current increase is normal, but in this cited silicon revision, the difference may be significant and of particular concern for low-power applications.

For further details, see [Table 3](#).

TABLE 3: TYPICAL CURRENT CONSUMPTION

Case 1:			
Voltage Regulator Enabled Temperature = 25°C SEC_RUN mode using 32 kHz Timer1 Crystal			
Condition	ID _{DD} (μA)	V _{DD} (V)	
No RAM access ⁽¹⁾	59	3.3	
Typ RAM access ⁽²⁾	201	3.3	
Extreme RAM access ⁽³⁾	906	3.3	
Case 2:			
Voltage Regulator Disabled V _{DDCORE} is tied to V _{DD} Temperature = 25°C SEC_RUN mode using 32 kHz Timer1 Crystal			
Condition	ID _{DD} (μA)	V _{DD} (V)	V _{DDCORE} (V)
No RAM access ⁽¹⁾	20	2.5	2.5
Typ RAM access ⁽²⁾	132	2.5	2.5
Extreme RAM access ⁽³⁾	723	2.5	2.5

- Note 1:** Code execution patterns where no instructions access SRAM.
2: Code execution that accesses SRAM, once every seven instruction cycles.
3: Code execution where every instruction cycle executes an instruction that accesses SRAM.

Work around

None.

Affected Silicon Revisions

A1	A2	A4	A5	A6	C1		
X							

5. Module: Low-Voltage Detect

The LVDSTAT, V_{DDCORE} status bit (WDTCON<6>), is not implemented in this revision of silicon.

Work around

None.

Affected Silicon Revisions

A1	A2	A4	A5	A6	C1		
X							

6. Module: MSSPx (I²C™ Master)

If the module is in I²C Master mode, and the slave performs clock stretching, the first clock pulse after the slave releases the SCLx line may be narrower than the configured clock width. This may result in the slave missing the first clock in the next transmission/reception.

Work around

If the module is in I²C Master mode, do not allow the slave to perform clock stretching. Alternately, the master can slow down the SCLx clock frequency to a level where the slave can detect the narrowed clock pulse.

Affected Silicon Revisions

A1	A2	A4	A5	A6	C1		
X	X	X	X	X	X		

7. Module: Enhanced Universal Synchronous Asynchronous Receiver Transmitter (EUSART)

In Synchronous Slave Transmission mode, the TRMT bit (TXSTA<1>) may not indicate when the TSR register is empty.

Work around

Instead of polling the TRMT bit to determine the status of the EUSART, poll the TXIF flag (PIR1<4>) to determine when new data can be written to the TXREG register.

Affected Silicon Revisions

A1	A2	A4	A5	A6	C1		
X	X	X	X	X	X		

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS39778D):

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

1. Module: Table 27-1: Memory Programming Requirements

On page 398, the parameter, D132, which provides the minimum and maximum voltage levels of the Self-Timed Erase or Write for VDD and VDDCORE, are included. A new parameter (D133B) is added. The TWE parameter number and conditions column are changed. The changed/ appended values are indicated in bold text in the following table:

TABLE 27-1: MEMORY PROGRAMMING REQUIREMENTS

DC CHARACTERISTICS			Standard Operating Conditions (unless otherwise stated) Operating temperature $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$ for industrial				
Param No.	Sym	Characteristic	Min	Typ†	Max	Units	Conditions
Program Flash Memory							
D130	EP	Cell Endurance	10K	—	—	E/W	-40°C to +85°C V _{MIN} = Minimum operating voltage
D131	VPR	VDD for Read	V _{MIN}	—	3.6	V	
D132B	VPEW	Voltage for Self-Timed Erase or Write					
		VDD	2.35	—	3.6	V	ENVREG tied to VDD
		VDDCORE	2.25	—	2.7	V	ENVREG tied to Vss
D133A	TIW	Self-Timed Write Cycle Time	—	2.8	—	ms	Provided no other specifications are violated
D133B	TIE	Self-Timed Page Erase Cycle Time	—	33.0	—	ms	
D134	TRETD	Characteristic Retention	20	—	—	Year	
D135	IDDP	Supply Current during Programming	—	3	14	mA	
D140	TWE	Writes per Erase Cycle	—	—	1	—	For each physical address

† Data in “Typ” column is at 3.3V, 25°C unless otherwise stated. These parameters are for design guidance only and are not tested.

PIC18F87J11 FAMILY

2. Module: Table 27-2: Comparator Specifications

On page 399, the maximum Input Offset Voltage (Parameter No. D300) is changed to ± 25 mV.

The parameter numbers for TRESP and TMC2OV are changed to D303 and D304, respectively.

A new parameter, D305, for VIRV is added.

The changed/appended values are indicated in bold text in the following table:

TABLE 27-2: COMPARATOR SPECIFICATIONS

Operating Conditions: $3.0V < V_{DD} < 3.6V$, $-40^{\circ}C < T_A < +85^{\circ}C$ (unless otherwise stated)							
Param No.	Sym	Characteristics	Min	Typ	Max	Units	Comments
D300	VIOFF	Input Offset Voltage	—	± 5.0	± 25	mV	
D301	VICM	Input Common Mode Voltage	0	—	$AV_{DD} - 1.5$	V	
D302	CMRR	Common Mode Rejection Ratio	55	—	—	dB	
D303	TRESP	Response Time ⁽¹⁾	—	150	400	ns	
D304	TMC2OV	Comparator Mode Change to Output Valid	—	—	10	μs	
D305	VIRV	Internal Reference Voltage	—	1.2	—	V	

Note 1: Response time measured with one comparator input at $(V_{DD} - 1.5)/2$, while the other input transitions from VSS to VDD.

3. Module: Table 27-4: Internal Voltage Regulator Specifications

On page 399, the comments column for the CF is changed. The note which states “These parameters are characterized but not tested” is removed. The changed content is indicated in bold text in the following table:

TABLE 27-4: INTERNAL VOLTAGE REGULATOR SPECIFICATIONS

Operating Conditions: $-40^{\circ}C < T_A < +85^{\circ}C$ (unless otherwise stated)							
Param No.	Sym	Characteristics	Min	Typ	Max	Units	Comments
	VRGOUT	Regulator Output Voltage*	—	2.5	—	V	
	CF	External Filter Capacitor Value*	4.7	10	—	μF	Capacitor must be low series resistance (<5 Ohms)

PIC18F87J11 FAMILY

4. Module: Section 27.3 “DC Characteristics: PIC18F87J11 Family (Industrial)”

On page 396, the characteristics and conditions of the Input Leakage Current are updated for the Analog (D060) and included for the Digital (D060A) I/O ports. The changed values are indicated in bold text in the following table:

DC CHARACTERISTICS			Standard Operating Conditions (unless otherwise stated) Operating temperature $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$ for industrial			
Param No.	Symbol	Characteristic	Min	Max	Units	Conditions
	V_{IL}	Input Low Voltage All I/O Ports: with TTL Buffer	V_{SS}	$0.15 V_{DD}$	V	$V_{DD} < 3.3\text{V}$
D030			—	0.8	V	$3.3\text{V} \leq V_{DD} \leq 3.6\text{V}$
D030A						
D031		with Schmitt Trigger Buffer	V_{SS}	$0.2 V_{DD}$	V	
D032		$\overline{\text{MCLR}}$	V_{SS}	$0.2 V_{DD}$	V	
D033		OSC1	V_{SS}	$0.3 V_{DD}$	V	HS, HSPLL modes
D033A		OSC1	V_{SS}	$0.2 V_{DD}$	V	EC, ECPLL modes
D034		T1CKI	V_{SS}	0.3	V	
	V_{IH}	Input High Voltage I/O Ports with Non 5.5V Tolerance:⁽²⁾ with TTL Buffer	$0.25 V_{DD} + 0.8\text{V}$	V_{DD}	V	$V_{DD} < 3.3\text{V}$
D040			2.0	V_{DD}	V	$3.3\text{V} \leq V_{DD} \leq 3.6\text{V}$
D040A						
D041		with Schmitt Trigger Buffer	$0.8 V_{DD}$	V_{DD}	V	
		I/O Ports with 5.5V Tolerance:⁽²⁾ with TTL Buffer	$0.25 V_{DD} + 0.8\text{V}$	5.5	V	$V_{DD} < 3.3\text{V}$
Dxxx			2.0	5.5	V	$3.3\text{V} \leq V_{DD} \leq 3.6\text{V}$
DxxxA						
Dxxx		with Schmitt Trigger Buffer	$0.8 V_{DD}$	5.5	V	
D042		$\overline{\text{MCLR}}$	$0.8 V_{DD}$	V_{DD}	V	
D043		OSC1	$0.7 V_{DD}$	V_{DD}	V	HS, HSPLL modes
D043A		OSC1	$0.8 V_{DD}$	V_{DD}	V	EC, ECPLL modes
D044		T1CKI	1.6	V_{DD}	V	
	I_{IL}	Input Leakage Current⁽¹⁾ I/O Ports with Non 5.5V Tolerance:⁽²⁾	—	± 1	μA	$V_{SS} \leq V_{PIN} \leq V_{DD}$, Pin at high-impedance
D060						
D060A		I/O Ports with 5.5V Tolerance:⁽²⁾	—	± 1	μA	$V_{SS} \leq V_{PIN} \leq 5.5\text{V}$, Pin at high-impedance
D061		$\overline{\text{MCLR}}$	—	± 1	μA	$V_{SS} \leq V_{PIN} \leq V_{DD}$
D063		OSC1	—	± 5	μA	$V_{SS} \leq V_{PIN} \leq V_{DD}$

Note 1: Negative current is defined as current sourced by the pin.

2: Refer to Table 10-1 for the pins that have corresponding tolerance limits.

PIC18F87J11 FAMILY

5. Module: Example 6-2: Erasing a Flash Program Memory Row

On page 94, an instruction to enable the write process to memory for erasing the Flash programming memory row is missing in the example. The changed content is indicated in bold text in the following example:

EXAMPLE 6-2: ERASING A FLASH PROGRAM MEMORY ROW

```
                MOVLW CODE_ADDR_UPPER           ; load TBLPTR with the base
                MOVWF TBLPTRU                   ; address of the memory block
                MOVLW CODE_ADDR_HIGH
                MOVWF TBLPTRH
                MOVLW CODE_ADDR_LOW
                MOVWF TBLPTRL
ERASE_ROW
                BSF EECON1, WREN                ; enable write to memory
                BSF EECON1, FREE                ; enable Row Erase operation
                BCF INTCON, GIE                 ; disable interrupts
Required      MOVLW 55h
Sequence     MOVWF EECON2                      ; write 55h
                MOVLW 0AAh
                MOVWF EECON2                  ; write 0AAh
                BSF EECON1, WR                 ; start erase (CPU stall)
                BSF INTCON, GIE                ; re-enable interrupts
```

6. Module: Section 19.3 “SPI Mode” and Section 19.4 “I²C™ Mode”


In **Section 19.3 “SPI Mode”** on page 223 and **Section 19.4 “I²C™ Mode”** on page 233, the following new note is included to describe the procedure to disable the MSSPx module:

Note: Disabling the MSSPx module by clearing the SSPEN (SSPxCON1<5>) bit may not reset the module. It is recommended to clear the SSPxSTAT, SSPxCON1 and SSPxCON2 registers and select the mode prior to setting the SSPEN bit to enable the MSSPx module.

7. Module: Figure 19-10: I²C™ Slave Mode Timing (Transmission, 7-Bit Address)

On page 244, the figure is replaced with the new timing diagram provided in [Figure 19-10](#).

FIGURE 19-10: I²C™ SLAVE MODE TIMING (TRANSMISSION, 7-BIT ADDRESS)




PIC18F87J11 FAMILY

8. Module: **Figure 19-24: I²C™ Master Mode Waveform (Reception, 7-Bit Address)**

On page 261, the condition (R/\overline{W}) when the Acknowledge signal (ACK) is received from the slave, after transmitting the address to the slave, is changed to '1'. The changed value is indicated in bold text in [Figure 19-24](#).

FIGURE 19-24: I²C™ MASTER MODE WAVEFORM (RECEPTION, 7-BIT ADDRESS)



PIC18F87J11 FAMILY

9. Module: Table 1-3: PIC18F6XJ1X Pinout I/O Descriptions

On page 20, the pin type for the RF3, RF4 and RF5 pins is changed from I (Input) to I/O (Input/Output). The changed content is indicated in bold text in the following table.

Pin Name	Pin Number	Pin Type	Buffer Type	Description
	64-TQFP			
RF1/AN6/C2OUT	17			PORTF is a bidirectional I/O port. Digital I/O. Analog input 6. Comparator 2 output.
RF1		I/O	ST	
AN6		I	Analog	
C2OUT		O	—	
RF2/PMA5/AN7/C1OUT	16			Digital I/O. Parallel Master Port address. Analog input 7. Comparator 1 output.
RF2		I/O	ST	
PMA5		O	—	
AN7		I	Analog	
C1OUT		O	—	
RF3/AN8/C2INB	15			Digital I/O. Analog input 8. Comparator 2 input B.
RF3		I/O	ST	
AN8		I	Analog	
C2INB		I	Analog	
RF4/AN9/C2INA	14			Digital I/O. Analog input 8. Comparator 2 input A.
RF4		I/O	ST	
AN9		I	Analog	
C2INA		I	Analog	
RF5/AN10/C1INB/CVREF	13			Digital I/O. Analog input 10. Comparator 1 input B. Comparator reference voltage output.
RF5		I/O	ST	
AN10		I	Analog	
C1INB		I	Analog	
CVREF		O	Analog	
RF6/AN11/C1INA	12			Digital I/O. Analog input 11. Comparator 1 input A.
RF6		I/O	ST	
AN11		I	Analog	
C1INA		I	Analog	
RF7/SS1	11			Digital I/O. SPI slave select input.
RF7		I/O	ST	
SS1		I	TTL	

Legend: TTL = TTL compatible input
 ST = Schmitt Trigger input with CMOS levels
 I = Input
 P = Power
 CMOS = CMOS compatible input or output
 Analog = Analog input
 O = Output
 OD = Open-Drain (no P diode to VDD)

Note 1: Default assignment for ECCP2/P2A when Configuration bit, CCP2MX, is set.
2: Alternate assignment for ECCP2/P2A when Configuration bit, CCP2MX, is cleared.

10. Module: Memory Organization

On page 75, the note at the end of **Section 5.3.4 “Special Function Registers”** has been amended. The new information is indicated in bold text.


Note: Addresses, F5Ah through F5Fh, are not part of the Access Bank. These registers must always be accessed using the Bank Select Register. **Addresses, F40h to F59h, are not implemented and not accessible to the user.**

11. Module: Memory Organization

On page 73, in Figure 5-7, Note 2 has been added. The additional note is indicated in bold text in Figure 5-7.

PIC18F87J11 FAMILY

FIGURE 5-7: DATA MEMORY MAP FOR PIC18F87J11 FAMILY DEVICES



12. Module: Guidelines for Getting Started with PIC18FJ Microcontrollers

Section 2.4 “Voltage Regulator Pins (ENVREG and VCAP/VDDCORE)” has been replaced with a new and more detailed section. The entire text follows:

2.4 Voltage Regulator Pins (ENVREG and VCAP/VDDCORE)

The on-chip voltage regulator enable pin, ENVREG, must always be connected directly to either a supply voltage or to ground. Tying ENVREG to VDD enables the regulator, while tying it to ground disables the regulator. Refer to Section 23.3.2 “On-Chip Voltage Regulator” for details on connecting and using the on-chip regulator.

When the regulator is enabled, a low-ESR (< 5Ω) capacitor is required on the VCAP/VDDCORE pin to stabilize the voltage regulator output voltage. The VCAP/VDDCORE pin must not be connected to VDD and must use a capacitor of 10 μF connected to ground. The type can be ceramic or tantalum. Suitable examples of capacitors are shown in Table 2-1. Capacitors with equivalent specification can be used.

Designers may use Figure 2-3 to evaluate ESR equivalence of candidate devices.

It is recommended that the trace length not exceed 0.25 inch (6 mm). Refer to Section 26.0 “Electrical Characteristics” for additional information.

When the regulator is disabled, the VCAP/VDDCORE pin must be tied to a voltage supply at the VDDCORE level. Refer to Section 26.0 “Electrical Characteristics” for information on VDD and VDDCORE.

Note that the “LF” versions of some low pin count PIC18FJ parts (e.g., the PIC18LF45J10) do not have the ENVREG pin. These devices are provided with the voltage regulator permanently disabled; they must always be provided with a supply voltage on the VDDCORE pin.

FIGURE 2-3 FREQUENCY vs. ESR PERFORMANCE FOR SUGGESTED VCAP




TABLE 2-1 SUITABLE CAPACITOR EQUIVALENTS

Make	Part #	Nominal Capacitance	Base Tolerance	Rated Voltage	Temp. Range
TDK	C3216X7R1C106K	10 μF	±10%	16V	-55 to 125°C
TDK	C3216X5R1C106K	10 μF	±10%	16V	-55 to 85°C
Panasonic	ECJ-3YX1C106K	10 μF	±10%	16V	-55 to 125°C
Panasonic	ECJ-4YB1C106K	10 μF	±10%	16V	-55 to 85°C
Murata	GRM32DR71C106KA01L	10 μF	±10%	16V	-55 to 125°C
Murata	GRM31CR61C106KC31L	10 μF	±10%	16V	-55 to 85°C

PIC18F87J11 FAMILY

2.4.1 CONSIDERATIONS FOR CERAMIC CAPACITORS

In recent years, large value, low-voltage, surface mount ceramic capacitors have become very cost effective in sizes up to a few tens of microfarad. The low-ESR, small physical size and other properties make ceramic capacitors very attractive in many types of applications.

Ceramic capacitors are suitable for use with the VDDCORE voltage regulator of this microcontroller. However, some care is needed in selecting the capacitor to ensure that it maintains sufficient capacitance over the intended operating range of the application.


Typical low cost, 10 μF ceramic capacitors are available in X5R, X7R and Y5V dielectric ratings (other types are also available, but are less common). The initial tolerance specifications for these types of capacitors are often specified as $\pm 10\%$ to $\pm 20\%$ (X5R and X7R), or $-20\%/+80\%$ (Y5V). However, the effective capacitance that these capacitors provide in an application circuit will also vary based on additional factors, such as the applied DC bias voltage and the temperature. The total in-circuit tolerance is, therefore, much wider than the initial tolerance specification.

The X5R and X7R capacitors typically exhibit satisfactory temperature stability (ex: $\pm 15\%$ over a wide temperature range, but consult the manufacturer's data sheets for exact specifications). However, Y5V capacitors typically have extreme temperature tolerance specifications of $+22\%/ -82\%$. Due to the extreme temperature tolerance, a 10 μF nominal rated Y5V type capacitor may not deliver enough total capacitance to meet minimum VDDCORE voltage regulator stability and transient response requirements. Therefore, Y5V capacitors are not recommended for use with the Vddcore regulator if the application must operate over a wide temperature range.

In addition to temperature tolerance, the effective capacitance of large value ceramic capacitors can vary substantially, based on the amount of DC voltage applied to the capacitor. This effect can be very significant, but is often overlooked or is not always documented.

A typical DC bias voltage vs. capacitance graph for X7R type and Y5V type capacitors is shown in [Figure 2-4](#).

FIGURE 2-4 DC BIAS VOLTAGE vs. CAPACITANCE CHARACTERISTICS



When selecting a ceramic capacitor to be used with the VDDCORE voltage regulator, it is suggested to select a high-voltage rating, so that the operating voltage is a small percentage of the maximum rated capacitor voltage. For example, choose a ceramic capacitor rated at 16V for the 2.5V VDDCORE voltage. Suggested capacitors are shown in [Table 2-1](#).

DOCUMENT REVISION HISTORY

Rev A Document (2/2010)

Combined existing silicon and data sheet errata documents into the new, single document format. Added the A6 silicon revision, but no issues or clarifications.

This document replaces these errata documents:

- DS80418A, "*PIC18F87J11 Family Rev. A5 Silicon Errata*"
- DS80417A, "*PIC18F87J11 Family Rev. A4 Silicon Errata*"
- DS80344A, "*PIC18F87J11 Family Rev. A2 Silicon Errata*"
- DS80305B, "*PIC18F87J11 Family Rev. A1 Silicon Errata*"
- DS80408B, "*PIC18F87J11 Family Data Sheet Errata*"

Rev B Document (7/2010)

Added silicon issue 6 (MSSPx I²C™ Master).

Added data sheet clarifications 10 and 11 (Memory Organization).

Rev C Document (8/2010)

Added silicon revision B0; includes existing silicon issues 1 (Master Synchronous Serial Port – MSSPx) and 6 (MSSPx – I²C Master).

No new data sheet clarifications added.

Rev D Document (2/2011)

Replaced silicon revision B0 with revision C1 for lower pin count devices. Added silicon issue 12 (Enhanced Universal Synchronous Asynchronous Receiver Transmitter (EUSART)). Removed data sheet clarification 12 (Electrical Characteristics).

PIC18F87J11 FAMILY

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC³² logo, rPIC and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniscient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICTail, REAL ICE, rLAB, Select Mode, Total Endurance, TSHARC, UniWinDriver, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2011, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN: 978-1-60932-921-1

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC[®] MCUs and dsPIC[®] DSCs, KEELOQ[®] code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.

**QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==**



MICROCHIP

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Cleveland
Independence, OH
Tel: 216-447-0464
Fax: 216-447-0643

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara
Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto
Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Chongqing
Tel: 86-23-8980-9588
Fax: 86-23-8980-9500

China - Hong Kong SAR
Tel: 852-2401-1200
Fax: 852-2401-3431

China - Nanjing
Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian
Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Xiamen
Tel: 86-592-2388138
Fax: 86-592-2388130

China - Zhuhai
Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444
Fax: 91-80-3090-4123

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Yokohama
Tel: 81-45-471- 6166
Fax: 81-45-471-6122

Korea - Daegu
Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur
Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang
Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-6578-300
Fax: 886-3-6578-370

Taiwan - Kaohsiung
Tel: 886-7-213-7830
Fax: 886-7-330-9305

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham
Tel: 44-118-921-5869
Fax: 44-118-921-5820

02/18/11