



# dsPIC33FJ32GS406/606/608/610 and dsPIC33FJ64GS406/606/608/610

## dsPIC33FJ32GS406/606/608/610 and dsPIC33FJ64GS406/606/608/610 Family Silicon Errata and Data Sheet Clarification

The dsPIC33FJ32GS406/606/608/610 and dsPIC33FJ64GS406/606/608/610 family devices that you have received conform functionally to the current Device Data Sheet (DS70591C), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).

The errata described in this document will be addressed in future revisions of the dsPIC33FJ32GS406/606/608/610 and dsPIC33FJ64GS406/606/608/610 silicon.

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (A0).

Data Sheet clarifications and corrections start on [page 7](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers and emulation tools, which are available at the Microchip corporate web site ([www.microchip.com](http://www.microchip.com)).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with MPLAB ICD 2 or PICKit™ 3:

1. Using the appropriate interface, connect the device to the MPLAB ICD 2 programmer/debugger or PICKit 3.
2. From the main menu in MPLAB IDE, select *Configure>Select Device*, and then select the target part number in the dialog box.
3. Select the MPLAB hardware tool (*Debugger>Select Tool*).
4. Perform a "Connect" operation to the device (*Debugger>Connect*). Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

**Note:** If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various dsPIC33FJ32GS406/606/608/610 and dsPIC33FJ64GS406/606/608/610 silicon revisions are shown in [Table 1](#).

**TABLE 1: SILICON DEVREV VALUES**

Part Number	Device ID <sup>(1)</sup>	Revision ID for Silicon Revision <sup>(2)</sup>
		A0
dsPIC33FJ32GS406	0x4000	0x3000
dsPIC33FJ32GS606	0x4002	
dsPIC33FJ32GS608	0x4004	
dsPIC33FJ32GS610	0x4006	
dsPIC33FJ64GS406	0x4001	
dsPIC33FJ64GS606	0x4003	
dsPIC33FJ64GS608	0x4005	
dsPIC33FJ64GS610	0x4007	

- Note 1:** The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format "DEVID DEVREV".
- 2:** Refer to the "dsPIC33F/PIC24H Flash Programming Specification" (DS70152) for detailed information on Device and Revision IDs for your specific device.

**TABLE 2: SILICON ISSUE SUMMARY**

Module	Feature	Item Number	Issue Summary	Affected Revisions <sup>(1)</sup>
				A0
ECAN	WAKIF bit	1.	The WAKIF bit in the CxINTF register cannot be cleared by software instruction after the device is interrupted from Sleep due to activity on the CAN bus.	X
Reserved	—	2.	—	—
SPI	ASS1 Pin	3.	The ASS1 pin function does not work.	X
JTAG	Boundary Scan	4.	The boundary scan cells for the RD3 and RD13 pins are swapped.	X
PWM	Secondary Master Time Base Synchronization	5.	The external time base synchronization output pin, SYNCO2, does not work.	X
Interrupts	Exit from Doze Mode on Interrupt	6.	An interrupt with a priority level lower than the CPU priority level will trigger the dsPIC <sup>®</sup> DSC device to exit the Doze mode, but an interrupt request will not be generated.	X
ADC	Current Consumption in Sleep Mode	7.	If the ADC module is in an enabled state when the device enters Sleep mode, the power-down current (IPD) of the device may exceed the device data sheet specifications.	X
PWM	External Period Reset Mode (XPRES)	8.	When using the External Period Reset mode, PWM period will get reset immediately if the Reset signal is active at the end of the PWM ON time.	X
High Speed PWM	PWM Module Enable	9.	A glitch may be observed on the PWM pins when the PWM module is enabled after assignment of pin ownership to the PWM module.	X
ECAN	Error Interrupt Flag	10.	The ERRIF status bit does not get set when a CAN error condition occurs.	X

**Note 1:** Only those issues indicated in the last column apply to the current silicon revision.

**Silicon Errata Issues**

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. The shaded column in the “Affected Silicon Revisions” table included in each issue indicates that the issue applies to the most current revision of silicon (**A0**).

**1. Module: ECAN**

The WAKIF bit in the CxINTF register cannot be cleared by software instruction after the device is interrupted from Sleep due to activity on the CAN bus.

When the device wakes up from Sleep due to CAN bus activity, the ECAN module is placed in operational mode. The ECAN event interrupt occurs due to the WAKIF flag. Trying to clear the flag in the Interrupt Service Routine (ISR) may not clear the flag. The WAKIF bit being set will not cause repetitive Interrupt Service Routine execution.

**Work around**

Although the WAKIF bit does not clear, the device Sleep and ECAN Wake function continue to work as expected. If the ECAN event is enabled, the CPU will enter the Interrupt Service Routine due to the WAKIF flag getting set. The application can maintain a secondary flag, which tracks the device Sleep and Wake events.

**Affected Silicon Revisions**

<b>A0</b>								
X								

**2. Module: Reserved**

The issue in the previous version of the document has been removed.

**3. Module: SPI**

The  $\overline{ASS1}$  pin is provided as an alternative pin for the slave select function of the SPI1 module. However, the alternate slave select function ( $\overline{ASS1}$ ) on this pin does not work. All other functions multiplexed on the same pin work as expected.

**Work around**

Use the  $\overline{SS1}$  pin for the slave select function.

**Affected Silicon Revisions**

<b>A0</b>								
X								

**4. Module: JTAG**

The boundary scan cells for the RD3 and RD13 pins are swapped. When running the boundary scan test, an input to the RD3 pin excites the RD13 pin, and vice versa.

This erratum does not affect any other functionality on the RD3 and RD13 pins.

**Work around**

None.

**Affected Silicon Revisions**

<b>A0</b>								
X								

**5. Module: PWM**

The SYNCO2 pin can be used to transmit synchronization pulses to generate an identical PWM time base on another device. However, the SYNCO2 function does not work as expected. As a result of this erratum, the secondary master time base cannot be used for synchronizing a slave device.

All other functions multiplexed on the same pin work as expected.

**Work around**

A spare PWMxL/PWMxH pin can be used as the synchronization source output instead of the SYNCO2 pin using the following procedure:

1. Configure the spare PWMxL/PWMxH pin to operate on the same time base, period, and phase as the synchronizing (or reference) PWM channel.
2. Set up the duty cycle for the spare PWMxL/PWMxH pin to the desired pulse width for the synchronization signal (typically 100 ns at the highest PWM resolution).
3. Connect the spare PWMxL/PWMxH pin to the synchronization input of the slave PWM generator.

**Affected Silicon Revisions**

<b>A0</b>								
X								

**6. Module: Interrupts**

When the dsPIC<sup>®</sup> DSC device is operating in Doze mode, any interrupt should trigger the device to exit Doze mode and generate an interrupt request (IRQ) regardless of the interrupt priority level. However, if the interrupt priority level is lower than the CPU priority level, the interrupt request will not be generated. As a result, the CPU will not detect that it has exited Doze mode.

**Work around**

Any interrupt that is expected to wake the CPU from Doze mode must be configured for an interrupt priority level higher than the CPU priority level. This work around can be implemented in software right before the device enters Doze mode and reverted to the desired priority level after it wakes up from Doze mode.

**Affected Silicon Revisions**

<b>A0</b>								
X								

**7. Module: ADC**

If the ADC module is in an enabled state when the device enters Sleep mode as a result of executing a `PWRSVAV #0` instruction, the device power-down current (IPD) may exceed the specifications listed in the device data sheet. This may happen even if the ADC module is disabled by clearing the ADON bit prior to entering Sleep mode.

**Work around**

In order to remain within the IPD specifications listed in the device data sheet, the user software must completely disable the ADC module by setting the ADC Module Disable bit in the corresponding Peripheral Module Disable register (PMDx), prior to executing a `PWRSVAV #0` instruction.

**Affected Silicon Revisions**

<b>A0</b>								
X								

**8. Module: PWM**

The External Period Reset mode is used to reset the PWM period when the selected reset signal is asserted during the OFF time of the PWM. If the reset signal is asserted during the PWM ON time, then the reset signal must be ignored.

However, on the dsPIC33FJ32GS406/606/608/610 and dsPIC33FJ64GS406/606/608/610 devices, the reset signal is not ignored at the end of the PWM ON time. Therefore, the PWM period will be reset immediately after the end of the PWM ON time.

**Work around**

Ensure that the External Period Reset signal is asserted during the PWM OFF time.

**Affected Silicon Revisions**

<b>A0</b>								
X								

**9. Module: High Speed PWM**

The PENH and PENL bits in the IOCONx register are used to assign ownership of the pins to either the PWM module or the GPIO module. The correct procedure to configure the PWM module is to first assign pin ownership to the PWM module and then enabling it using the PTEN bit in the PTCN register.

If the PWM module is enabled using the above sequence, then a glitch may be observed on the PWM pins before actual switching of the PWM outputs begins. This glitch may cause momentary turn ON of power MOSFETs that are driven by the PWM pins and may cause damage to the application hardware.

**Work around**

Follow the given sequence to avoid any glitches from appearing on the PWM outputs at the time of enabling.

1. Configure the respective PWM pins to digital inputs using the TRISx registers. This step will put the PWM pins in a high-impedance state. The PWM outputs must be maintained in a safe state by using pull-up or pull-down resistors.

2. Assign pin ownership to the GPIO module by configuring IOCONx<PENH> = 0 and IOCONx<PENL> = 0.
3. Specify the PWM override state to the desired safe state for the PWM pins using the OVRDAT<1:0> bit-field in the IOCONx register.
4. Override the PWM outputs by setting IOCONx<OVRENH> = 1 and IOCONx<OVRENL> = 1.
5. Enable the PWM module by setting PTCN<PTEN> = 1.
6. Remove the PWM Overrides by making IOCONx<OVRENH> = 0 and IOCONx<OVRENL> = 0.
7. Assign pin ownership to the PWM module by setting IOCONx<PENH> = 1 and IOCONx<PENL> = 1.

The code in [Example 1](#) illustrates the use of this work around.

**EXAMPLE 1: CONFIGURE PWM MODULE TO PREVENT GLITCHES ON PWM1H AND PWM1L PINS AT THE TIME OF ENABLING**

```

TRISAbits.TRISA4 = 1; // Configure PWM1H/RA4 as digital input
                    // Ensure output is in safe state using pull-up or
                    // pull-down resistors
TRISAbits.TRISA3 = 1; // Configure PWM1L/RA3 as digital input
                    // Ensure output is in safe state using pull-up or
                    // pull-down resistors

IOCON1bits.PENH = 0; // Assign pin ownership of PWM1H/RA4 to GPIO module
IOCON1bits.PENL = 0; // Assign pin ownership of PWM1L/RA3 to GPIO module

IOCON1bits.OVRDAT = 0; // Configure override state of the PWM outputs to
                    // desired safe state.

IOCON1bits.OVRENH = 1; // Override PWM1H output
IOCON1bits.OVRENL = 1; // Override PWM1L output

PTCNbits.PTEN = 1; // Enable PWM module

IOCON1bits.OVRENH = 0; // Remove override for PWM1H output
IOCON1bits.OVRENL = 0; // Remove override for PWM1L output

IOCON1bits.PENH = 1; // Assign pin ownership of PWM1H/RA4 to PWM module
IOCON1bits.PENL = 1; // Assign pin ownership of PWM1L/RA3 to PWM module
    
```

**Affected Silicon Revisions**

A0								
X								

**10. Module: ECAN**

The ERRIF status flag (CiINTF<5>) does not get set when a CAN error condition occurs. However, the corresponding CiIF interrupt flag will get set on a CAN error condition, and an interrupt will be correctly generated if enabled.

**Work around**

Do not inspect the state of the ERRIF bit to determine if a CAN error interrupt has occurred. Instead, inspect the individual error condition status flags TXBO, TXBP, RXBP, TXWAR, RXWAR and EWARN (CiINTF<13:8>).

**Affected Silicon Revisions**

<b>A0</b>								
X								

**Data Sheet Clarifications**

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS70591C):

**Note:** Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

**1. Module: DC Characteristics: I/O Pin Input Specifications**

The maximum value for parameter DI19 (V<sub>IL</sub> specifications for SDA<sub>x</sub> and SCL<sub>x</sub> pins) was stated incorrectly in Table 31-9 of the current device data sheet. Also, parameters DI28 and DI29 (V<sub>IH</sub> specifications for SDA<sub>x</sub> and SCL<sub>x</sub> pins) were not stated. The correct values are shown in bold type in [Table 3](#).

**TABLE 3: DC CHARACTERISTICS: I/O PIN INPUT SPECIFICATIONS**

DC CHARACTERISTICS			Standard Operating Conditions: 3.0V to 3.6V (unless otherwise stated) Operating temperature -40°C ≤T <sub>A</sub> ≤+85°C for Industrial -40°C ≤T <sub>A</sub> ≤+125°C for Extended				
Param No.	Symbol	Characteristic	Min	Typ	Max	Units	Conditions
DI18	V <sub>IL</sub>	Input Low Voltage <b>SDA<sub>x</sub>, SCL<sub>x</sub></b>	V <sub>SS</sub>	—	0.3 V <sub>DD</sub>	V	SMBus disabled
DI19		<b>SDA<sub>x</sub>, SCL<sub>x</sub></b>	V <sub>SS</sub>	—	<b>0.8</b>	V	SMBus enabled
<b>DI28</b>	V <sub>IH</sub>	Input High Voltage <b>SDA<sub>x</sub>, SCL<sub>x</sub></b>	<b>0.7 V<sub>DD</sub></b>	—	<b>5.5</b>	<b>V</b>	<b>SMBus disabled</b>
<b>DI29</b>		<b>SDA<sub>x</sub>, SCL<sub>x</sub></b>	<b>2.1</b>	—	<b>5.5</b>	<b>V</b>	<b>SMBus enabled</b>

## APPENDIX A: REVISION HISTORY

### Rev A Document (10/2009)

Initial release of this document; issued for revision A0. Includes silicon issues 1 ([ECAN](#)), 2 ([SPI](#)), 3 ([SPI](#)) 4 ([JTAG](#)), 5 ([PWM](#)) and 6 ([Interrupts](#)).

### Rev B Document (6/2010)

Removed silicon issue 2 ([SPI](#)) and marked its location as reserved.

Updated the work around in silicon issue 5 ([PWM](#)).

Added silicon issues 7 ([ADC](#)), 8 ([PWM](#)) and 9 ([High Speed PWM](#)) and data sheet clarification 1 ([DC Characteristics: I/O Pin Input Specifications](#)).

### Rev C Document (11/2010)

Updated the Device IDs in [Table 1](#) for the following devices:

- dsPIC33FJ32GS606
- dsPIC33FJ32GS608
- dsPIC33FJ32GS610
- dsPIC33FJ64GS406
- dsPIC33FJ64GS606
- dsPIC33FJ64GS608

Added silicon issue 10 ([ECAN](#)).



---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

**Trademarks**

The Microchip name and logo, the Microchip logo, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC<sup>32</sup> logo, rPIC and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniscient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICTail, REAL ICE, rLAB, Select Mode, Total Endurance, TSHARC, UniWinDriver, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2010, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN: 978-1-60932-635-7

*Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC<sup>®</sup> MCUs and dsPIC<sup>®</sup> DSCs, KEELOQ<sup>®</sup> code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*

**QUALITY MANAGEMENT SYSTEM  
CERTIFIED BY DNV  
== ISO/TS 16949:2002 ==**



# MICROCHIP

## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://support.microchip.com>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Cleveland**  
Independence, OH  
Tel: 216-447-0464  
Fax: 216-447-0643

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Farmington Hills, MI  
Tel: 248-538-2250  
Fax: 248-538-2260

**Kokomo**  
Kokomo, IN  
Tel: 765-864-8360  
Fax: 765-864-8387

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**Santa Clara**  
Santa Clara, CA  
Tel: 408-961-6444  
Fax: 408-961-6445

**Toronto**  
Mississauga, Ontario,  
Canada  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Harbour City, Kowloon  
Hong Kong  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8528-2100  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

**China - Chongqing**  
Tel: 86-23-8980-9588  
Fax: 86-23-8980-9500

**China - Hong Kong SAR**  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**China - Nanjing**  
Tel: 86-25-8473-2460  
Fax: 86-25-8473-2470

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8203-2660  
Fax: 86-755-8203-1760

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xian**  
Tel: 86-29-8833-7252  
Fax: 86-29-8833-7256

**China - Xiamen**  
Tel: 86-592-2388138  
Fax: 86-592-2388130

**China - Zhuhai**  
Tel: 86-756-3210040  
Fax: 86-756-3210049

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444  
Fax: 91-80-3090-4123

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-2566-1512  
Fax: 91-20-2566-1513

**Japan - Yokohama**  
Tel: 81-45-471- 6166  
Fax: 81-45-471-6122

**Korea - Daegu**  
Tel: 82-53-744-4301  
Fax: 82-53-744-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Kuala Lumpur**  
Tel: 60-3-6201-9857  
Fax: 60-3-6201-9859

**Malaysia - Penang**  
Tel: 60-4-227-8870  
Fax: 60-4-227-4068

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-6578-300  
Fax: 886-3-6578-370

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830  
Fax: 886-7-330-9305

**Taiwan - Taipei**  
Tel: 886-2-2500-6610  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**UK - Wokingham**  
Tel: 44-118-921-5869  
Fax: 44-118-921-5820

08/04/10