



# dsPIC33FJ32MC202/204 and dsPIC33FJ16MC304

---

## dsPIC33FJ32MC202/204 and dsPIC33FJ16MC304 Rev. A2/A3/A4 Silicon Errata

---

The dsPIC33FJ32MC202/204 and dsPIC33FJ16MC304 (Rev. A2/A3/A4) devices you received were found to conform to the specifications and functionality described in the following documents:

- DS70283 – “dsPIC33FJ32MC202/204 and dsPIC33FJ16MC304 Data Sheet”
- DS70157 – “dsPIC30F/33F Programmer’s Reference Manual”

The exceptions to the specifications in the documents listed above are described in this section. The specific devices for which these exceptions are described are listed below:

- dsPIC33FJ32MC202
- dsPIC33FJ32MC204
- dsPIC33FJ16MC304

dsPIC33FJ32MC202/204 and dsPIC33FJ16MC304 Rev. A2/A3/A4 silicon is identified by performing a “Reset and Connect” operation to the device using MPLAB® ICD 2 or MPLAB REAL ICE™ in-circuit emulator, with MPLAB IDE v7.60 or later. The output window will show a successful connection to the device specified in *Configure>Select Device*. The resulting DEVREV register values for Rev. A2/A3/A4 silicon are 0x3001, 0x3002 and 0x3003, respectively.

The errata described in this document will be addressed in future revisions of silicon.

### Silicon Errata Summary

The following list summarizes the errata described in further detail through the remainder of this document:

1. JTAG Programming  
JTAG programming does not work.
2. UART Module  
The auto-baud feature may not calculate the correct baud rate when the Baud Rate Generator (BRG) is set up for 4x mode.
3. UART Module  
With the auto-baud feature selected, the Sync Break character (0x55) may be loaded into the FIFO as data.
4. UART Module  
The auto-baud feature measures baud rate inaccurately for certain baud rate and clock speed combinations.
5. UART Module  
When an auto-baud is detected, the receive interrupt may occur twice.
6. Motor Control PWM - PWM Counter Register  
PTMR does not keep counting down after halting code execution in Debug mode.
7. Quadrature Encoder Interface (QE1) Module  
The QE1 module does not generate an interrupt in a particular overflow condition.
8. UART Module  
The 16x baud clock signal on the BCLK pin is present only when the module is transmitting.
9. UART Module  
When the UART is in 4x mode (BRGH = 1) and using two Stop bits (STSEL = 1), it may sample the first Stop bit instead of the second one.
10. SPI Module  
The SPIxCON1 DISSCK bit does not influence port functionality.
11. I<sup>2</sup>C™ Module  
The BCL bit in I2CSTAT can be cleared only with 16-bit operation and can be corrupted with 1-bit or 8-bit operations on I2CSTAT.

# dsPIC33FJ32MC202/204 and dsPIC33FJ16MC304

---

## 12. I<sup>2</sup>C Module

The ACKSTAT bit is cleared shortly after being set following a slave transmit.

## 13. I<sup>2</sup>C Module: 10-bit Addressing Mode

When the I<sup>2</sup>C module is configured for 10-bit addressing using the same address bits (A10 and A9) as other I<sup>2</sup>C device A10 and A9 bits may not work as expected.

## 14. Product Identification

Revision A2 devices marked as extended temperature range (E) devices, support only industrial temperature range (I).

## 15. UART (UxE Interrupt)

The UART error interrupt may not occur, or may occur at an incorrect time, if multiple errors occur during a short period of time.

## 16. UART Module

When the UART module is operating in 8-bit mode (PDSEL = 0x) and using the IrDA<sup>®</sup> encoder/decoder (IREN = 1), the module incorrectly transmits a data payload of 80h as 00h.

## 17. Internal Voltage Regulator

When the VREGS (RCON<8>) bit is set to a logic '0' higher sleep current may be observed.

## 18. PSV Operations

An address error trap occurs in certain addressing modes when accessing the first four bytes of any PSV page.

## 19. I<sup>2</sup>C Module: 10-bit Addressing Mode

When the I<sup>2</sup>C module is configured as a 10-bit slave with an address of 0x102, the I2CxRCV register content for the lower address byte is 0x01 rather than 0x02.

## 20. I<sup>2</sup>C Module

With the I<sup>2</sup>C module enabled, the PORT bits and external Interrupt Input functions (if any) associated with SCL and SDA pins will not reflect the actual digital logic levels on the pins.

## 21. I<sup>2</sup>C Module: 10-bit Addressing Mode

The 10-bit slave does not set the RBF flag or load the I2CxRCV register, on address match if the Least Significant bits (LSbs) of the address are the same as the 7-bit reserved addresses.

## 22. Motor Control PWM – Operation in DOZE Mode

The Motor Control PWM module generates more interrupts than expected when DOZE mode is used and the output postscaler value is different than 1:1.

## 23. Quadrature Encoder Interface

The Quadrature Encoder Interface module does not generate an interrupt in a particular overflow condition.

The following sections describe the errata and work around to these errata, where they may apply.

# dsPIC33FJ32MC202/204 and dsPIC33FJ16MC304

## 1. Module: JTAG Programming

JTAG programming does not work.

### Work around

None.

## 2. Module: UART

The auto-baud feature may not calculate the correct baud rate when the High Baud Rate Enable bit, BRGH, is set. With the BRGH bit set, the baud rate calculation used is the same as BRG = 0.

### Work around

If the auto-baud feature is needed, use the Low Baud Rate mode by clearing the BRGH bit.

## 3. Module: UART

With the auto-baud feature selected, the Sync Break character (0x55) may be loaded into the FIFO as data.

### Work around

To prevent the Sync Break character from being loaded into the FIFO, load the UxBRG register with either 0x0000 or 0xFFFF prior to enabling the auto-baud feature (ABAUD = 1).

## 4. Module: UART

The auto-baud feature may miscalculate for certain baud rate and clock speed combinations, resulting in a BRG value that is greater than or less than the expected value by 1. This may result in reception or transmission failures.

### Work around

Test the auto-baud rate at various clock speed and baud rate combinations that would be used in an application. If an inaccurate BRG value is generated, manually correct the baud rate in user software.

## EXAMPLE 1:

```
unsigned int POSCNT_b15 = 0;
unsigned int Motor_Position = 0;

int main(void)
{
    // ... User's code

    MAXCNT = 0x7FFF;        // Instead of 0xFFFF

    Motor_Position = POSCNT_b15 + POSCNT;

    // ... User's code
}

void __attribute__((__interrupt__)) _QEInterrupt(void)
{
    IFSxbits.QEIIF = 0;    // Clear QEI interrupt flag
                          // x=2 for dsPIC30F
                          // x=3 for dsPIC33F
    POSCNT_b15 ^= 0x8000; // Overflow or Underflow
}
```

## 5. Module: UART

When an auto-baud is detected, the receive interrupt may occur twice. The first interrupt occurs at the beginning of the Start bit and the second after reception of the Sync field character.

### Work around

If an extra interrupt is detected, ignore the additional interrupt.

## 6. Module: Motor Control PWM - PWM Counter Register

If the PTDIR bit is set (when PTMR is counting down), and the CPU execution is halted (after a breakpoint is reached), PTMR will start counting up, as if PTDIR was zero.

### Work around

None.

# dsPIC33FJ32MC202/204 and dsPIC33FJ16MC304

## 7. Module: QEI Interrupt Generation

The Quadrature Encoder Interface (QEI) module does not generate an interrupt when MAXCNT is set to 0xFFFF and the following events occur:

1. POSCNT underflows from 0x0000 to 0xFFFF.
2. POSCNT stops.
3. POSCNT overflows from 0xFFFF to 0x0000.

This sequence of events occurs when the motor is running in one direction, which causes POSCNT to underflow to 0xFFFF. Once this happens, the motor stops and starts to run in the opposite direction, which generates an overflow from 0xFFFF to 0x0000. The QEI module does not generate an interrupt when this condition occurs.

### Work around

To prevent this condition from occurring, set MAXCNT to 0x7FFF, which will cause an interrupt to be generated by the QEI module.

In addition, a global variable could be used to keep track of bit 15, so that when an overflow or underflow condition is present on POSCNT, the variable will toggle bit 15. Example 2 shows the code required for this global variable.

### EXAMPLE 2:

```
unsigned int POSCNT_b15 = 0;
unsigned int Motor_Position = 0;

int main(void)
{
    // ... User's code

    MAXCNT = 0x7FFF;      // Instead of 0xFFFF

    Motor_Position = POSCNT_b15 + POSCNT;

    // ... User's code
}

void __attribute__((__interrupt__)) _QEInterrupt(void)
{
    IFSxbits.QEIIF = 0;   // Clear QEI interrupt flag
                        // x=2 for dsPIC30F
                        // x=3 for dsPIC33F
    POSCNT_b15 ^= 0x8000; // Overflow or Underflow
}
```

## 8. Module: UART

When the UART is configured for IR interface operations ( $UxMODE\langle 9:8 \rangle = 11$ ), the 16x baud clock signal on the BCLK pin is present only when the module is transmitting. The pin is idle at all other times.

### Work around

Configure one of the output compare modules to generate the required baud clock signal when the UART is receiving data or in an Idle state.

## 9. Module: UART

When the UART is in 4x mode ( $BRGH = 1$ ) and using two Stop bits ( $STSEL = 1$ ), it may sample the first Stop bit instead of the second one. This issue does not affect the other UART configurations.

### Work around

Use the 16x baud rate option ( $BRGH = 0$ ) and adjust the baud rate accordingly.

## 10. Module: SPI

When the SPI module is enabled, setting the DISSCK bit in the SPIxCON1 register does not allow the user application to use the SCK pin as a general purpose I/O pin.

### Work around

None.

## 11. Module: I<sup>2</sup>C

The BCL bit in I2CSTAT can be cleared only with 16-bit operation and can be corrupted with 1-bit or 8-bit operations on I2CSTAT.

### Work around

Use 16-bit operations to clear BCL.

## 12. Module: I<sup>2</sup>C

During I<sup>2</sup>C communication, after a device operating in Slave mode transmits data to the master, the ACKSTAT bit in the I2CxSTAT register is set or cleared depending on whether the master sent an ACK or NACK after the byte of data. If the ACKSTAT bit is set, it will be cleared again after some delay.

### Work around

Store the value of the ACKSTAT bit immediately after an I<sup>2</sup>C interrupt occurs.

## 13. Module: I<sup>2</sup>C

If there are two I<sup>2</sup>C devices on the bus, one of them is acting as the Master receiver and the other as the Slave transmitter. Suppose that both devices are configured for 10-bit addressing mode, and have the same value in the A10 and A9 bits of their addresses. When the Slave select address is sent from the Master, both the Master and Slave acknowledges it. When the Master sends out the read operation, both the Master and the Slave enter into Read mode and both of them transmit the data. The resultant data will be the ANDing of the two transmissions.

### Work around

Use different addresses including the higher two bits (A10 and A9) for different modules.

## 14. Module: Product Identification

Revision A2 devices marked as extended temperature range (E) devices, support only industrial temperature range (I).

### Work around

Use Revision A3 or newer devices marked as extended temperature range (E) devices.

## 15. Module: UART (UxE Interrupt)

The UART error interrupt may not occur, or may occur at an incorrect time, if multiple errors occur during a short period of time.

### Work around

Read the error flags in the UxSTA register whenever a byte is received to verify the error status. In most cases, these bits will be correct, even if the UART error interrupt fails to occur.

## 16. Module: UART (IrDA)

When the UART is operating in 8-bit mode (PDSEL = 0x) and using the IrDA encoder/decoder (IREN = 1), the module incorrectly transmits a data payload of 80h as 00h.

### Work around

None.

## 17. Module: Internal Voltage Regulator

When the VREGS (RCON<8>) bit is set to a logic '0', higher sleep current may be observed.

### Work around

Ensure VREGS (RCON<8>) bit is set to a logic '1' for device Sleep mode operation.

## 18. Module: PSV Operations

An address error trap occurs in certain addressing modes when accessing the first four bytes of an PSV page. This only occurs when using the following addressing modes:

- MOV.D
- Register indirect addressing (word or byte mode) with pre/post-decrement

### Work around

Do not perform PSV accesses to any of the first four bytes using the above addressing modes. For applications using the C language, MPLAB C30 version 3.11 or higher, provides the following command-line switch that implements a work around for the erratum.

```
-merrata=psv_trap
```

Refer to the `readme.txt` file in the MPLAB C30 v3.11 tool suite for further details.

# dsPIC33FJ32MC202/204 and dsPIC33FJ16MC304

---

## 19. Module: I<sup>2</sup>C

When the I<sup>2</sup>C module is configured as a 10-bit slave with an address of 0x102, the I2CxRCV register content for the lower address byte is 0x01 rather than 0x02; however, the module acknowledges both address bytes.

### Work around

None.

## 20. Module: I<sup>2</sup>C

With the I<sup>2</sup>C module enabled, the PORT bits and external interrupt input functions (if any) associated with the SCL and SDA pins do not reflect the actual digital logic levels on the pins.

### Work around

If the SDA and/or SCL pins need to be polled, these pins should be connected to other port pins in order to be read correctly. This issue *does not* affect the operation of the I<sup>2</sup>C module.

## 21. Module: I<sup>2</sup>C

In 10-bit Addressing mode, some address matches don't set the RBF flag or load the receive register I2CxRCV, if the lower address byte matches the reserved addresses. In particular, these include all addresses with the form XX0000XXXX and XX1111XXXX, with the following exceptions:

- 001111000X
- 011111001X
- 101111010X
- 111111011X

### Work around

Ensure that the lower address byte in 10-bit Addressing mode does not match any 7-bit reserved addresses.

## 22. Module: Motor Control PWM

When the device is operated in DOZE mode and the Motor Control PWM module has a postscaler set to any value different than 1:1 (PTOPS > 0 in PxTCON register), the Motor Control PWM module generates more interrupts than expected.

### Work around

Do not use DOZE mode with the Motor Control PWM if the time base output postscaler is different than 1:1 (PTOPS > 0 in PxTCON register).

# dsPIC33FJ32MC202/204 and dsPIC33FJ16MC304

## 23. Module: QEI – Interrupt Generation

The Quadrature Encoder Interface module does not generate an interrupt when MAXCNT is set to 0xFFFF and the following events occur:

1. POSCNT underflows from 0x0000 to 0xFFFF.
2. POSCNT stops.
3. POSCNT overflows from 0xFFFF to 0x0000.

This sequence of events occurs when a motor, which is running in one direction, making POSCNT underflow to 0xFFFF, stops in that position, and starts running in the opposite direction, generating an overflow from 0xFFFF to 0x0000. The QEI module does not generate an interrupt when this occurs.

## Work around

The MAXCNT register should be set to 0x7FFF, so that an interrupt is generated by the QEI module, should this condition occur. In addition, a global variable is needed to keep track of bit 15, so that if there is an overflow or underflow condition on the POSCNT register, this variable would toggle bit 15.

Code for achieving the work around is provided in Example 3.

### EXAMPLE 3:

```
unsigned int POSCNT_b15 = 0;
unsigned int Motor_Position = 0;

int main(void)
{
    // ... User's code

    MAXCNT = 0x7FFF; // Instead of 0xFFFF

    Motor_Position = POSCNT_b15 + POSCNT;

    // ... User's code
}
void __attribute__((__interrupt__)) _QEInterrupt(void)
{
    IFSxbits.QEIIF = 0; // Clear QEI interrupt flag
                       // x=2 for dsPIC30F
                       // x=3 for dsPIC33F
    POSCNT_b15 ^= 0x8000; // Overflow or Underflow
}
```

# dsPIC33FJ32MC202/204 and dsPIC33FJ16MC304

---

## APPENDIX A: REVISION HISTORY

### Revision A (8/2007)

Initial release of this document, which includes silicon issues 1 (JTAG Programming) and 2-4 (UART).

### Revision B (11/2007)

Added silicon issues 5 (UART) and 6 (Motor Control PWM - PWM Counter Register).

### Revision C (4/2008)

Added silicon issues 7 (QEI Interrupt Generation), 8-9 (UART), 10 (SPI), 11-13 (I<sup>2</sup>C) and 14 (Product Identification).

### Revision D (9/2008)

Added reference to silicon revision A4. Updated silicon issue 14 (Product Identification). Added silicon issues 15 (UART (UxE Interrupt)), 16 (UART (IrDA)), 17 (Internal Voltage Regulator), 18 (PSV Operations), 19-21 (I<sup>2</sup>C), 22 (Motor Control PWM) and 23 (QEI – Interrupt Generation).



---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

**Trademarks**

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, rfPIC, SmartShunt and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


FilterLab, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, PICkit, PICDEM, PICDEM.net, PICtail, PIC<sup>32</sup> logo, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rfLAB, Select Mode, Total Endurance, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2008, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

**QUALITY MANAGEMENT SYSTEM  
CERTIFIED BY DNV  
== ISO/TS 16949:2002 ==**

*Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*



---

---

## Worldwide Sales and Service

---

---

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://support.microchip.com>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Farmington Hills, MI  
Tel: 248-538-2250  
Fax: 248-538-2260

**Kokomo**  
Kokomo, IN  
Tel: 765-864-8360  
Fax: 765-864-8387

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**Santa Clara**  
Santa Clara, CA  
Tel: 408-961-6444  
Fax: 408-961-6445

**Toronto**  
Mississauga, Ontario,  
Canada  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Harbour City, Kowloon  
Hong Kong  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8528-2100  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

**China - Hong Kong SAR**  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**China - Nanjing**  
Tel: 86-25-8473-2460  
Fax: 86-25-8473-2470

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8203-2660  
Fax: 86-755-8203-1760

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xiamen**  
Tel: 86-592-2388138  
Fax: 86-592-2388130

**China - Xian**  
Tel: 86-29-8833-7252  
Fax: 86-29-8833-7256

**China - Zhuhai**  
Tel: 86-756-3210040  
Fax: 86-756-3210049

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-4182-8400  
Fax: 91-80-4182-8422

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-2566-1512  
Fax: 91-20-2566-1513

**Japan - Yokohama**  
Tel: 81-45-471- 6166  
Fax: 81-45-471-6122

**Korea - Daegu**  
Tel: 82-53-744-4301  
Fax: 82-53-744-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Kuala Lumpur**  
Tel: 60-3-6201-9857  
Fax: 60-3-6201-9859

**Malaysia - Penang**  
Tel: 60-4-227-8870  
Fax: 60-4-227-4068

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-572-9526  
Fax: 886-3-572-6459

**Taiwan - Kaohsiung**  
Tel: 886-7-536-4818  
Fax: 886-7-536-4803

**Taiwan - Taipei**  
Tel: 886-2-2500-6610  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**UK - Wokingham**  
Tel: 44-118-921-5869  
Fax: 44-118-921-5820