Date Created: 2007/05/10 Date Issued On: 2007/06/13

PCN# : **Q2071910**

DESIGN/PROCESS CHANGE NOTIFICATION -- FINAL

This is to inform you that a design and/or process change will be made to the following product(s). This notification is for your information and concurrence.

If you require data or samples to qualify this change, please contact Fairchild Semiconductor within 30 days of receipt of this notification.

Updated process quality documentation, such as FMEAs and Control Plans, are available for viewing upon request.

If you have any questions concerning this change, please contact:

Technical Contact:

Name: LEE, JEONGSOO

E-mail: JEONGSOO.LEE@fairchildsemi.com

Phone: 82-32-680-1311

PCN Originator:

Name: LEE, JEONGSOO

E-mail: JEONGSOO.LEE@fairchildsemi.com

Phone: 82-32-680-1311

Implementation of change:

Expected 1st Device Shipment Date: 2007/06/24

Earliest Year/Work Week of Changed Product: G26

Change Type Description: Lead Frame Composition

Description of Change (From): TO-3PN Package :L/F plating change : from Bare Cu L/F +

With pre-bake process

Description of Change (To): to Ni plated L/F + Without pre-bake process

Reason for Change: To simplify the assembly process and improve the high-temperature

reliability

Qual/REL Plan Numbers: Q20070196

Passed 1000Hrs items

Qualification:

Passed 1000Hrs items

Results/Discussion

| Test: (Autoclave) | | | | |
|---------------------|---------|-------------|-------------|--------------|
| Lot | Device | 96-HOUR | RS | Failure Code |
| Q20070196AAACLV | FDA8440 | 0/77 | | |
| Q20070196ABACLV | FDA8440 | 0/77 | | |
| Q20070196ACACLV | FDA8440 | 0/77 | | |
| Test: (Power Cycle) | | | | |
| Lot | Device | 3000-CYCLES | 6000-CYCLES | Failure Code |
| Q20070196AAPRCL | FDA8440 | 0/77 | | |
| Q20070196AAPRCL | FDA8440 | | 0/77 | |

| Q20070196ABPRCL | FDA8440 | 0/77 | | |
|----------------------|-----------------------|------------|-------------|--------------|
| Q20070196ABPRCL | FDA8440 | | 0/77 | |
| Q20070196ACPRCL | FDA8440 | 0/77 | | |
| Q20070196ACPRCL | FDA8440 | | 0/77 | |
| Test: -55, 150C (Ter | nperature Cycle) | | | |
| Lot | Device | 500-CYCLES | 1000-CYCLES | Failure Code |
| Q20070196AATMCL3 | FDA8440 | 0/77 | | |
| Q20070196AATMCL3 | FDA8440 | | 0/77 | |
| Q20070196ABTMCL3 | FDA8440 | 0/77 | | |
| Q20070196ABTMCL3 | FDA8440 | | 0/77 | |
| Q20070196ACTMCL3 | FDA8440 | 0/77 | | |
| Q20070196ACTMCL3 | FDA8440 | | 0/77 | |
| Test: 130C (Highly A | ccelerated Stress Tes | st) | | |
| Lot | Device | 96-HC | URS | Failure Code |
| Q20070196AAHAST1 | FDA8440 | 0/77 | | |
| Q20070196ABHAST1 | FDA8440 | 0/77 | | |
| Q20070196ACHAST1 | FDA8440 | 0/77 | | |

Product Id Description : There is Power Trench Product, FDA8440.

Affected FSIDs:

| FDA8440 | |
|---------|--|