



**Intel<sup>®</sup> Server Board S5000PAL**  
**Intel<sup>®</sup> Server Board S5000XAL**  
**Intel<sup>®</sup> Server System SR1500AL**  
**Intel<sup>®</sup> Server System SR1550AL**  
**Intel<sup>®</sup> Server System SR2500AL**

*Intel Order Number D65289-017*

**October 2007**

**Enterprise Platforms and Services Marketing**



## Revision History

Date	Modifications
Jun. 2006	Initial release.
Aug. 2006	Updated errata #6, 8, 16, 18, 19, 21, 22, 23, 24, 25, 26, and 27. Erratum #28 has been added
Nov. 2006	Errata #30, 31, 32, 33, 34 have been added; Documentation change 3, 4 have been added.
Feb. 2007	Errata # 35, 36, 37 have been added; Updated Erratum # 25, 33.
Mar. 2007	Errata # 38, 39, 40 have been added.
Apr. 2007	Errata #41 and 42 have been added.
Jun. 2007	Errata # 42, 43, 44, 45, 46, 47, 48, 49 have been added.
Jul. 2007	Updated errata #36 and #42. Erratum # 50 has been added.
Aug. 2007	Updated erratum #47.
Sept. 2007	Errata #51, 52 and 53 have been added.
Oct. 2007	Updated errata # 42; Errata # 54 has been added.

## ***Disclaimers***

The Intel Products Specified may contain design defects or errors known as errata that may cause the products to deviate from the published specifications. Current characterized errata are documented in this Specification Update.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Intel, Itanium, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation.

\*Other brands and names may be claimed as the property of others.

Copyright © Intel Corporation 2007.

# Contents

<b>Preface</b> .....	<b>7</b>
<b>Summary Tables of Changes</b> .....	<b>8</b>
<b>Errata</b> .....	<b>11</b>
1. IPMI over serial direct connect not supported. ....	11
2. Serial over LAN and IPMI over LAN connections may terminate unexpectedly under certain conditions. ....	11
3. Intermittent beep code 1-5-2-1 when booting with two processors. ....	11
4. Power supply population errors may not appear in the SEL.....	12
5. Fan 5 may report a reading of 0 RPM after the BMC is updated.....	12
6. The BMC may not respond to the IPMI command, <i>Send Message</i> sent via LAN. ....	12
7. Fans may take a long time to slow down after fan boosting. ....	13
8. System requires ~35 seconds after AC power applied before the power button responds. ....	13
9. SEL events for HSC may appear after a DC cycle. ....	13
10. Fans may run faster than expected after exiting BIOS setup. ....	14
11. System fault LED may report incorrect status for some events. ....	14
12. Fan removal does not generate a SEL event. ....	14
13. Power supply redundancy state is misleading when only one power supply is installed. ....	15
14. HSC and LCP updates may take a long time. ....	15
15. Console Redirection Baud Rate Setting auto changing to 19.2K with Serial Over LAN (SOL) active.....	15
16. Serial Over LAN (SOL) unable to redirect DOS output.....	16
17. Password on boot not supported.....	16
18. Intel® Embedded Server RAID Technology II option is not enabled in initial BIOS release. ....	16
19. HSC and BMC versions intermittently not seen in BIOS setup.....	17
20. Intel® Server Boards S5000PAL/S5000XAL and Intel® Server System SR1500AL show a “Changes in Hardware or Drivers Detected” error message during WHQL ACPI stress testing. ....	17
21. POST LEDs don’t turn off after operating system loads. ....	17
22. Checkup7.exe (microcode update utility) is not storing microcode in BIOS. ....	18
23. Intel® RAID Controller SRCAS144E causes systems to reset multiple times before completing POST. ....	18

24. Change Logo Utility does not save modified BIOS capsule files with correct extension. 18

25. PS2 keyboards and mice may stop functioning after Red Hat\* Enterprise Linux is installed. 19

26. Failures seen installing to a SATA drive when SATA is set to “Legacy” in BIOS setup. 19

27. System hangs after disabling onboard video in BIOS setup..... 20

28. The SMBIOS entry point may not be visible under certain hardware configurations.20

29. Intel® Embedded Server RAID Technology II and IO module IRQ routing conflict.20

30. SuSE\* Linux Enterprise Server may not install successfully with Intel® Embedded Server RAID Technology II enabled. .... 21

31. Red Hat\* Enterprise Linux 4 and BIOS setup display a different L2 cache size for the Quad-Core Intel® Xeon® processor 5300 Series. .... 21

32. Change Logo Utility causes BIOS corruption. .... 22

33. Microsoft Windows\* System Event Viewer may record ID 11 Error Event. .... 22

34. POST screen may generate "NMI has been received - System Halted" message after the system reboots. .... 22

35. Intel® RAID Web Console 2 utility displays “Unexpected Sensor” warning message in Microsoft Windows\* operating system. .... 23

36. Random drives may go offline when a sixth drive is installed and Intel® Embedded Server RAID Technology II is enabled in the Intel® Server System SR2500ALBRP. .... 23

37. Intel recommends enterprise class hard drives for use with Intel® Server Systems.24

38. Dual Gigabit Expansion Module may not properly reset..... 24

39. SAS drive in a ROMB RAID 5 may drop offline during a reboot in the Intel® Server System SR2500PALLX..... 24

40. Intel® Server System SR2500ALLX 6<sup>th</sup> hard drive filler panel is difficult to remove.25

41. SuSE\* Linux Enterprise Server unable to boot after basic installation ..... 25

42. Drives may not be detected or may go offline in the Intel® Server System SR2500ALBRP when operating at SATA 300 MB/s data rate..... 26

43. New versions of BMC firmware with previous versions of BIOS cause system POST failure. .... 26

44. Intel® Server System SR2500ALLX may operate louder than expected. .... 27

45. Red Hat\* Enterprise Linux may report the wrong processor speed..... 27

46. The SuSE\* Linux Enterprise Server 10 driver for SAS HW RAID causes unwanted error logs during installation. .... 27

47. IERR or thermal trip event reported in System Event Log (SEL) after system power on. 28

48. USB device induces – “The following boot-start or system-start driver(s) failed to load: i8042prt” error message in Windows\* operating systems. .... 28

49. Microsoft\* Windows, RAID Web Console 2 report an error when ASR2500SATAPE kit used..... 28

50. System May Log IERRs When Running Red Hat\* Enterprise Linux 4, Update 4 on S500PAL with Video Driver (ati\_drv.o 6.5.6) ..... 29

51. Microsoft\* Windows\* Operating Systems without Service Pack will exhibit blue screen with BIOS 79 and 81..... 29

52. Sluggish system performance may be experienced with BMC60..... 30

53. Firmware Downgrade of Integrated RAID (ROMB), Embedded Server RAID Technology II (ESRT2) or SAS might cause system break ..... 30

54. In SR2500ALLX, Flashing of SAS Firmware 1.22 and SAS BIOS 06.16.00 Makes Hard Drive #1 (upper left drive tray) Undetected During SAS Controller Scanning..... 31

**Documentation Changes..... 32**

1. The SMBUS block diagram (Figure #16) as provided in Rev 1.1 of the Intel® Server Board S5000PAL/S5000XAL TPS requires changes to accurately reflect production hardware design. 32

2. The power block diagram (Figure #25) as provided in Rev 1.1 of the Intel® Server Board S5000PAL/S5000XAL TPS does not reflect final production level baseboard design.. 33

3. SAS/SAS RAID mid-plane board (Figure #22) as provided in Rev.1.0 of the Intel® Server System SR2500AL TPS should swap the descriptions of items A and K. .... 34

4. Front panel pin-out on the Intel® Server Board S5000PAL Quick Reference Label is incorrect. .... 35

**This page intentionally left blank**

## Preface

---

This document communicates product Errata and Documentation Changes & Corrections for the following Intel Server Products:

- Intel® Server Board S5000PAL
- Intel® Server Board S5000XAL
- Intel® Server Chassis SR1500
- Intel® Server System SR1500AL
- Intel® Server Chassis SR1550
- Intel® Server System SR1550AL
- Intel® Server Chassis SR2500
- Intel® Server System SR2500AL

Refer to the *Dual-Core Intel® Xeon® Processor 5000 Sequence Specification Update* (Order Number 313065) for specification updates concerning the Dual-Core Intel® Xeon® Processor 5000 Series processors. Items contained in the *Dual-Core Intel® Xeon® Processor 5000 Sequence Specification Update* that either do not apply to the products in this document or have been worked around, are noted in this document. Otherwise, it should be assumed that any processor errata for a given stepping are applicable to the Printed Board Assembly (PBA) revisions(s) associated with that stepping.

The following defines items communicated in this document.

**Specification Changes** are modifications to the current published specifications for a given product. These include typos, errors, or omissions. Specified changes will be incorporated in the next release of the document.

**Specification Clarifications** describe a supported feature or function in greater detail or further highlight their impact to a complex design requirement. These clarifications will be incorporated in the next release of the document.

**Errata** are design defects or deviations from current published specifications for a given product. Published errata may or may not be corrected.

- Hardware and software designed to be used with any given processor stepping must assume that all errata documented for that processor stepping are present on all devices.

## Summary Tables of Changes

The following tables provide an overview of known errata and known document changes that apply to the specified Intel Server Products. The tables use the following notations:

**Doc** Intel intends to update the appropriate documentation in a future revision.

**Fix** Intel intends to correct this erratum.

**Fixed** This erratum has been corrected.

**No Fix** There are no plans to correct this erratum.

**Shaded** This item is new or has been modified from the previous specification update.

**Table 1. Errata Summary**

No.	Plans	Description of Errata
1.	Doc	IPMI over serial direct connect not supported.
2.	Fix	Serial over LAN and IPMI over LAN connections may terminate unexpectedly under certain conditions.
3.	Fix	Intermittent beep code 1-5-2-1 when booting with two processors.
4.	Doc	Power supply population errors may not appear in the SEL.
5.	Fix	Fan 5 may report a reading of 0 RPM after the BMC is updated.
6.	Fixed	The BMC may not respond to the IPMI command, <i>Send Message</i> sent via LAN.
7.	Fix	Fans may take a long time to slow down after fan boosting.
8.	Fixed	System requires ~35 seconds after AC power applied before the power button responds.
9.	Fix	SEL events for HSC may appear after a DC cycle.
10.	Fix	Fans may run faster than expected after exiting BIOS setup.
11.	Fix	System fault LED may report incorrect status for some events.
12.	Fix	Fan removal does not generate a SEL event.
13.	Fix	Power supply redundancy state is misleading when only one power supply is installed.
14.	Fix	HSC and LCP updates may take a long time.
15.	Fixed	Console Redirection Baud Rate Setting auto changing to 19.2K with Serial Over LAN (SOL) active.
16.	Fixed	Serial Over LAN (SOL) unable to redirect DOS output.
17.	No Fix	Password on boot not supported.
18.	Fixed	Intel® Embedded Server RAID Technology II option is not enabled in initial BIOS release.
19.	Fixed	HSC and BMC versions intermittently not seen in BIOS setup.
20.	Fixed	Intel® Server Boards S5000PAL/S5000XAL and Intel® Server System SR1500AL show a "Changes in Hardware or Drivers Detected" error message during WHQL ACPI stress testing.
21.	Fixed	POST LEDs don't turn off after operating system loads.
22.	Fixed	Checkup7.exe (microcode update utility) is not storing microcode in BIOS.
23.	Fixed	Intel® RAID Controller SRCAS144E causes systems to reset multiple times before completing POST.

24.	Fixed	Change Logo Utility does not save modified BIOS capsule files with correct extension.
25.	Fixed	PS2 keyboards and mice may stop functioning after Red Hat* Enterprise Linux is installed.
26.	Fixed	Failures seen installing to a SATA drive when SATA is set to "Legacy" in BIOS setup.
27.	Fixed	System hangs after disabling onboard video in BIOS setup.
28.	Fixed	The SMBIOS entry point may not be visible under certain hardware configurations.
29.	Fixed	Intel® Embedded Server RAID Technology II and IO module IRQ routing conflict.
30.	No Fix	SuSE* Linux Enterprise Server may not install successfully with Intel® Embedded Server RAID Technology II enabled.
31.	No Fix	Red Hat* Enterprise Linux 4 and BIOS setup display a different L2 cache size for the Quad-Core Intel® Xeon® processor 5300 Series.
32.	Fixed	Change Logo Utility causes BIOS corruption.
33.	Fixed	Microsoft Windows* System Event Viewer may record ID 11 Error Event.
34.	Fixed	POST screen may generate "NMI has been received - System Halted" message after the system reboots.
35.	Fix	Intel® RAID Web Console 2 utility displays "Unexpected Sensor" warning message in Microsoft Windows* operating system.
36.	Fixed	Random drives may go offline when a sixth drive is installed and Intel® Embedded Server RAID Technology II is enabled in the Intel® Server System SR2500ALBRP.
37.	No Fix	Intel recommends enterprise class hard drives for use with Intel® Server Systems.
38.	Fix	Dual Gigabit Expansion Module may not properly reset.
39.	Fixed	SAS drive in a ROMB RAID 5 may drop offline during a reboot in the Intel® Server System SR2500PALLX.
40.	Fix	Intel® Server System SR2500ALLX 6 <sup>th</sup> hard drive filler panel is difficult to remove.
41.	No fix	SUSE* Linux Enterprise Server unable to boot after basic installation
42.	Fix	Drives may not be detected or may go offline in the Intel® Server System SR2500ALBRP when operating at SATA 300 MB/s data rate.
43.	No Fix	New versions of BMC firmware with previous versions of BIOS cause system POST failure.
44.	Fixed	Intel® Server System SR2500ALLX may operate louder than expected.
45.	No Fix	Red Hat* Enterprise Linux may report the wrong processor speed.
46.	Fix	The SuSE* Linux Enterprise Server 10 driver for SAS HW RAID causes unwanted error logs during installation.
47.	Fix	IERR or thermal trip event reported in System Event Log (SEL) after system power on.
48.	No Fix	USB device induces – "The following boot-start or system-start driver(s) failed to load: i8042prt" error message in Windows* operating systems.
49.	No Fix	Microsoft* Windows, RAID Web Console 2 report an error when ASR2500SATAPE kit used.
50.	No Fix	System May Log IERRs When Running Red Hat* Enterprise Linux 4, Update 4 on S500PAL with Video Driver (ati_drv.o 6.5.6)
51.	Fix	Microsoft* Windows* Operating Systems without Service Pack will exhibit blue screen with BIOS 79 and 81.
52.	Fix	Sluggish system performance may be experienced with BMC60.
53.	No Fix	Firmware Downgrade of Integrated RAID (ROMB), Embedded Server RAID Technology II (ESRT2) or SAS might cause system break
54.	Fix	In SR2500ALLX or SR1550ALSAS, Flashing of SAS Firmware 1.22 and SAS BIOS 06.16.00 Makes Hard Drive #1 (upper left drive tray) Undetected During SAS Controller Scanning.

Table 2. Documentation Changes

No.	Plans	Document Name	Description of Documentation Change
1.	Fixed	Intel® Server Board S5000PAL/S5000XAL Technical Product Specification rev. 1.1	The SMBUS block diagram (Figure #16) as provided in Rev 1.1 of the Intel® Server Board S5000PAL/S5000XAL TPS requires changes to accurately reflect production hardware design.
2.	Fixed	Intel® Server Board S5000PAL/S5000XAL Technical Product Specification rev. 1.1	The power block diagram (Figure #25) as provided in Rev 1.1 of the Intel® Server Board S5000PAL/S5000XAL TPS does not reflect final production level baseboard design.
3.	Fix	Intel® Server System SR2500AL Technical Product Specification rev. 1.0	SAS/SAS RAID mid-plane board (Figure #22) as provided in Rev.1.0 of the Intel® Server System SR2500AL TPS should swap the descriptions of items A and K.
4.	Fix	Intel® Server Board S5000PAL Quick Reference Label	The front panel pin-out on the Intel® Server Board S5000PAL Quick Reference Label is incorrect.

The following sections provide in-depth descriptions of each erratum / documentation change indicated in the tables above. The errata and documentation change numbers referenced in the following sections correspond to the numbers in the tables above.

## Errata

---

### 1. IPMI over serial direct connect not supported.

Problem	Dual-Core Intel® Xeon® processor 5000 sequence - based server boards list support for IPMI access via serial direct connect. Serial access to the BMC is not supported at this time.
Implication	Users should use the IPMI over LAN interface to connect to the BMC. Note: this only affects serial and terminal mode access to the BMC; this does not affect BIOS console redirection via serial, and OS redirection via serial.
Status	This erratum may be fixed in a future firmware revision and hardware revision.
Workaround	None.

### 2. Serial over LAN and IPMI over LAN connections may terminate unexpectedly under certain conditions.

Problem	During an active serial over LAN connection, or during an active IPMI over LAN connection to the BMC, intermittently the connection may be lost during a DC cycle or reset.
Implication	The user's connection may be lost and the user will have to reconnect the session.
Status	This erratum may be fixed in a future firmware revision.
Workaround	None.

### 3. Intermittent beep code 1-5-2-1 when booting with two processors.

Problem	During POST, the system may pause at POST code 0x13 (SMM Initialization) if two processors are installed. This may result in a 1-5-2-1 beep code and a processor event in the System Event Log (SEL).
Implication	The system may log erroneous errors in the SEL or via beep code, and under some conditions the system may halt at 0x13 and require an AC cycle.
Status	This erratum is fixed in BMC release 47 and later releases.
Workaround	If an error is encountered, AC cycle the system and the system should run normally.

#### 4. Power supply population errors may not appear in the SEL.

Problem	The BMC will not give any indication if a single power supply is improperly installed in a redundant chassis.
Implication	Some chassis require power supplies to be installed in specific slots if a single power supply is installed.
Status	This erratum may be fixed in a future firmware revision.
Workaround	None.

#### 5. Fan 5 may report a reading of 0 RPM after the BMC is updated.

Problem	After a BMC update, fan 5 may not return an accurate reading until AC power is cycled.
Implication	Intel® System Management Software and other software may display a reading of 0 RPM for this sensor. The BMC may respond as though this fan has failed and fan redundancy is lost. This will cause the system fault LED and fan status LED to indicate a failure for this sensor, and the fans will run in a high speed 'boost' state.
Status	This erratum may be fixed in a future firmware revision.
Workaround	AC cycle the system again and the system should run normally.

#### 6. The BMC may not respond to the IPMI command, *Send Message sent via LAN*.

Problem	The BMC may not respond correctly to a <i>Send Message</i> command from the LAN channel to the IPMB channel. This issue only affects an IPMI 2.0 based RMCP+ session, not an IPMI 1.5 based RMCP session.
Implication	Remote IPMI over LAN software cannot forward commands to the IPMB bus.
Status	This erratum is fixed in BMC release 50 and later releases.
Workaround	Software developers should use IPMI 1.5 based sessions to bridge commands to the IPMB channel.

## 7. Fans may take a long time to slow down after fan boosting.

Problem	System fans that 'boost' due to an increased processor temperature may not return to normal speed immediately after the processor temperature returns to normal.
Implication	If the system fans 'boost' due to a high processor temperature, the BMC will not restore the fans to a normal speed until a similar amount of time that they spent in a 'boosted' state passes. For example, if a high processor temperature caused the fans to boost for five minutes, the fans would not return to normal until five minutes after the processor temperature returned to normal.
Status	This erratum may be fixed in a future firmware revision.
Workaround	The fans will return to normal speed over time.

## 8. System requires ~35 seconds after AC power applied before the power button responds.

Problem	The BMC requires approximately 35 seconds to fully initialize the system after an AC cycle before the system can be powered on.
Implication	After an AC cycle, a user will have to wait ~35 seconds before the power button will respond. The BMC will cause the front panel LED to blink in an alternating amber/green pattern while the BMC initialization is in progress. Users should wait until the LED stops blinking in this pattern before pressing the power button.
Status	This erratum is fixed in BMC release 50 and later releases.
Workaround	None.

## 9. SEL events for HSC may appear after a DC cycle.

Problem	The HSC may log critical and non-critical temperature events in the SEL after a DC cycle.
Implication	The SEL events are 'deassertion' events, which are not an indication of a problem with the system. Users can ignore these events as they are not errors or an indication of a problem in the system.
Status	This erratum will be fixed in a future HSC firmware revision.
Workaround	None.

**10. Fans may run faster than expected after exiting BIOS setup.**

Problem	Some system fans may run faster after exiting BIOS setup using the 'save and exit' option.
Implication	The system may generate more fan noise than normal.
Status	This erratum may be fixed in a future firmware revision.
Workaround	The system must be AC cycled, or allowed to boot to the OS and then reset, to restore fans to their normal speeds.

**11. System fault LED may report incorrect status for some events.**

Problem	The system fault LED may report incorrect status for some events. The proper LED state is described in the server board TPS, but some events may not reflect the states described in the TPS.
Implication	The user may receive an incorrect indication via the system fault LED. The user should verify the system state by looking at the SEL. No event is reported with a less severe status than expected, but events may appear with a higher severity status.
Status	This erratum will be fixed in a future firmware version.
Workaround	None.

**12. Fan removal does not generate a SEL event.**

Problem	Fan removal does not trigger a fan failure event.
Implication	Simulating a fan failure by fan removal will not work.
Status	This erratum may be fixed in a future firmware revision.
Workaround	None.

### **13. Power supply redundancy state is misleading when only one power supply is installed.**

Problem	If a single power supply is installed in a chassis that supports redundant power supplies, the BMC will indicate the power supply redundancy state as 'redundant'.
Implication	In a single power supply configuration, the redundancy sensor should be ignored. Redundant chassis with fully redundant power supplies will accurately reflect the redundancy status.
Status	This erratum may be fixed in a future firmware revision.
Workaround	None.

### **14. HSC and LCP updates may take a long time.**

Problem	The Hot Swap Controller (HSC) and Local Control Panel (LCP) updates may take a long time. The time to complete each update may exceed 30 minutes.
Implication	Updating HSC and LCP may take a long time.
Status	This erratum may be fixed in a future firmware revision.
Workaround	None.

### **15. Console Redirection Baud Rate Setting auto changing to 19.2K with Serial Over LAN (SOL) active.**

Problem	If configuring a SOL connection, the only baud rate allowed is 19.2K. If any other baud rate is chosen the system will always revert back to 19.2K after the DC cycle.
Implication	Users who require a different baud rate for their application will not be able to configure this.
Status	This erratum is fixed in BIOS release R0045 and later releases.
Workaround	None.

**16. Serial Over LAN (SOL) unable to redirect DOS output.**

Problem	No SOL output is seen when booted to DOS. SOL will only redirect F2 Setup and POST output.
Implication	Users who require SOL to redirect DOS output will not be able to use this feature.
Status	This erratum is fixed in BIOS release R0054 and later releases.
Workaround	None.

**17. Password on boot not supported.**

Problem	If an 'admin' or 'user' password is set in BIOS setup, this will be required before the user can enter into BIOS Setup. There is no option to configure a password during POST before the server will boot.
Implication	Users will not be able to create and require a password on boot.
Status	Intel does not intend to fix this erratum.
Workaround	None.

**18. Intel® Embedded Server RAID Technology II option is not enabled in initial BIOS release.**

Problem	The Intel® Embedded Server RAID Technology II feature that has been available in pre-production BIOS releases will not be available in the initial production BIOS release. The option ROM that allows configuration of the Intel® Embedded Server RAID Technology II was deemed not ready for production by Intel at this time.
Implication	Users who require or were planning to use this feature in their production environments will need to wait for a post-launch BIOS release which will have this feature enabled.
Status	This erratum is fixed in BIOS release R0057 and later releases.
Workaround	Several hardware RAID options are readily available and supported by Intel® Server Boards. Consult the product Tested Hardware and Operating System list for a variety of hardware options. No workarounds for the Intel® Embedded Server RAID Technology II are available.

## 19. HSC and BMC versions intermittently not seen in BIOS setup.

Problem	BMC and HSC revision information is intermittently missing from BIOS setup.
Implication	HSC and BMC information is not easily found.
Status	This erratum is fixed in BIOS release R0057 and later releases.
Workaround	<p>Users will need to use the DOS utility, 'fwpiaupd.exe' to probe and get the backplane HSC information. Boot to DOS and using the fwpiaupd.exe utility which is used to flash the BMC and HSC code onto the server system, enter the following command: "<i>fwpiaupd -i -address={c0, c2}</i>" where c0= primary backplane address and c2= secondary backplane address. This will provide you with the operational code revision for the HSC on each backplane.</p> <p>To retrieve the BMC version information, use the same 'fwpiaupdt.exe' utility with the following command: "<i>fwpiaupdt -i -address=20</i>".</p>

## 20. Intel® Server Boards S5000PAL/S5000XAL and Intel® Server System SR1500AL show a "Changes in Hardware or Drivers Detected" error message during WHQL ACPI stress testing.

Problem	While running HCT 12.1 ACPI stress device I/O or any HCT test that needs to reboot, the system will show the following error message: "Changes in Hardware or Drivers Detected".
Implication	This message may prevent users from receiving Microsoft WHQL certification.
Status	This erratum is fixed in BIOS release R0045 and later releases.
Workaround	If system is shut down and restarted, rather than rebooted, between tests, the error does not appear.

## 21. POST LEDs don't turn off after operating system loads.

Problem	The POST Code LEDs at the rear of the system do not turn off once POST completes and the operating system loads. The POST code LEDs will show [Green Red Green Red] at the rear of the system.
Implication	User may believe that since there are LEDs lit on the baseboard that an error has occurred.
Status	This erratum is fixed in BIOS release R0057 and later releases.
Workaround	None.

## 22. Checkup7.exe (microcode update utility) is not storing microcode in BIOS.

Problem	The Checkup7.exe utility which is used to update the processor microcode in BIOS is not working properly. The utility says it completes the flash update successfully, however upon the next reboot the microcode is not actually present in the BIOS.
Implication	Users will not be able to update their BIOS with a new processor microcode.
Status	This erratum is fixed in BIOS release R0057 and later releases.
Workaround	Users will need to update to the latest BIOS revision which will include the latest processor microcode releases. They will not be able to use this utility to add a microcode patch to the existing BIOS.

## 23. Intel® RAID Controller SRCAS144E causes systems to reset multiple times before completing POST.

Problem	With the Intel® RAID Controller SRCAS144E installed in the system, the system may become caught in a reset loop during POST. The system resets itself 4 to 5 times before completing POST. This is seen early in POST within the first seconds of power on and before video initialization. POST code LEDs show 0x21 "Chipset" Initializing a chipset component.
Implication	POST will take approximately 15-20 seconds longer to complete.
Status	This erratum is fixed in BIOS release R0057 and later releases.
Workaround	Moving the RAID controller into a different slot will sometimes resolve this issue. Populating the card in a slower bus (x4 or x8) seems to make this issue appear less frequently.

## 24. Change Logo Utility does not save modified BIOS capsule files with correct extension.

Problem	When using the Change Logo Utility to modify a BIOS capsule file and replace the Intel Splash Screen logo with a new one, it fails to save the new capsule file with a .cap extension. The file that is produced has an .fd extension. The file is the correct capsule file, but it has the wrong extension.
Implication	Users may be confused and believe the utility is not saving the file in the correct format.
Status	This erratum is fixed in version 4.16 of the utility.

**Workaround** When saving the file, on the "Save As" dialogue box, choose Capsule File (\*.cap) in the 'Save as Type' drop down box. Then in the File Name box, type the name of the file with the .cap extension. It is important that you include the '.cap' extension in the file name; otherwise the Change Logo Utility will save the file with the incorrect extension.

If you forget to include the '.cap' in the file name, but you have chosen 'Capsule File (\*.cap)' in the 'Save as Type' drop down box, you can simply rename the file from an .fd extension to a .cap extension and this will work as well.

## **25. PS2 keyboards and mice may stop functioning after Red Hat\* Enterprise Linux is installed.**

**Problem** After installing Red Hat\* Enterprise Linux on a system with BIOS release R0045, the PS2 keyboard and mouse stop working, however USB keyboards and mice will work fine.

**Implication** Users will be unable to use the Linux operating system if a PS2 keyboard and mouse are installed.

**Status** This erratum is fixed in BIOS release R0054 and later releases.

**Workaround** If the user goes into BIOS setup and disables port 60/64 emulation, PS2 keyboards and mice will continue to work. The user should enable port 60/64 emulation if USB keyboards and mice are used.

## **26. Failures seen installing to a SATA drive when SATA is set to "Legacy" in BIOS setup.**

**Problem** If a user has SATA set to "Legacy" in BIOS setup and tries to install an operating system the installation may fail.

**Implication** Users who require SATA to be configured in legacy mode may not be able to get their operating system to install properly.

**Status** This erratum is fixed in BIOS release R0057 and later releases.

**Workaround** Leave SATA in enhanced mode if possible. There is no workaround for the legacy mode issue.

**27. System hangs after disabling onboard video in BIOS setup.**

Problem	After disabling onboard video in BIOS setup, the system will hang during POST.
Implication	Users will not be able to disable onboard video via BIOS setup.
Status	This erratum is fixed in BIOS release R0057 and later releases.
Workaround	Adding in a video controller will automatically disable the onboard video. It is not necessary to manually disable the video controller via BIOS setup. There is no workaround for configurations which do not include video controller support.

**28. The SMBIOS entry point may not be visible under certain hardware configurations.**

Problem	The server BIOS maintains an area in memory to act as an entry point to locate the SMBIOS area. This entry point includes the anchor string “_SM_”, memory pointers and information about the SMBIOS area as required by the SMBIOS specification. This information is dynamically created by the BIOS during POST and is placed in a required memory range between 000F0000h-000FFFFFh. Hardware configurations which require large amounts of memory at POST (option ROM space or I/O configuration space) could fill up this memory range and the SMBIOS entry point cannot be created correctly.
Implication	This problem manifests as an inability for software to locate the SMBIOS records. This can affect management software, and also some Intel provided update utilities, including: BIOS update utilities and FRUSDR update utilities. An error may also appear in the BIOS error manager. Intel update utilities will generate an error and abort before performing an update.
Status	This erratum is fixed in BIOS release R0060 and later releases.
Workaround	If a specific hardware configuration experiences this issue, remove the add-in PCI and PCIe* cards to reduce the amount of add-in card resource space used. Perform the system update (BIOS, FRUSDR) and replace the add-in cards when updates are completed.

**29. Intel® Embedded Server RAID Technology II and IO module IRQ routing conflict.**

Problem	If the Intel® Embedded Server RAID Technology II is enabled in BIOS while an IO module is installed, the system will hang at the RAID Option ROM on the next reboot due to the RAID device's IRQ not being serviced properly.
---------	---

Implication	The Intel® Embedded Server RAID Technology II option in BIOS cannot be used while an IO module is installed in the system.
Status	This erratum is fixed since BIOS release R0061 and later releases.
Workaround	None.

### 30. SuSE\* Linux Enterprise Server may not install successfully with Intel® Embedded Server RAID Technology II enabled.

Problem	If SuSE* Linux Enterprise Server is being installed with Intel® Embedded Server RAID Technology II enabled, the RAID array may not be detected after the driver has been loaded, which results in an installation failure.
Implication	The AHCI.o module inside the operating system is loaded prior to the third party driver, and therefore may take control of the RAID controller. This will result in an installation failure.
Status	Users cannot load a third party RAID driver and the AHCI driver simultaneously in SuSE* Linux Enterprise Server; doing so may cause installation failures.
Workaround	The “brokenmodule-ahci” command can prevent AHCI from loading during installation. At the very first install screen, press F6 to load a driver. In the text tab, type <code>brokenmodules=ahci</code> ; this will allow the installation to complete successfully.

### 31. Red Hat\* Enterprise Linux 4 and BIOS setup display a different L2 cache size for the Quad-Core Intel® Xeon® processor 5300 Series.

Problem	In Red Hat* Enterprise Linux 4, the Quad-Core Intel® Xeon® processor 5300 Series L2 cache size is displayed as 4MB, while in BIOS setup the cache size is displayed as 8MB.
Implication	In BIOS setup, the system reports the total L2 cache size as 8MB due to the 4MB + 4MB structure of the processor. The Quad-Core Intel® Xeon® processor 5300 Series is similar to a package of two sets, each with a 4MB L2 cache size. In each set, the two cores share the 4MB cache. Red Hat* Enterprise Linux 4 views the processor per logical CPU thread. Each logical thread (each set) has access to only 4MB cache, and Red Hat* Enterprise Linux 4 reports it as such.
Status	The different L2 cache size display is due to the different cache size reporting mechanisms of Red Hat* Enterprise Linux 4 and BIOS setup, and is not an incorrect display by the operating system.
Workaround	None.

**32. Change Logo Utility causes BIOS corruption.**

Problem	Any board flashed with a version of BIOS release R0064 edited with the Change Logo Utility will no longer boot. The board will hang with "Off – Off – Red – Green" shown on the Post Code LEDs at the rear of the board.
Implication	The Change Logo Utility cannot be used with BIOS release R0064.
Status	This erratum is fixed in BIOS release R0066 and later releases.
Workaround	None.

**33. Microsoft Windows\* System Event Viewer may record ID 11 Error Event.**

Problem	In the Microsoft Windows* operating system, the Event Viewer's System log may record an Error Event; the source is lsi_sas and the event ID is 11.
Implication	The problem may occur because the controller is sending an unsupported command to the enclosure management device. This error doesn't affect functionality and the error can be ignored.
Status	This erratum has been fixed in Intel® Embedded Server RAID Technology II firmware and/or drivers later than the following revisions: SAS firmware revision -- v.01.16.00.00; MPT OpROM revision -- v.6.10.00; SAS ESRT2 OpROM v. A.01.10241435I.
Workaround	None.

**34. POST screen may generate "NMI has been received - System Halted" message after the system reboots.**

Problem	POST screen may generate "NMI has been received - System Halted" message after the system reboots.
Implication	Along with this error, sometimes "Bus Uncorrectable Error" might also be recorded to System Event Log (SEL).
Status	This erratum is fixed in BIOS release R0066 and later releases.
Workaround	Reboot the system again.

### 35. Intel® RAID Web Console 2 utility displays “Unexpected Sensor” warning message in Microsoft Windows\* operating system.

Problem	The “unexpected sensor” warning message may be displayed in the Intel® RAID Web Console 2 utility, however there seems to be no functional issues with system.
Implication	This warning message is only seen in Microsoft Windows* operating systems. Previous RAID firmware versions (before v.89) were not able to support any communication to the Storage Enclosure Processor (SEP) on backplanes. The firmware was modified to support SEP devices, but the backplanes used in the Intel® Server Chassis SR1500, Intel® Server Chassis SR1550, and Intel® Server Chassis SR2500 do not respond as expected to the inquiry command, so the error is generated and captured in the log. This is a harmless message and will not cause any problems with the RAID array or the drives.
Status	This warning message may be removed from the Intel® RAID Web Console 2’s error reporting mechanism in a future RAID firmware release.
Workaround	None.

### 36. Random drives may go offline when a sixth drive is installed and Intel® Embedded Server RAID Technology II is enabled in the Intel® Server System SR2500ALBRP.

Problem	When a sixth drive is installed and Intel® Embedded Server RAID Technology II is enabled in the Intel® Server System SR2500ALBRP, random drives may go offline. This may result in boot failure of the Intel® Embedded Server RAID Technology II or the operating system.
Implication	This may result in boot failure of the Intel® Embedded Server RAID Technology II or the operating system.
Status	Fixed. This has been identified as a documentation issue. The sixth drive backplane insert needs to be cabled directly to the baseboard. Use the cabling method documented at: <a href="http://support.intel.com/support/motherboards/server/sb/CS-025698.htm">http://support.intel.com/support/motherboards/server/sb/CS-025698.htm</a>
Workaround	Not Applicable.

### **37. Intel recommends enterprise class hard drives for use with Intel<sup>®</sup> Server Systems.**

Problem	Some desktop class hard disk drives have shown performance loss, and in some cases take the drive off-line when they are running in an enterprise environment.
Implication	Desktop drives often lack workload management to lower thermal stresses and have a lower tolerance for the normal rotational vibration found in a server environment. They are not designed to run twenty four hours a day, seven days a week, and may fail prematurely when installed in a server. To attain best performance and avoid drive failures, Intel recommends using enterprise class hard drives for server applications.
Status	No fix.
Workaround	None.

### **38. Dual Gigabit Expansion Module may not properly reset.**

Problem	In certain conditions it is possible that the Dual Gigabit Expansion Module may not properly reset after a system reset.
Implication	If the expansion module does not properly reset, the module could lose network connectivity and the operating system will not be able to see the Gigabit ports. This has only been seen on the Intel <sup>®</sup> Server System SR1550AL.
Status	Will fix in a future revision of the Dual Gigabit Expansion Module.
Workaround	If the module is not reset it can be forced to reset by removing and replacing AC power to the system.

### **39. SAS drive in a ROMB RAID 5 may drop offline during a reboot in the Intel<sup>®</sup> Server System SR2500PALLX.**

Problem	When 5 or 6 drives are inserted and SAS ROMB RAID 5 is configured, drives may drop offline during a system reboot in the Intel <sup>®</sup> Server System SR2500PALLX.
Implication	This only happens with specific drives. After the drive's firmware has been updated to the latest version, the issue should disappear.
Status	Fixed by updating SAS drive firmware.
Workaround	None.

#### 40. Intel® Server System SR2500ALLX 6<sup>th</sup> hard drive filler panel is difficult to remove.

Problem	It may be difficult to remove the Intel® Server System SR2500ALLX 6 <sup>th</sup> hard drive filler panel.
Implication	Certain systems may exhibit this issue. Root cause has been found with the manufacturing tooling. Modification of the tooling will be implemented to resolve this issue. Prior to the tooling modification, new systems will go through screening and/or rework as necessary to correct this issue.
Status	Will be fixed by a future change to the system tooling.
Workaround	None.

#### 41. SuSE\* Linux Enterprise Server unable to boot after basic installation

Problem	<p>During SuSE* Linux Enterprise Server installation, if a USB floppy drive is used to load the mass storage driver, SuSE* Linux Enterprise Server may not be able to boot after basic installation.</p> <p>The following message may appear:</p> <pre>resume device /dev/sdb1 not found (ignoring)  waiting for device /dev/sdb2 to appear.....not found -- exiting to /bin/sh  \$</pre>
Implication	During installation, the USB floppy device is recognized as sda, and the mass storage is recognized as sdb. After reboot, the mass storage is now recognized as sda, but SuSE* Linux Enterprise Server still tries to load system files from sdb. To resolve this issue, the grub menu list file and the fstab file need to be modified.
Status	No Fix.
Workaround	<a href="http://support.intel.com/support/motherboards/server/sb/CS-025446.htm">http://support.intel.com/support/motherboards/server/sb/CS-025446.htm</a> describes this issue and its workaround.

#### **42. Drives may not be detected or may go offline in the Intel® Server System SR2500ALBRP when operating at SATA 300 MB/s data rate.**

Problem	In the Intel® Server System SR2500ALBRP with a passive mid-plane, hard drives may not maintain stable operation at 300 MB/s data rate. The problem is known to exist when using the onboard ESB2 controller with any 300 MB/s capable drive. The active mid plane is not affected.
Implication	The drives may not be detected during boot or may go offline during an operating system installation or stress load.
Status	The erratum will be fixed with new revision of the passive mid-plane that will improve SATA signal margins. The new revision of the passive mid-plane will become available in Q1'2008 timeframe.
Workaround	<p>Force hard drives to operate at 150 MB/s data rate. The SATA data rate change does not have a significant impact on hard drive performance as the data rate of 150 MB/s is still substantially higher than sustained drive media throughput (~50-100 MB/s depending on drive model). The active mid plane is not affected.</p> <p>On most drives, the SATA data rate can be forced to 150 MB/s by installing a jumper on the drive. If jumpering the HDD is not an option, contact your HDD supplier for alternate options.</p>

#### **43. New versions of BMC firmware with previous versions of BIOS cause system POST failure.**

Problem	In systems that are updated with new versions of BMC firmware only, there is a high failure rate that they can no longer POST successfully.
Implication	Any BIOS/BMC/FRU update should adhere to the "SYSTEM FIRMWARE REQUIREMENTS" in the release notes, where the minimum required versions have been listed. If the release notes recommendations are not followed, there may be unexpected errors.
Status	If the system is going to be updated by system firmware, always follow SFUP (System Firmware Update Package) to update the BIOS and BMC together. Always update the FRU after the hardware configuration has changed (including changing the power supply, processor, and system fans).
Workaround	No.

#### **44. Intel® Server System SR2500ALLX may operate louder than expected.**

Problem	The Intel® Server System SR2500ALLX may operate louder than expected.
Implication	The abnormal noise is caused by unbalanced system fans #5 and #6 – the two 60mm system fans. Using a FRUSDR which is older than v41 also contributes to the faster fan speed and noise.
Status	FRUSDR v41 and later set the maximum fan speed to be 75% of original maximum value. This change lowers the fan noise, and does not break the thermal condition design specification.
Workaround	None.

#### **45. Red Hat\* Enterprise Linux may report the wrong processor speed.**

Problem	In Red Hat* Enterprise Linux, the operating system may report the wrong processor speed. Example: processor is 3.0GHz, the operating system shows it as 3300MHz.
Implication	This symptom is operating system related. Although it doesn't reflect the processor speed correctly, this is only a report; it is harmless to the system, and it can be ignored.
Status	Ignore the processor speed in Red Hat* Enterprise Linux.
Workaround	None.

#### **46. The SuSE\* Linux Enterprise Server 10 driver for SAS HW RAID causes unwanted error logs during installation.**

Problem	The SuSE* Linux Enterprise Server 10 driver for SAS HW RAID causes unwanted error logs during installation.
Implication	The error logs are repeatedly displayed on screen if Alt+F4 is pressed during installation. They can also be displayed by typing the dmesg command after the operating system has been installed successfully. These are harmless errors and it can be ignored.
Status	The driver version equal to, or later than 00.00.03.09 will remove these error logs during installation.
Workaround	None.

#### **47. IERR or thermal trip event reported in System Event Log (SEL) after system power on.**

Problem	An IERR or thermal trip event may be reported in the System Event Log (SEL) after the system is powered on. The system status LED on front panel will also go amber, but the system seems to run normally.
Implication	This is due to internal communication error induced by the chip GTL2007 on the motherboard. GTL2007 has an interaction issue with the BMC, and startup times with processor at power on can cause false CPU IERRs; the false error can be ignored.
Status	A hardware change to GTL2107 will be implemented on future board revisions to fix this issue. See PCN107725-01 for additional details.
Workaround	Processor Retest can make system status LED go back to a normal state.

#### **48. USB device induces – “The following boot-start or system-start driver(s) failed to load: i8042prt” error message in Windows\* operating systems.**

Problem	With only a USB keyboard and mouse, and no PS/2 devices connected, sometimes a popup dialog box may display “At least one service or driver failed during system startup. Use Event Viewer to examine the event log for details”, and the error message “The following boot-start or system-start driver(s) failed to load: i8042prt” may be recorded in Windows* event log.
Implication	This is a harmless warning message, which may happen only if a USB keyboard and mouse are used, and no PS/2 devices are connected.
Status	This is a harmless error message in Windows* operating systems and can be ignored.
Workaround	Use PS/2 keyboard and mouse.

#### **49. Microsoft\* Windows, RAID Web Console 2 report an error when ASR2500SATAPE kit used.**

Problem	In the SR2500 with the ASR2500SATAPE SAS/SATA tape drive mounting kit, once logged in to Microsoft* Windows a pop-up message will appear noting "Controller ID 0 PHY is bad on enclosure". The same message will be seen when viewing the RAID log through RAID Web Console 2. This is a false error, and there is no impact to performance. The error message does not appear when booting off the Intel Deployment Assistant CD and running the RAID Console from there.
Implication	Users will need to acknowledge this pop-up window after logging on.

Status	No Fix.
Workaround	Powering the tape drive via an external source, rather than the ASR2500SATAPE kit, will prevent the message from appearing.

## 50. System May Log IERRs When Running Red Hat\* Enterprise Linux 4, Update 4 on S500PAL with Video Driver (ati\_drv.o 6.5.6)

Problem	When running Red Hat Enterprise Linux 4.0, Update 4 on the S5000PAL with video driver (ati_drv.o 6.5.6), an IERR event may be reported in the System Event Log (SEL). Keyboard and mouse may also not respond until an AC cycle is applied to reboot the system.
Implication	Stressing the video controller on the S5000PAL running RHEL3U8, RHEL4U4 and RHEL4U5 can induce timeout errors caused by the default video driver (ati_drv.o 6.5.6). This error triggers IERRs, and then causes the system to not respond. Register dumps can be obtained if the system is instrumented for NMI.
Status	This erratum is fixed in Red Hat* Enterprise Linux 5 and later releases.
Workaround	Users can load the VESA video driver rather than the ati_drv.o 6.5.6 video driver to prevent IERRs and system not responding.

## 51. Microsoft\* Windows\* Operating Systems without Service Pack will exhibit blue screen with BIOS 79 and 81.

Problem	If a user attempts to install Microsoft Windows without an integrated service pack, it will blue screen during the installation process if BIOS 79 or BIOS 81 is on the Intel Server Board. Conversely, if a user upgrades the system BIOS to BIOS 79 or 81 <i>prior</i> to installing the appropriate service pack, the system will blue screen. Starting in BIOS 79, support for enhanced sleep states was added. This addition to the BIOS requires that the Microsoft Service Pack be integrated into the operating system installation process to understand the extended sleep state support.
---------	---

The following is a list of Microsoft Operating Systems and required service packs:

- Windows 2003 32-bit and 64-bit requires Service Pack 1
- Windows 2003 SBS requires Service Pack 1
- Windows XP 32-bit and 64-bit requires Service Pack 2

Implication	Users cannot install Microsoft Windows or upgrade the system BIOS to BIOS 79 or BIOS 81 without a service pack integrated into the installation process.
-------------	--

Status	This erratum may be fixed in a future firmware revision.
Workaround	Users need to remain on BIOS 76, use a Windows installation process that includes the service pack integrated into the installation, or install Windows and service pack prior to updating to BIOS 79 or 81. Additionally, the R2 release versions of Windows do not exhibit this issue. Use of this version of Windows, if possible, is also another valid workaround.

## **52. Sluggish system performance may be experienced with BMC60**

Problem	An issue with BMC 60 is causing incorrect interpretation of the user selected BIOS Setup Open Loop Thermal Throttling (OLTT) options. Advanced BIOS Setup contains OLTT selections for Performance Mode and Acoustic mode. BMC 60 is recognizing a Performance Mode selection in BIOS setup as Acoustic mode request. Acoustic mode selection in BIOS setup is being disregarded and fail safe defaults for Fan Profiles are enforced. This misinterpretation can manifest the BIOS/BMC interaction causing a throttling condition slowing down the system performance significantly.
Implication	Systems set to Performance mode are incorrectly being configured in Acoustics mode which could make the system more susceptible to overheating, especially in 1U chassis or performance degradation due to memory throttling rather than fan boosts being used to cool the memory. Systems being configured to Acoustics mode in the BIOS are actually being set up in fail safe state.
Status	This erratum will be fixed in a future firmware revision.
Workaround	None.

## **53. Firmware Downgrade of Integrated RAID (ROMB), Embedded Server RAID Technology II (ESRT2) or SAS might cause system break**

Problem	Downgrading firmwares of Integrated RAID (ROMB), Embedded Server RAID Technology II (ESRT2) or SAS from original version to older versions might cause unexpected issues, like controller broken, controller invisible during system POST. The failure could be a permanent damage that cannot be recovered.
Implication	Any downgrade actions of firmware could result in system broken and we do not officially support firmware downgrade for any of above situations.
Status	No Fix. This is not an issue. Do not downgrade firmwares in Integrated RAID (ROMB), Embedded Server RAID Technology II (ESRT2) or SAS.
Workaround	None.

**54. In SR2500ALLX or SR1550ALSAS, Flashing of SAS Firmware 1.22 and SAS BIOS 06.16.00 Makes Hard Drive #1 (upper left drive tray) Undetected During SAS Controller Scanning.**

Problem	In SR2500ALLX or SR1550ALSAS, flashing of SAS Firmware 1.22 and SAS BIOS 06.16.00 makes Hard Drive #1 Undetected During SAS Controller Scanning..
Implication	In either SAS Only Mode or SAS Software RAID, hard drive #1 might be undetected.
Status	Will be fixed in a future SAS Firmware and SAS BIOS release.
Workaround	Choose update package of SAS Firmware 1.20 and SAS BIOS 06.14.00. Enter EFI interface, go to the firmware directory and run almp_upd.nsh to flash it.


# Documentation Changes

## 1. The SMBUS block diagram (Figure #16) as provided in Rev 1.1 of the Intel® Server Board S5000PAL/S5000XAL TPS requires changes to accurately reflect production hardware design.

Problem: The current diagram doesn't reflect the following board design changes made to the final production level baseboard.

- o Add PECl controller
- o Remove separate HSC connector
- o Correct Midplane -> FP Smbus connections and 1-wire temp sensor
- o Correct Smbus and 1-wire temp sensor connections to FP connector.
- o Correct FBDIMM labeling

The correct diagram is shown below.



Implication: Inaccurate understanding of actual baseboard design with respect to specified diagram.

Work Around: None.

Status: Corrections incorporated into version 1.2 of the Intel® Server Board S5000PAL Technical Product Specification.



**3. SAS/SAS RAID mid-plane board (Figure #22) as provided in Rev.1.0 of the Intel® Server System SR2500AL TPS should swap the descriptions of items A and K.**

Problem: The current diagram has the descriptions of item A and K swapped:


- Item A should be the battery connector; it is incorrectly described as the RAID activation key connector.
- Item K should be the RAID activation key connector; it is incorrectly described as the battery connector.

The corrected diagram is shown below.

**System Board Interconnects**

Intel® Server System SR2500AL

The chassis also supports an active SAS / SAS RAID mid-plane. This system board incorporates an LSI\* LSISAS1068 SAS controller onto the board. See Chapter 5 for details describing SAS / SAS RAID support. The following diagram shows the location for each connector found on this board.



**Figure 22. SAS/SAS RAID Mid-plane Board**

A	Battery	G	Fan 4 Connector
B	Power Connector	H	Fan 3 Connector
C	Mini-DIMM Connector	I	Fan 1 Connector
D	Fan 6 Connector	J	Fan 2 Connector
E	Fan 5 Connector	K	RAID Activation Key
F	Bridge Board Connector	L	Backplane Connector


Implication: This is a typo.

Work Around: None.

Status: Corrections will be incorporated into next version of the Intel® Server System SR2500AL Technical Product Specification.

**4. Front panel pin-out on the Intel® Server Board S5000PAL Quick Reference Label is incorrect.**

Problem: The current diagram incorrectly lists a 'cooling status' pin, does not have the temperature sensor listed, and shows incorrect locations for the ID LED. The corrected diagram is shown below.



Implication: This is a typo.

Work Around: None.

Status: Corrections will be incorporated into the next version of the label.