



SMA* Hermetically-Sealed Panel Feedthrough Jack Receptacles

Instruction Sheet 408-4847

08 OCT 02 Rev A




Figure 1

1. INTRODUCTION

SMA Hermetically-Sealed Panel Feedthrough Jack Receptacles 1053159-1, 1053181-1, 1053182-1, 1053226-1, 1053227-1, 1053254-1, 1061372-1, and 1089139-1 are designed to be mounted onto a panel using the following tools:

TOOL DESCRIPTION	PART NUMBER CROSS-REFERENCE	
	TYCO ELECTRONICS	M/A-COM
Step Reamer	1055284–1	2098-0442-54
.250-36, UNS-2B Bottoming Tap	_	2098–5618–54
Torque Tool	1055251–1	2098-0248-54
³ / ₈ –in. Open Wrench■	_	_

■ Commercially available



Unless otherwise specified, dimensions in this instruction sheet are in metric units (with U.S. customary units in brackets].

Reasons for reissue of this instruction sheet are provided in Section 5, REVISION SUMMARY.

2. DESCRIPTION

The jack receptacle consists of a jack and metal gasket. See Figure 1.

3. ASSEMBLY PROCEDURE



Follow safety precautions included with the tools used for assembly.

- 1. Refer to Figure 2, and drill a hole in the panel to the diameter shown. Using the step reamer, ream the hole to the depth shown. Using the bottoming tap, tap the thread to the depth shown.
- 2. While holding the collet of the torque tool, turn the handle *clockwise* until it stops. Thread the jack into the tool until it bottoms inside the tool. Hand-tighten the jack. Refer to Figure 3.

NOTE

The torque tool is preset between 2.60 and 3.05 Nm [23 and 27 in.-lb].

Recommended Panel Cutout

Note: Dimensions are in inches over millimeters.





Figure 2






Figure 3

Collet (Ref)

3. Install the metal gasket onto the jack. See Figure 4.




Figure 4



- 4. Thread the jack into the connector housing by turning the handle of the torque tool *clockwise* until the handle releases. See Figure 5, Detail A.
- 5. While holding the collet of the torque tool with the open wrench, turn the handle *counter clockwise*, and remove the jack assembly from the torque tool. See Figure 5, Detail B.
- 6. Install the jack assembly onto the panel.

Connector Handle of Torque Tool Collet (Ref) Turn Handle Clockwise




Figure 5

4. REPLACEMENT AND REPAIR

Discard and replace any defective or damaged jack receptacles or metal gaskets.

5. REVISION SUMMARY

Revisions to this instruction sheet per EC 0990–1532–02 include:

- Updated document to corporate requirements
- Removed obsolete jack receptacles
- Added Section 4

2 of 2 Rev **A**