

Ten, Eight and Six Channel HD Audio Codecs

Overview

The current errata and updates for the revision B2 are described below. These items were gathered through **evaluation**, if additional items are identified, notice will be given. Device reliability, life span, and suitability for intended use are not affected. Product covered by this errata carry standard guarantee and warranties.

Product Summary

Product can be identified in several ways. The main part number is located below the IDT Name on the physical chip top marking. The revision code is the first two digits of the fourth line of marking. Products can be identified specifically through the software accessible registers as indicated in the table below. It is recommended that software programmers incorporate identification and adjustment code for the device revisions when updating drivers.

Revision Code Marking	92HD73E 92HDW74E	92HD73D 92HDW74D	92HD73C 92HDW74C1 92HDW74C2
Vendor ID (Parameter 00h (MSB))	111Dh	111Dh	111Dh
Device ID (Parameter 00h (LSB))	7676h	7674h	7675h
Revision ID(Parameter 02h (LSB))	0202h		
Issue Date	April 2008		
Production Status	Production		

Table1. Product Identification

Errata

Errata Item	Issue Description	Workaround	Status
DMIC out of band noise	Noise may be heard when running digital microphone at or below the standard clock rate (2.58MHz) with the total record gain + boost > ~20dB.	Option 1. Run digital microphones using the 3.528MHz clock rate (may require a waiver from certain DMIC vendors whose parts are rated with a max clock value below 3.528MHz). This option is implemented with a simple BIOS widget write and does not require any hardware or driver changes. Option 2. Disable the hardware gain inside the driver and implement the boost/gain in SW. This option will require a driver spin, and it will limit the total mic gain to 30dB. Additionally, this option is not available when using the MS Class Driver (which will expose the hardware gain).	May be addressed in a future silicon revision. Contact IDT sales
DAC-MIXER-ADC Path 3.3V	May experience clipping and/or distortion at -1dB signal levels.	These devices are not offered with a productized 3.3V Analog option. If customer chooses to run the device as 3.3V, please note that material will not be ATE tested at that level and this errata may apply.	This will not be addressed.

Table 2. Errata

Dynamic Range: Headphone ports with 10k loading have a recommended external filter of 50hms/22nF. With the new WLP requirements, using an external 27nF capacitor or other value is acceptable. Please note that you may have to be "tune" the system for optimal DR behavior by changing this external capacitor during DTM certification. It has no actual effect on audio performance and is only done to compensate for the AP test equipment.

Please note there are no additional known issues or errata items at this time.

Innovate with IDT and accelerate your future networks. Contact:

www.IDT.com

For Sales

800-345-7015
408-284-8200
Fax: 408-284-2775

Corporate Headquarters

Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138
United States
800 345 7015
+408 284 8200 (outside U.S.)

Asia Pacific and Japan

Integrated Device Technology
Singapore (1997) Pte. Ltd.
Reg. No. 199707558G
435 Orchard Road
#20-03 Wisma Atria
Singapore 238877
+65 6 887 5505

Europe

IDT Europe, Limited
321 Kingston Road
Leatherhead, Surrey
KT22 7TU
England
+44 1372 363 339

