

## Active Errata List

- DMA Access Request During Processor LOCK Accesses
- BUSRDY\* and Waitstates on Exchange Memory Area
- Floating-point Compare Instruction Followed by OR Instruction

## Errata History

Product Release	Errata List
All lot numbers	1, 2, 3

## Errata Description

### 1. DMA Access Request During Processor LOCK Accesses

The error case appears when the DMAREQ\* assertion by the DMA unit and the LOCK assertion by the processor occur in the same clock cycle. In this case, if no DMA transfer is performed during the DMA session, the processor only retrieves control on the bus after the DMA time-out has expired. The DMA time-out can be disabled by software. If DMA time-out is disabled and the error case is present, the processor will never retrieve the bus. A reset would be the only way to restart processor in normal activity.

When the error case condition is fulfilled, on the same clock rising edge, DMAGNT\* assertion by the processor and internal LOCK sampling by the memory controller are executed. A DMA session is started and at the same time, the LOCK signal is decoded by the MEC. The memory controller generates an internal signal that makes the IU enter a 'hold' mode. The IU remains in 'hold' mode until internal signals are updated through DMAAS assertion or DMA time-out. The external LOCK pin is a direct representation of the IU signal whereas internal LOCK is only effective in the following rising edge of the clock.

#### Workarounds

Software workaround:

No inactive DMA cycle is performed. At least one DMAAS per DMA cycle.

Hardware workaround:

The DMA unit must decode the LOCK signal so that no DMA request is sent to the processor while a locked cycle is in progress. Insertion of a one-clock-cycle delay on assertion of DMAREQ\* when LOCK is active is one way to avoid the above processor behavior.

### 2. BUSRDY\* and Waitstates on Exchange Memory Area

The error appears during exchange memory accesses that use both programmed waitstates and BUSRDY\*.

An exchange memory access is only terminated if on the rising edge of SYSCLK that separates the 'waitstate cycle' and the 'end of cycle' the BUSRDY\* signal is low.

If BUSRDY\* is high and the programmed waitstates are elapsed, the processor remains in a waiting state. It retrieves a nominal behaviour when a bus timeout occurs.

#### Workarounds

When 'n' waitstates are programmed, generate a 'n+2' SYSCLK cycles length BUSRDY\*.

When the programmed waitstates elapse, assert a second pulse of BUSRDY\*.



## SPARC Processor

## TSC695

## Errata Sheet

4280D-AERO-07/06



### 3. Floating-Point Compare Single or Double Instruction followed by specific IU Instruction followed by Floating-Point Store Double Instruction

If a floating-point compare single or double instruction (FCMPS, FCMPEs, FCMpD or FCMpED) is immediately followed by one of the OR, ORcc, ORN, ORNcc, SRL, TADDccTV, Ticc, RDWIM or WRWIM instruction, and the next instruction is a floating-point store double (STDF) of any floating-point register (involved or not in the floating-point compare single or double instruction), the stored floating-point double value is corrupted.

Data corruption happens as follows: the program location of the floating-point compare single or double instruction is written into memory at the effective store address instead of the expected most significant word in the even-numbered floating-point source register.

The floating-point registers involved in the floating-point store double operation are not corrupted, nor any other floating-point register.

The error case appears when any of the four following sequences of instructions is present:

– Case 1:

```
FCMPS %fx,%fy
IUOp(1)
STD %fz, [address]
```

– Case 2:

```
FCMPES %fx,%fy
IUOp(1)
STD %fz, [address]
```

– Case 3:

```
FCMPD %fx,%fy
IUOp(1)
STD %fz, [address]
```

– Case 4:

```
FCMPED %fx,%fy
IUOp(1)
STD %fz, [address]
```

Note: 1. IUOp is one of OR, ORcc, ORN, ORNcc, SRL, TADDccTV, Ticc, RDWIM or WRWIM instructions, whatever the operands are.

#### Workarounds

If direct control over assembly language is possible, simply insert a NOP after the floating-point compare single or double instruction:

– Case 1:

```
FCMPS %fx,%fy
NOP
IUOp(1)
STD %fz, [address]
```

– Case 2:

```
FCMPES %fx,%fy
NOP
IUOp(1)
STD %fz, [address]
```

– Case 3:

```
FCMPD %fx,%fy
NOP
```

---

```
IUop(1)  
STD    %fz, [address]
```

– Case 4:

```
FCMPED %fx, %fy  
NOB  
IUop(1)  
STD    %fz, [address]
```

Note: 1. *IUop* is one of OR, ORcc, ORN, ORNcc, SRL, TADDccTV, Ticc, RDWIM or WRWIM instructions, whatever the operands are.

If direct control over assembly language is not possible (high-level programming language such as C), checking of the SPARC binary code against any of the four above mentioned faulty sequences of instructions shall be done using the check program provided by Atmel (see *doc7662.pdf* on Atmel web site).

Although there is a very low likelihood of occurrence with high-level programming languages, customers facing this problem shall contact SPARC hotline ([sparc-applab.hotline@nto.atmel.com](mailto:sparc-applab.hotline@nto.atmel.com)).



## Atmel Corporation

2325 Orchard Parkway  
San Jose, CA 95131, USA  
Tel: 1(408) 441-0311  
Fax: 1(408) 487-2600

## Regional Headquarters

### Europe

Atmel Sarl  
Route des Arsenaux 41  
Case Postale 80  
CH-1705 Fribourg  
Switzerland  
Tel: (41) 26-426-5555  
Fax: (41) 26-426-5500

### Asia

Room 1219  
Chinachem Golden Plaza  
77 Mody Road Tsimshatsui  
East Kowloon  
Hong Kong  
Tel: (852) 2721-9778  
Fax: (852) 2722-1369

### Japan

9F, Tonetsu Shinkawa Bldg.  
1-24-8 Shinkawa  
Chuo-ku, Tokyo 104-0033  
Japan  
Tel: (81) 3-3523-3551  
Fax: (81) 3-3523-7581

## Atmel Operations

### Memory

2325 Orchard Parkway  
San Jose, CA 95131, USA  
Tel: 1(408) 441-0311  
Fax: 1(408) 436-4314

### Microcontrollers

2325 Orchard Parkway  
San Jose, CA 95131, USA  
Tel: 1(408) 441-0311  
Fax: 1(408) 436-4314

### La Chantrerie

BP 70602  
44306 Nantes Cedex 3, France  
Tel: (33) 2-40-18-18-18  
Fax: (33) 2-40-18-19-60

### ASIC/ASSP/Smart Cards

Zone Industrielle  
13106 Rousset Cedex, France  
Tel: (33) 4-42-53-60-00  
Fax: (33) 4-42-53-60-01

1150 East Cheyenne Mtn. Blvd.  
Colorado Springs, CO 80906, USA  
Tel: 1(719) 576-3300  
Fax: 1(719) 540-1759

Scottish Enterprise Technology Park  
Maxwell Building  
East Kilbride G75 0QR, Scotland  
Tel: (44) 1355-803-000  
Fax: (44) 1355-242-743

### RF/Automotive

Theresienstrasse 2  
Postfach 3535  
74025 Heilbronn, Germany  
Tel: (49) 71-31-67-0  
Fax: (49) 71-31-67-2340

1150 East Cheyenne Mtn. Blvd.  
Colorado Springs, CO 80906, USA  
Tel: 1(719) 576-3300  
Fax: 1(719) 540-1759

### Biometrics/Imaging/Hi-Rel MPU/ High Speed Converters/RF Datacom

Avenue de Rochepleine  
BP 123  
38521 Saint-Egreve Cedex, France  
Tel: (33) 4-76-58-30-00  
Fax: (33) 4-76-58-34-80

---

### Literature Requests

[www.atmel.com/literature](http://www.atmel.com/literature)

**Disclaimer:** The information in this document is provided in connection with Atmel products. No license, express or implied, by estoppel or otherwise, to any intellectual property right is granted by this document or in connection with the sale of Atmel products. **EXCEPT AS SET FORTH IN ATMEL'S TERMS AND CONDITIONS OF SALE LOCATED ON ATMEL'S WEB SITE, ATMEL ASSUMES NO LIABILITY WHATSOEVER AND DISCLAIMS ANY EXPRESS, IMPLIED OR STATUTORY WARRANTY RELATING TO ITS PRODUCTS INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, OR NON-INFRINGEMENT. IN NO EVENT SHALL ATMEL BE LIABLE FOR ANY DIRECT, INDIRECT, CONSEQUENTIAL, PUNITIVE, SPECIAL OR INCIDENTAL DAMAGES (INCLUDING, WITHOUT LIMITATION, DAMAGES FOR LOSS OF PROFITS, BUSINESS INTERRUPTION, OR LOSS OF INFORMATION) ARISING OUT OF THE USE OR INABILITY TO USE THIS DOCUMENT, EVEN IF ATMEL HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.** Atmel makes no representations or warranties with respect to the accuracy or completeness of the contents of this document and reserves the right to make changes to specifications and product descriptions at any time without notice. Atmel does not make any commitment to update the information contained herein. Unless specifically provided otherwise, Atmel products are not suitable for, and shall not be used in, automotive applications. Atmel's products are not intended, authorized, or warranted for use as components in applications intended to support or sustain life.

© Atmel Corporation 2006. All rights reserved. Atmel®, logo and combinations thereof, and Everywhere You Are® are the trademarks or registered trademarks, of Atmel Corporation or its subsidiaries. Other terms and product names may be trademarks of others.



Printed on recycled paper.

4280D-AERO-07/06