
DI Errata

- ATAM893S
- ATAM894P
- ATAR092P
- ATAR892P
- ATAR090H
- ATAR890H
- ATAR080F
- ATA6020N
- ATAR510F
- ATAR862N3/N4/N8

The latest product enhancement (PCN HC030703 DI enhancement) introduced to all MARC4 products during 2003, leads, under some conditions, to an unforeseen and unwanted behavior. The circuit may not process interrupts correctly. All above mentioned MARC4 products are affected.

Description

If a DI command is immediately followed by a CALL or SCALL command and an interrupt meets this DI command, this interrupt is kept in the interrupt active register permanently despite a correct RTI execution. Even if the EI command in the interrupted program has been executed, this bit in the interrupt active register stays set and disables the execution of any interrupt of the same or lower priority. Only an interrupt with a higher priority or a reset is able to solve this blocking status.

If the command following the DI is a NOP, the interrupt active register usually is cleared correctly after an RTI and executing interrupts then continues normally.



MARC4 4-bit Microcontrollers

ATAM893S
ATAM894P
ATAR092/892P
ATAR090/890H
ATAR080F
ATA6020N
ATAR510F
ATAR862N3/4/8

Errata Sheet

Rev. 4813A-4BMCU-06/04



Workaround

MTP Parts

a) Experienced customers using Atmel MTP parts (ATAM893S, ATAM894P) can modify the HEX-file directly. Within each interrupt service routine, replace the HEX-code for CCR! in front of the RTI with a SCALL to a free address. Introduce the HEX-codes for the commands LIT_1, OR, CCR! and EXIT at this address. Now, with each RTI, the interrupt enable flag is set. This software modification overrides the last hardware modification, i.e., the parts behave as if not having received DI-enhancement, and the interrupt active register will be cleared correctly.

b1) An equivalent modification can be done in the source code, but the modification depends on the content the compiler saved at the beginning of an interrupt service routine:

```
0080 : INT1
0080 0D CCR@ \ $SAVEREG
0081 73 Y@
0082 72 X@
```

In this case, CCR, X and Y registers were saved, therefore, the modification should look as follows:

```
2>R 2>R 1 or 2R> 2R>
```

either at the beginning or at the end of the interrupt service routine.

b2) If only CCR and one of the registers were saved:

```
01E0 :INT7
01E0 0D CCR@ \ $SAVEREG
01E1 73 Y@
```

The modification looks as follows:

```
ROT 1 or <ROT
```

c) Customers using MTP parts may switch their order to the predecessor version.

ROM Parts

Customers using ROM parts may switch their order to the predecessor version.

Up to now it has not occurred, that parts working correctly under all conditions might fail in the future or under different environmental conditions.



Atmel Corporation

2325 Orchard Parkway
San Jose, CA 95131, USA
Tel: 1(408) 441-0311
Fax: 1(408) 487-2600

Regional Headquarters

Europe

Atmel Sarl
Route des Arsenalux 41
Case Postale 80
CH-1705 Fribourg
Switzerland
Tel: (41) 26-426-5555
Fax: (41) 26-426-5500

Asia

Room 1219
Chinachem Golden Plaza
77 Mody Road Tsimshatsui
East Kowloon
Hong Kong
Tel: (852) 2721-9778
Fax: (852) 2722-1369

Japan

9F, Tonetsu Shinkawa Bldg.
1-24-8 Shinkawa
Chuo-ku, Tokyo 104-0033
Japan
Tel: (81) 3-3523-3551
Fax: (81) 3-3523-7581

Atmel Operations

Memory

2325 Orchard Parkway
San Jose, CA 95131, USA
Tel: 1(408) 441-0311
Fax: 1(408) 436-4314

Microcontrollers

2325 Orchard Parkway
San Jose, CA 95131, USA
Tel: 1(408) 441-0311
Fax: 1(408) 436-4314

La Chantrerie
BP 70602
44306 Nantes Cedex 3, France
Tel: (33) 2-40-18-18-18
Fax: (33) 2-40-18-19-60

ASIC/ASSP/Smart Cards

Zone Industrielle
13106 Rousset Cedex, France
Tel: (33) 4-42-53-60-00
Fax: (33) 4-42-53-60-01

1150 East Cheyenne Mtn. Blvd.
Colorado Springs, CO 80906, USA
Tel: 1(719) 576-3300
Fax: 1(719) 540-1759

Scottish Enterprise Technology Park
Maxwell Building
East Kilbride G75 0QR, Scotland
Tel: (44) 1355-803-000
Fax: (44) 1355-242-743

RF/Automotive

Theresienstrasse 2
Postfach 3535
74025 Heilbronn, Germany
Tel: (49) 71-31-67-0
Fax: (49) 71-31-67-2340

1150 East Cheyenne Mtn. Blvd.
Colorado Springs, CO 80906, USA
Tel: 1(719) 576-3300
Fax: 1(719) 540-1759

Biometrics/Imaging/Hi-Rel MPU/ High Speed Converters/RF Datacom

Avenue de Rochepleine
BP 123
38521 Saint-Egreve Cedex, France
Tel: (33) 4-76-58-30-00
Fax: (33) 4-76-58-34-80

Literature Requests

www.atmel.com/literature

Disclaimer: Atmel Corporation makes no warranty for the use of its products, other than those expressly contained in the Company's standard warranty which is detailed in Atmel's Terms and Conditions located on the Company's web site. The Company assumes no responsibility for any errors which may appear in this document, reserves the right to change devices or specifications detailed herein at any time without notice, and does not make any commitment to update the information contained herein. No licenses to patents or other intellectual property of Atmel are granted by the Company in connection with the sale of Atmel products, expressly or by implication. Atmel's products are not authorized for use as critical components in life support devices or systems.

© Atmel Corporation 2004. All rights reserved.

Atmel® and combinations thereof are the registered trademarks of Atmel Corporation or its subsidiaries.

Other terms and product names may be the trademarks of others.



Printed on recycled paper.

4813A-4BMCU-06/04