



# PIC24FV32KA304 FAMILY

## PIC24FV32KA304 Family Silicon Errata and Data Sheet Clarification

The PIC24FV32KA304 family devices that you have received conform functionally to the current Device Data Sheet (DS39995B), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).

The errata described in this document will be addressed in future revisions of the PIC24FV32KA304 family silicon.

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (A4).

Data Sheet clarifications and corrections start on [page 4](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip’s programmers, debuggers, and emulation tools, which are available at the Microchip corporate web site ([www.microchip.com](http://www.microchip.com)).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with MPLAB ICD 2 or PICKit™ 3:

1. Using the appropriate interface, connect the device to the MPLAB ICD 2 programmer/debugger or PICKit™ 3.
2. From the main menu in MPLAB IDE, select *Configure>Select Device*, and then select the target part number in the dialog box.
3. Select the MPLAB hardware tool (*Debugger>Select Tool*).
4. Perform a “Connect” operation to the device (*Debugger>Connect*). Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

**Note:** If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC24FV32KA304 family silicon revisions are shown in [Table 1](#).

**TABLE 1: SILICON DEVREV VALUES**

Part Number	Device ID <sup>(1)</sup>	Revision ID for Silicon Revision <sup>(2)</sup>	Part Number	Device ID <sup>(1)</sup>	Revision ID for Silicon Revision <sup>(2)</sup>
		A4			A4
PIC24F32KA304	4516h	0004h	PIC24FV32KA304	4517h	0004h
PIC24F32KA302	4512h		PIC24FV32KA302	4513h	
PIC24F32KA301	4518h		PIC24FV32KA301	4519h	
PIC24F16KA304	4506h		PIC24FV16KA304	4507h	
PIC24F16KA302	4502h		PIC24FV16KA302	4503h	
PIC24F16KA301	4508h		PIC24FV16KA301	4509h	

- Note 1:** The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format “DEVID DEVREV”.
- 2:** Refer to the “*PIC24FXXKA1XX/KA3XX Flash Programming Specifications*” (DS39919) for detailed information on Device and Revision IDs for your specific device.

# PIC24FV32KA304 FAMILY

---

---

**TABLE 2: SILICON ISSUE SUMMARY**

Module	Feature	Item Number	Issue Summary	Affected Revisions <sup>(1)</sup>
				A4
Core	Low-Voltage Regulator	1.	High-voltage programming entry unavailable in Low-Voltage Sleep modes.	X
Reset	BOR	2.	Unexpected BOR events when BOR is disabled in Sleep mode.	X
A/D	Threshold Detect	3.	Auto-scan feature may not trigger correctly in Sleep mode.	X

**Note 1:** Only those issues indicated in the last column apply to the current silicon revision.

# PIC24FV32KA304 FAMILY

## Silicon Errata Issues

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (A4).

### 1. Module: Core (Low-Voltage Regulator)

When operating in Low-Voltage Sleep mode,  $LVREN = 1$  (RCON<12>) and  $LVRCFG = 0$  (FPOR<2>), the device may not be able to enter programming modes using high-voltage entry ( $V_{IH}$  applied to MCLR).

#### Work around

If entry into a programming mode is required while the device is in Low-Voltage Sleep mode, use low-voltage entry into programming. Verify that MCLR functionality is enabled,  $MCLRE = 1$  (FPOR<7>), before attempting programming.

#### Affected Silicon Revisions

A4							
X							

### 2. Module: Reset (BOR)

Under certain conditions, the device may improperly perform a Brown-out Reset upon wake-up from a Sleep mode. This has been observed under two conditions:

1. When the BOR is disabled in Sleep mode,  $BOREN<1:0> = 10$  (FPOR<1:0>), a BOR may occur when the device wakes from Sleep, regardless of the supply voltage.
2. When the BOR is configured for software control ( $BOREN<1:0> = 01$ ), the device enters and wakes from Sleep normally while the BOR is disabled in software,  $SBOREN = 0$  (RCON<13>). However, if the BOR was disabled prior to entering Sleep mode and is subsequently enabled after waking from Sleep, a BOR may occur, regardless of the supply voltage.

BOR functions normally when it is always enabled or disabled ( $BOREN<1:0> = 11$  or  $00$ ).

#### Work around

Do not use Sleep mode when  $BOREN<1:0> = 10$ .

If the BOR is to operate under software control, always enable the HLVD module,  $HLVDEN = 1$  (HLVDCON<15>), before enabling the BOR in software ( $SBOREN = 1$ ). This procedure activates the internal band gap reference and assures its stability for the BOR circuit.

#### Affected Silicon Revisions

A4							
X							

### 3. Module: A/D (Threshold Detect)

When the auto-scan feature of Threshold Detect is enabled ( $AD1CON5<15> = 1$ ), automatic scan may fail when these conditions occur together:

- the Device is in Sleep mode, and
- Timer1 is selected as the sample trigger clock source ( $AD1CON1<7:4> = 0101$ ).

Timer1 and other timers will function correctly as sample triggers in other power-saving modes, such as Idle mode.

#### Work around

If auto-scan functionality is required during Sleep, use INT0 as the sample trigger.

#### Affected Silicon Revisions

A4							
X							

# PIC24FV32KA304 FAMILY

---

## Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS39995B):

<b>Note:</b> Corrections are shown in <b>bold</b> . Where possible, the original bold text formatting has been removed for clarity.
---

### 1. Module: Overview (and Other Locations)

In several locations throughout the document, references are made to, and information provided for, devices in 20-pin QFN packages. In fact, PIC24FV32KA304 family devices are not available in this package type.

All data for 20-pin QFN packages for this family is to be disregarded. This includes:

- Table 1-3, "PIC32FV32KA304 Family Pinout Descriptions".
- Table 29-2, "Thermal Packaging Characteristics" in **Section 29.0 "Electrical Characteristics"**.

### 2. Module: Overview

Throughout Table 1-3 ("PIC32FV32KA304 Family Pinout Descriptions"), the pin assignments for some functions have been incorrectly listed for some package types. These include:

- All CTMU Edge Detect Inputs (CTEDn)
- Input Capture 1
- Output Compare 1 and 3
- Output Compare Fault Input B
- ICSP™ Ports 2 and 3 (PGEC/D 2 and 3)
- I2C2 Clock
- SPI1 and 2 Pins (SCK1 and 2, SDI1 and 2, SDO2,  $\overline{SS2}$ )
- UART1 Transmit and Receive

In some cases, the pin assignments listed were in error. In others, multiple pin assignments were listed where only one existed.

Corrected values for the affected pin functions are provided in [Table 3](#) (corrections in **bold**). Pin functions and assignments that are not shown in this table may be assumed to be correct in the original device data sheet. In addition, the fully multiplexed pin names, shown in the package diagrams at the beginning of the data sheet, may be assumed to be correct.

# PIC24FV32KA304 FAMILY

**TABLE 3: PIC24FV32KA304 FAMILY AMENDED PINOUTS**

Function	F					FV				
	Pin Number					Pin Number				
	20-Pin PDIP/ SSOP/ SOIC	28-Pin SPDIP/ SSOP/ SOIC	28-Pin QFN	44-Pin QFN/ TQFP	48-Pin UQFN	20-Pin PDIP/ SSOP/ SOIC	28-Pin SPDIP/ SSOP/ SOIC	28-Pin QFN	44-Pin QFN/ TQFP	48-Pin UQFN
CTED1	14	20	17	7	7	11	2	27	19	21
CTED2	15	23	20	10	11	15	23	20	10	11
CTED3	—	19	16	6	6	—	19	16	6	6
CTED4	13	18	15	1	1	13	18	15	1	1
CTED5	17	25	22	14	15	17	25	22	14	15
CTED6	18	26	23	15	16	18	26	23	15	16
CTED7	—	—	—	5	5	—	—	—	5	5
CTED8	—	—	—	13	14	—	—	—	13	14
CTED9	—	22	19	9	10	—	22	19	9	10
CTED10	12	17	14	44	48	12	17	14	44	48
CTED11	—	21	18	8	9	—	21	18	8	9
CTED12	5	5	2	22	24	5	5	2	22	24
CTED13	6	6	3	23	25	6	6	3	23	25
IC1	14	19	16	6	6	11	19	16	6	6
OC1	14	20	17	7	7	11	16	13	43	47
OC3	5	21	18	12	13	5	21	18	12	13
OFCB	16	24	21	32	35	16	24	21	32	35
PGEC2	2	22	19	9	10	2	22	19	9	10
PGED2	3	21	18	8	9	3	21	18	8	9
PGEC3	10	15	12	42	46	10	15	12	42	46
PGED3	9	14	11	41	45	9	14	11	41	45
SCK1	15	22	19	9	10	15	22	19	9	10
SCK2	2	14	11	38	41	2	14	11	38	41
SCL2	18	7	4	24	26	18	7	4	24	26
SDI1	17	21	18	8	9	17	21	18	8	9
SDI2	4	19	16	36	39	4	19	16	36	39
SDO2	3	15	12	37	40	3	15	12	37	40
SS2	15	23	20	35	38	15	23	20	35	38
U1RX	6	6	3	2	2	6	6	3	2	2
U1TX	11	16	13	3	3	11	16	13	3	3

### 3. Module: A/D (Threshold Detect)

In Figure 22-2, the CHOLD capacitor is listed with an incorrect value. The correct value is 32 pF.

# PIC24FV32KA304 FAMILY

---

## APPENDIX A: DOCUMENT REVISION HISTORY

### Rev A Document (3/2011)

Initial release of this document; issued for revision A4. Includes silicon issues 1 (Core, Low-Voltage Regulator) and 2 (Reset, BOR).

### Rev B Document (5/2011)

Adds silicon issue 3 (A/D, Threshold Detect) to silicon revision A4.

Adds data sheet clarifications 1 (Overview and Other Locations), 2 (Overview) and 3 (A/D, Threshold Detect) for data sheet revision B.

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

**Trademarks**

The Microchip name and logo, the Microchip logo, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC<sup>32</sup> logo, rPIC and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniscient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICTail, REAL ICE, rLAB, Select Mode, Total Endurance, TSHARC, UniWinDriver, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2011, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN: 978-1-61341-158-2

*Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC<sup>®</sup> MCUs and dsPIC<sup>®</sup> DSCs, KEELOQ<sup>®</sup> code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*

**QUALITY MANAGEMENT SYSTEM  
CERTIFIED BY DNV  
== ISO/TS 16949:2002 ==**



# MICROCHIP

## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Cleveland**  
Independence, OH  
Tel: 216-447-0464  
Fax: 216-447-0643

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Farmington Hills, MI  
Tel: 248-538-2250  
Fax: 248-538-2260

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**Santa Clara**  
Santa Clara, CA  
Tel: 408-961-6444  
Fax: 408-961-6445

**Toronto**  
Mississauga, Ontario,  
Canada  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Harbour City, Kowloon  
Hong Kong  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8569-7000  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

**China - Chongqing**  
Tel: 86-23-8980-9588  
Fax: 86-23-8980-9500

**China - Hangzhou**  
Tel: 86-571-2819-3180  
Fax: 86-571-2819-3189

**China - Hong Kong SAR**  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**China - Nanjing**  
Tel: 86-25-8473-2460  
Fax: 86-25-8473-2470

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8203-2660  
Fax: 86-755-8203-1760

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xian**  
Tel: 86-29-8833-7252  
Fax: 86-29-8833-7256

**China - Xiamen**  
Tel: 86-592-2388138  
Fax: 86-592-2388130

**China - Zhuhai**  
Tel: 86-756-3210040  
Fax: 86-756-3210049

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444  
Fax: 91-80-3090-4123

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-2566-1512  
Fax: 91-20-2566-1513

**Japan - Yokohama**  
Tel: 81-45-471- 6166  
Fax: 81-45-471-6122

**Korea - Daegu**  
Tel: 82-53-744-4301  
Fax: 82-53-744-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Kuala Lumpur**  
Tel: 60-3-6201-9857  
Fax: 60-3-6201-9859

**Malaysia - Penang**  
Tel: 60-4-227-8870  
Fax: 60-4-227-4068

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-6578-300  
Fax: 886-3-6578-370

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830  
Fax: 886-7-330-9305

**Taiwan - Taipei**  
Tel: 886-2-2500-6610  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**UK - Wokingham**  
Tel: 44-118-921-5869  
Fax: 44-118-921-5820

05/02/11