Motorola Semiconductor Technical Data

Addendum to MC68HC908GR8

This addendum provides changes to the MC68HC908GR8 Technical Data Book Rev 4 (Motorola document order number MC68HC908GR8/D).

Incorrect Register Adresses

Incorrect addresses:

Address of Interrupt Status Register 1 (INT1) should be \$FE04, not \$FE09

Address of Interrupt Status Register 2 (INT2) should be \$FE05, not \$FE0A

Address of Interrupt Status Register 3 (INT3) should be \$FE06, not \$FE0B

Locations:

In 4th, 5th and 6th bullets of page 36, Memory Map section.

Near bottom of memory map on page 37, Memory Map section.

In bottom two registers on page 45 and top register on page 46, Memory Map section.

In last three registers on page 274, SIM section.



Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights or the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and

How to reach us:

USA/EUROPE: Motorola Literature Distribution; P.O. Box 5405, Denver, Colorado 80217. 1-303-675-2140

HOME PAGE: http://motorola.com/sps/

JAPAN: Motorola Japan Ltd.; SPS, Technial Information Center, 3-20-1, Minami-Azabu, Minato-ku, Tokyo 106-8573 Japan.

81-3-3440-3569

ASIA/PACIFIC: Motorola Semiconductors H.K. Ltd.; Silicon Harbour Centre, 2 Dai King Street, Tai Po Industrial Estate,

Tai Po, N.T., Hong Kong. 852-266668334 CUSTOMER FOCUS CENTER: 1-800-521-6274



© Motorola, Inc., 2002

MC68HC908GR8AD2/D