

RELIABILITY NOTE

OUR NAMY YEARS OF EXPERENCE DATA ACCUMULATION INDICATE THAT

SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.
PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

DRAWN BY:

BC

CHECKED BY:

APPROVED BY:

DATE:

PAGE:

SCALE:

10.6.98

1 OF 1

SSI-LXR3816PGDB150

T-5mm 555nm PURE GREEN LED PANEL INDICATOR,

GREEN DIFFUSED LENS, 6.0" WIRE LEADS.

Α