Search in the partlist [Devices]

Search products by..

if necessary restrict the search on parts

	Partlist
20 73 305 3921	
ESC 67-30 TP05, Data 3A	

Series	Ethernet Switch ESC 67-30 TP05U
	HARTING RJ Industrial® IP 67 Data 3A
	Ethernet Switch for the industrial apllications
Protection level	IP 65/IP 67 outside the control cabinet
	IP 20 inside the control cabinet
Hood type	Robust metal housing of die cast aluminium alloy
Dimensions	105x40x120 (WxDxH in mm, without connectors)
Mounting	directly on control cabinets and terminal boxes
Operating temperature	-40 °C ... + 70 °C
Input voltage	24 V DC (18 ... 30 V DC)
Supply current	100 mA (at 24 V DC)
Terminals	Screw terminal with 5 contacts, plug-in
	redundant power supply
Data transmission rate	10 or 100 MBit/s / auto-negotiation
Cables	Shielded Twisted Pair (STP) or
	Unshielded-Twisted-Pair (UTP), Category 5
Ethernet Interface available device	Outside the control cabinet: 2x HARTING RJ Industrial®
	Data 3A connectors
	Inside the control cabinet: 3 x RJ 45 connectors
	auto-crossing function
Max. cable length	100 m (Cat. 5) in acc. with EN 50 173

Inquiry

© Copyright 1999-2006 Harting KGaA and its licencors - Any suggestions and bug reports are welcome at: HARKIS@harting.com

---

X	**Network Access Message:** **The page cannot be displayed**

Explanation: The request timed out before the page could be retrieved.

Try the following:

- **Refresh page:** Search for the page again by clicking the Refresh button. The timeout may have occurred due to Internet congestion.
- **Check spelling:** Check that you typed the Web page address correctly. The address may have been mistyped.
- **Contact website:** You may want to contact the website administrator to make sure the Web page still exists. You can do this by using the e-mail address or phone number listed on the website home page.

If you are still not able to view the requested page, try contacting your administrator or Helpdesk.

Technical Information (for support personnel)

- Error Code 10060: Connection timeout
- Background: The gateway could not receive a timely response from the website you are trying to access. This might indicate that the network is congested, or that the website is experiencing technical difficulties.
- Date: 5/7/2006 11:19:12 AM
- Server: seba2.SiliconEgypt.com
- Source: Firewall