1

1. Connect 9V battery to board and set the switch to ON.

2

1. Press SEL three times in a row to start punch gauge demo.

2. Screen counts down, 3, 2, 1, Punch!

3

1. Push SEL to continue.

4

1. Insert the kit CD and run the CD's autorun utility.

2. Open the guide and install software.

[+] Feedback

LCD Segment Drive Evaluation Kit Details

- 9V Battery Terminals
- Battery On/Off
- Sleep / Wake Button
- PSoC 3
- JTAG Connector
- 9V-12V DC Power Jack
- CapSense Navigation Buttons

LCD Segment Drive Evaluation Kit Demo Control Flow

Start	Punch Meter	Punch Meter	Punch Meter	Punch Meter
Welcome Screen	PUNCH	Acceleration Measurement	Save Measurements	High ⇅ Gauge ⇅ Clear ⇅ Recall

LCD Demo	LCD Demo	LCD Demo
LCD DEMO	Character Demo	All Segments Demos

Contrast Control	Contrast Control
CONTRAST	Set LCD Contrast

Time-Temp	Time-Temp
RTC/TEMP	Clock Mode ⇅ Alarm On/Off ⇅ Set Alarm ⇅ Set Date ⇅ Set Time

For the latest information about this kit visit
www.cypress.com/go/CY8CKIT-006

[+] Feedback