






PCN - 09 094

Issue Date: July 01 2009

| | | | |
|-----------------------------------|---|-----|------|
| Product Name: | MILLIPACS | | |
| | MILLIPACS HEADERS AND ACCESSORIES | | |
| Product Manager: | JIBU BABU | | |
| Subject: | Process Change Notification | | |
| Distribution: | AM, AP, EU | | |
| Type of Change: | Product Documentation Change | | |
| Change Description: | Replace UL  and / or CSA  marks with combination mark  With the proposed change, there will not be any UL/CSA marking on the Millipacs Straight (HM2P-- series) / Right Angle Header (HM2J-- series) connectors. The UL/CSA marks on the packing box label of Millipacs Headers and Accessories (HM2H-- Series) would also be replaced with the combination mark | | |
| Reason for Change: | This UL Recognized Component Mark became effective April 1, 1998 and may be used on components certified by UL to both Canadian and U.S. requirements. Although UL had not originally planned to introduce a combined Recognized Component Mark, the popularity of the Canada/U.S. Listing and Classification Marks among clients with UL certifications for both Canada and the United States has led to the Combination Mark | | |
| Affected Parts: | Please find attached affected Part Number List | | |
| Effective Date of Change: | October | 01 | 2009 |
| Last Time Buy Date: | N/A | N/A | N/A |
| Last Disty Return Date: | N/A | N/A | N/A |
| Datasheet Attached? | No | | |
| Qual/Test Data Attached? | No | | |
| Samples Availability Date: | N/A | N/A | N/A |
| Available Alternatives? | N/A | | |
| Questions? | Contact your local FCI Representative, or Jibu Babu Sr. Product Engineer – Backpanel PFT, E Mail : Jibu.Babu@fciconnect.com Phone : 91-484-6611582 | | |