



October 24, 2006

AB3 Modem Adapter Board Rev. A Errata

The following schematic issues have been identified with the revision 1.0 of the AB3 Modem Adaptor Board as compared to revision 2.0.

- RD is connected to P4.7, and WR is connected to P4.6. In order to use the parallel interface of the Si2457, these signals must be corrected to match the schematic.
- AOUT_H is not connected to J1.
- SW3 is labeled RESET.