

Test Procedure for the NCP3066 3A BUCK Evaluation Board




Figure 1: Test Configuration

Voltage Supply (12 V, 3 A)	Voltage Meter	Electronic Load or
		Current Source

Test Procedure:

- 1. Connect the test setup as shown in Figure 1.
- 2. Apply Vout = 3.2 V in voltage mode at the electronic load (1 HB white LED).
- 3. Apply the input voltage Vcc = 12.
- 4. Check that Iout is 1050 mA.
- 5. Power down Vcc.
- 6. Power down the load.
- 7. End of test.