## Test Procedure for the NUD4001 Evaluation Board

## ON Semiconductor®



8/14/2006



**Table 1: Required Equipment** 

AC or DC Power Supply	Digital Multimeter	Red Test Leads
Black Test Leads		

## **Test Procedure:**

- 1. Apply 12 V ac or dc to the input pins.
- 2. The LEDs will light up.
- 3. Measure the current through the LEDs. It should be between 305 mA to 345 mA (325 mA typical).