


Product Discontinuation Notice


May, 2010

Discontinuation of DS relay (1-coil latching)



1. Reason: Low market demand

2. Affected parts:

 <p>DS relays</p>	<p>2 Form C 1-coil latching type</p>	<p>DS2E-ML- DS2E-SL-</p>
---	--	------------------------------

3. Last time buy: End of August 2010

4. Substitution:

<p>TX relay 1-coil latching type</p>	<p>TX2O-L- TX2O-L-H-</p>
--	------------------------------

Any questions, please contact your local Panasonic Electric Works Sales representatives.

(Ref#: T-1169)