



Product/Process  
Change  
Notification  
**PCN08139**

<b>Product:</b>	Clincher™ Latch Header Connectors	<b>Part Numbers Concerned:</b>	See list attached
<b>Product Manager:</b>	Alejandro Aguirre	<b>Issue Date:</b>	Oct 3 08
		<b>Page(s):</b>	1/1
<b>Distribution:</b>	GLOBAL		

**Subject:**

Clincher™ Latch Header Connectors color change only

**Nature of Change:**

Housing color for all Clincher™ Latch Header Connectors will be change from “black” to “natural” color.

**Impact of change:**

None. Resin will remain the same. Only the color will change. These connectors are internal board-to-cable connectors and color is not a customer requirement. Older black color and new natural color Clincher™ latch header connectors will mate to Clincher™ receptacle connectors designed for termination to flat flexible cable (FFC).

**Reason for chance:**

This change will consolidate resins and support increased responsiveness to customers.

**Implementation Date:**

After January 9<sup>th</sup> , 2009

**Affected Part Numbers:**

See attached file.

**Action Required:**

Notify all customers for this color change.

**For questions regarding this PCN contact:**

Alejandro Aguirre

Product Manager

Email.- [alejandro.aguirre@fci.com](mailto:alejandro.aguirre@fci.com)

MX Phone 01152 (656) 692-5872

USA Phone (915) 356-1172

MX Mobile Phone (656) 130-3351

Or contact your nearest FCI representative