

RELIABILITY NOTE
OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT
SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.
PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

CHECKED BY: APPROVED BY: DATE:

1.8.02

1 OF 1

<u>N/</u>A

PAGE:

SCALE:

DRAWN BY:

вс

T-5mm 636nm AllnGaP RED LED PANEL INDICATOR,

RED DIFFUSED LENS, 6" WIRE LEADS.