

# Connectors for control signals




## CM-series

HiPower











Type		Number of poles	Description	Order no.
		6 + PE	Cable socket, straight design, strain relief by means of a clamp Operating voltage: 10 A	932 460-100
		7	Cable socket, straight design, strain relief by means of a clamping cage Operating current: 16 A	933 052-100
		8	Cable socket, straight design, strain relief by means of a clamping cage Operating current: 10 A	932 842-100
		14	Cable socket, straight design, strain relief by means of a clamping cage Operating current: 5 A	933 067-100
		17	Cable socket, straight design, strain relief by means of a clamping cage Operating current: 4 A	933 068-100

# Connectors for control signals



## CM-series

HiPower











Type		Number of poles	Description	Order no.
		3	Surface-mounted connector with flange, contacts with solder bucket Operating current: 10 A	<b>933 047-100</b>
		4	Surface-mounted connector with flange, contacts with solder bucket Operating current: 10 A	<b>932 449-100</b>
		5	Surface-mounted connector with flange, contacts with solder bucket Operating current: 10 A	<b>932 843-100</b>
		6	Surface-mounted connector with flange, contacts with solder bucket Operating current: 10 A	<b>932 451-100</b>
		6 + PE	Surface-mounted connector with flange, contacts with solder bucket Operating current: 16 A	<b>932 455-100</b>

# Connectors for control signals



## CM-series

HiPower

Type		Number of poles	Description	Order no.
		6 + PE	Surface-mounted connector with flange, tipped with filters 6x1 nF Operating current: 2 A	<b>932 988-100</b>
		7	Surface-mounted connector with flange, contacts with solder bucket Operating current: 16 A	<b>933 050-100</b>
		8	Surface-mounted connector with flange, contacts with solder bucket Operating current: 10 A	<b>932 845-100</b>
		14	Surface-mounted connector with flange, contacts with solder bucket Operating current: 5 A	<b>933 062-100</b>
		17	Surface-mounted connector with flange, contacts with solder bucket Operating current: 4 A	<b>933 063-100</b>












HIRSCHMANN


# Connectors for control signals



## CM-series





HiPower

Type		Number of poles	Description	Order no.
 <p>CM 02 SD 14S</p>		-	Protection cap for surface-mounted connectors 3 – 6-pole	<b>831 620-100</b>
 <p>CM 02 SD 20</p>		-	Protection cap for surface-mounted connectors 7 – 17-pole	<b>831 766-100</b>
 <p>CM 06 SD 14S</p>		-	Protection cap for cable sockets 3 – 6-pole	<b>831 621-100</b>
 <p>CM 06 SD 20</p>		-	Protection cap for cable sockets 7 – 17-pole	<b>831 767-100</b>
 <p>CM 02 D 14S</p>		-	Flat gasket NBR	<b>733 321-002</b>



## CM-series

HiPower

Type		Number of poles	Description	Order no.
 <p>CM 02 D 20</p>		-	Flat gasket NBR	733 818-002
 <p>SHK 1</p>		-	Protective cover for surface-mounted connectors	733 849-001

## Notes