

RELIABILITY NOTE

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT

SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.

PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

DRAWN BY:

BC

CHECKED BY:

APPROVED BY: DATE:

PAGE:

SCALE:

2 26 99

1 OF 1

_N/A

T-5mm LED, SNAP-IN FAULT INDICATOR,

565nm SUPER GREEN LED, WATER CLEAR LENS.