

THE INFORMATION CONTINENTIAL INFORMATION
THE INFORMATION CONTINED IN THIS DOCUMENT IS THE PROPERTY OF
LUMEX NO. DIGGET AS SECFORALLY AUTHORIZED IN WRITING BY LUMEX
INC, THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION
CONTINEND HEREIN CONTINENTIAL AND SHALL PROPIET SAME IN WHOLE OR
IN PART FROM DISCLIGATION AND STALL PROPIET SAME IN WHOLE OR

RELIABILITY NOTE

OUR MANY YEARS OF EXPERENCE DATA ACCUMULATION INDICATE THAT

SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.
PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

DRAWN BY:

BC

290 E. HELEN ROAD PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com TW WEB: www.lumex.com.tw

DATE:

PAGE:

SCALE:

11.6.90

1 OF 1

CHECKED BY: APPROVED BY:

PART NUMBER

SSI-LXR4815ID-150B

T-5mm 635nm RED LED PANEL INDICATOR LED,

RED DIFFUSED LENS, WITH 6" WIRE LEADS.

REV.

 $\mathsf{D}$