

RELIABILITY NOTE
OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT
SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.
PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

290 E. HELLEN ROAD
PALATINE, ILLINOIS 60067
PHONE: (847) 359–2790
WEB: http://www.lumex.com

PAGE: 1 OF 1

N/A

SCALE:

CHECKED BY: APPROVED BY: DATE: 12.07.00

INCORPORATED

DRAWN BY:

СТ

PART NUMBER

SSL-LX20583SRD

T-2 STOVEPIPE LED, 660nm SUPER RED LED, RED DIFFUSED.

REV.