



Product/Process  
Change  
Notification  
**PCN08192**

<b>Product:</b>	Power USB plug kit connector of HPL 511	<b>Part Numbers Concerned:</b>	See list attached
<b>Product Manager:</b>	Jeff Liu	<b>Issue Date:</b>	11th Dec, 2008
		<b>Page(s):</b>	1/1
<b>Distribution:</b>	GLOBAL		

**Subject:**

Process change about attaching insulated Mylar in customers' cable assemble post-process for the USB + Power plug kit connector

**Nature of Change:**

In order to guarantee full isolation between terminals and shield, FCI strongly recommends adding insulated Mylar to cable assemblies using the USB + Power plug kit connector. Refer to the customer drawings with application directions.

**Implementation Date:**

No impact about Last time buy date/ Last time shipment date/ Last distributor return date, so the execute date for our customers will be the PCN release date

**Affected Part Numbers:**

74233 series and 57496 series

**Replacements:**

N/A

**Action Required:**

Sales and distributor organisation to notify customers accordingly of the PCN notification.

**For questions regarding this PCN contact:**

Product Manager : [Jeff Liu](#)

[Tel: 86 513 80167370](tel:8651380167370)

Email: [Jeff.Liu@fci.com](mailto:Jeff.Liu@fci.com)

Or contact with your nearest FCI representative