

No Clean Super Wick

Cat. No. 400NS Series



Product Description

Any place you put solder in, you can take it out with Super Wick. Remove the most expensive circuitry with confidence.

Super Wick is pure copper, specially wounded in static free bobbins.

- NO CLEAN type flux
- Static Free Bobbins
- Meets MIL-F-14256F (ansi/j-std-0004)
- RoHS Compliant

Application Tips

Just lay the Super Wick on the soldered joint, apply tip of soldering iron to top side till solder melts, and lift iron and Super Wick together to leave a clean connection ready for component removal or replacement.

Availability

No Clean Super Wick					
Length	0.025" #1 White	0.05" #2 Yellow	0.075" #3 Green	0.1" #4 Blue	0.125" #5 Brown
5 ft	-	424-NS	425-NS	426-NS	-
50 ft	-	453-NS	-	454-NS	-

Note:

This information is believed to be accurate. It is intended for professional end users having the skills to evaluate and use the data properly. M.G. Chemicals Ltd. Does not guarantee the accuracy of the data and assumes no liability in connection with damages incurred while using it.