



UPDATE CHANGE NOTIFICATION

Generic Copy

06 Feb 2008

SUBJECT: ON Semiconductor Update Notification #16096

TITLE: Update Notification to EOL 16083 - H2 2007 Pb to Pb Free Conversion EOL

Last Buy Date for newly added parts on this UN is Aug 06, 2008 Last Ship Date for newly added devices on this UN is Feb 06, 2009

AFFECTED CHANGE CATEGORY(S): Product Discontinuance

AFFECTED PRODUCT DIVISION(S): Logic Analog Discrete

ADDITIONAL RELIABILITY DATA: N/A

SAMPLES: N/A

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor Sales Office or Elizabeth Becker <Elizabeth.Becker@onsemi.com>

NOTIFICATION TYPE:

ON Semiconductor will consider this change approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice. To do so, contact your local ON Semiconductor Sales Office.

DESCRIPTION AND PURPOSE:

This is an Update Notification to EOL 16083 available at www.onsemi.com
EOL 16083 is the second half (H2) 2007 Pb to Pb free conversion EOL. The last BUY date on 16083 was incorrectly listed as July 31 2008. This date should have been listed as June 30 2008 following standard 6 month Buy / 6 month Ship policy.

Additionally, 64 devices that had been previously EOL'd on EOL 16004, (also available at www.onsemi.com) were repeated on 16083. The original dates published in 16004 for these 64 devices should hold. These 64 parts are listed below.

Lastly, some leaded devices were missed on 16083. These devices have been added below as well, and will follow the standard 6 months BUY / 6 months SHIP time frame; giving them a Last Buy date of Aug 06 2008 and a Last Ship date of Feb 06, 2009.

We apologize for any confusion this may have caused. Please contact your local ON Semi Sales office for specific concerns.



Update Notification #16096

AFFECTED DEVICE LIST

PARTS previously listed on EOL 16004 and repeated on 16083
Last BUY DATE was Dec 31 2007 and Last SHIP DATE is June 30
2008. Please contact local sales for concerns

MC34063AD	MC7815ABD2T
MC34063AP1	MC7815ABT
MC34163DW	MC7815ACD2T
MC34163P	MC7815ACT
MC34166D2T	MC7815BD2T
MC34166TH	MC7815BD2TR4
MC34166TV	MC7815BDT
MC34167D2TR4	MC7815BDTRK
MC34167TH	MC7815BT
MC7805ABT	MC7815CD2T
MC7805BD2T	MC7815CDT
MC7805BDT	MC7815CDTRK
MC7805CDTRK	MC7818ACT
MC7806ACT	MC7818BT
MC7806BD2T	MC7818CD2TR4
MC7806BD2TR4	MC7818CT
MC7806BT	MC7824ACT
MC7808ABD2TR4	MC7824BD2T
MC7808ACT	MC7824BD2TR4
MC7808BD2T	MC7824BT
MC7808BDTRK	MC7824CD2T
MC7808BT	MC7824CD2TR4
MC7808CD2TR4	MC7824CT
MC7809ACT	MC78L05ABD
MC7809BT	MC78L08ABD
MC7809CD2T	MC78L08ABDR2
MC7809CT	NCV33269DTRK-3.3
MC7812ABD2T	
MC7812ABD2TR4	
MC7812ABT	
MC7812ACD2T	
MC7812ACT	
MC7812BD2TR4	
MC7812BDT	
MC7812CD2T	
MC7812CDT	
MC7812CDTRK	



Update Notification #16096

AFFECTED DEVICE LIST

ADDITIONAL PARTS added to 16083	
Last BUY DATE Aug 06, 2008 Last SHIP DATE Feb 06, 2009.	
LEADED EOL part	Replacement Pb Free (G) part
NBSG86AMNR2	NBSG86AMNR2G
NBSG72AMNR2	NBSG72AMNR2G
NB7L11MMN	NB7L11MMNG
SB99026MNR2	SB99026MNR2G
SB99026MN	SB99026MNG
NBSG86AMN	NBSG86AMNG
NBSG72AMN	NBSG72AMNG
NBSG53AMN	NBSG53AMNG
NBSG16VSMNR2	NBSG16VSMNR2G
NBSG16VSMN	NBSG16VSMNG
NBSG16MNR2	NBSG16MNR2G
NBSG16MN	NBSG16MNG
NBSG16MMN	NBSG16MMNG
NBSG14MNR2	NBSG14MNR2G
NBSG14MN	NBSG14MNG
NBSG11MNR2	NBSG11MNR2G
NBSG11MN	NBSG11MNG
NB7N017MMN	NB7N017MMNG
NB7L86MMN	NB7L86MMNG
NB7L216MN	NB7L216MNG
NB7L14MMN	NB7L14MMNG
NB7L111MMN	NB7L111MMNG
NB6N239SMN	NB6N239SMNG
NB6L239MNR2	NB6L239MNR2G
NB6L239MN	NB6L239MNG
MC100EPT26MNR4	MC100EPT26MNR4G
MC100EPT23MNR4	MC100EPT23MNR4G
MC100EPT21MNR4	MC100EPT21MNR4G
MC100EP91MN	MC100EP91MNG
74VCXH245MNR2	74VCXH245MNR2G