

PCN #: 08_0092

Title:

Datasheet change: Change Conversion Time for AD7870/AD7875/AD7876 Internal Clock

Date Published:

October 15, 2008

Type:

Device

Part Number:

AD7870/AD7875/AD7876

Proposed Change:

Change from: 7 us min Conversion Time for AD7870/AD7875/AD7876 for Internal Clock.

Change to: 6.5 us min Conversion Time for AD7870/AD7875/AD7876 for Internal Clock.

Reason for Change:

An Edit of the Internal clock spec in the datasheet conversion time from 7 us to 6.5 us is required due to a marginal shift in the conversion time (internal) which leads to a speed change of the conversion.

Planned Date Change Effective:

January 14, 2009

EIA Date Code:

0903

Contact:

Jakub Szymczak

Applications Engineer

Phone: 353 61 494432

Fax: +353 61 304094

Email: jakub.szymczak@analog.com

Analog Devices, Inc.

-- ADI Confidential --
