

RELIABILITY NOTE
OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT
SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.
PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

REV.

CHECKED BY: APPROVED BY: DATE:

4.10.01 1 OF 1

N/A

PAGE:

SCALE:

DRAWN BY:

вс

SSL-LX3054USBC

T-3mm (T-1) 470nm ULTRA SUPER BLUE LED,

WATER CLEAR LENS.

REV.