

RELIABILITY NOTE
OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT
SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.
PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

CHECKED BY: APPROVED BY: DATE:

7.2.01 1 OF 1

<u>N/</u>A

PAGE:

SCALE:

DRAWN BY:

вс

2mm x 5mm RECTANGULAR LED WITH SHOULDER,

636nm SUPER INTENSITY RED LED, RED DIFFUSED LENS.