

<p>A = .100 [2.54] X No. of SPACES B = .100 [2.54] X No. of SPACES + .200 [5.08]</p> <p>4 POSITION SHOWN</p>	<p>CDR STRAIGHT PCB MOUNT</p> <p>CDR-06-TS</p> <p>Recommended PCB Layout</p>
<p>A = .100 [2.54] X No. of SPACES B = .100 [2.54] X No. of SPACES + .200 [5.08]</p> <p>4 POSITION SHOWN</p>	<p>CDR RIGHT ANGLE PCB MOUNT</p> <p>CDR-06-TR</p> <p>Recommended PCB Layout</p>
<p>A = .100 [2.54] X No. of SPACES B = .100 [2.54] X No. of SPACES + .099 [2.51]</p> <p>CDH HOUSING</p> <p>CDH-04</p>	<p>CDH-C-R CONTACT</p>