

## **PUSH & LEVER SERIES**









## SOLDERING PROCESSES

For best results, please follow these recommendations:  $\triangle$  Temperature Profile:

△HAND SOLDERING: Use a soldering iron of 30 watts, Controlled at 350°C approximately 5 seconds while

Applying solder.

**△REFLOW SOLDERING:** When applying reflow soldering the peak temperature of the reflow oven should be set to 260°C max.

