

SEALED MQS/JPT 81P/40P SLIDE LEVER TYPE CONNECTORS

108-5793-3 04JUL06 Rev.A

<u>This specification is the English language version of 108-5793</u> In the event of conflict, 108-5793 shall take precedence.

1. Scope:

1.1 Contents

This specification covers the requirements for product performance test methods and quality assurance provisions of Sealed MQS/JPT 81P/40P Slide Lever Type Connectors. Applicable product description and part numbers are as shown in Appendix 1.

2. Applicable Documents:

The following documents from a part of this specification to the extent specified herein. In the event of conflict between the requirements of this specification and the product drawing, the product drawing shall take precedence. In the event of conflict between the requirements of this specification and the referenced documents, this specification shall take precedence.

2.1 AMP Specifications:

- A. 109-5000 : Test Specification, General Requirements for Test Methods
- B. 114-18021 : Application Specification MQS Receptacle Contact
 - 114-18050-1 : Application Specification JPT Receptacle Contact
- C. 501-5437 : Examination Report
- D. 411-78008 : Instruction Sheet

2.2 Commercial Standards and Specifications:

- A. JASO D605: Multi-pole Connector for automobiles
- B. JASO D7101: Test Methods for Plastic Molded Parts
- C. JIS C3406 : Low-Voltage Wires and Cables for Automobiles
- D. JIS D0203: Method of Moisture, Rain and Spray Test for Automobile Parts
- E. JIS D0204: Method of High and Low Temperature Test for Automobiles Parts
- F. JIS D1601: Vibration Testing Method for Automobile Parts



3. Requirements:

3.1 Design and Construction:

Product shall be of the design, construction and physical dimensions specified on the applicable product drawing.

3.2 Material:

A. Contact:

Description	Material	Finish
· · · · ·	Phosphorus-bronze	Tin
Receptacle (Female)	Copper alloy	Tin
	Fig.1	
3. Housing:		
a. Front Cavity Block 40P : PA6	6	
b. Front Cavity Block 81P : PA66		
c. Main Cavity Block 40P : PBT		
d. Main Cavity Block 81P : PBT		
e. Seal Retainer 40P : PBT		
f. Seal Retainer 81P : PBT		
g. Slider 40P : PA66		
h. Slider 81P : PA66		
i. JPT Retainer : PBT		
j. Family Seal 32P : SILICONE		
k. Family Seal 76P : SILICONE		
I. Seal Ring 40P : SILICONE		
m. Seal Ring 81P : SILICONE		
C. And others:		
a. Wire Cover 40P : PBT		
b. Wire Cover 81P(A) : PBT		
c. Wire Cover 81P(B) : PBT		
d. Lever 40P : PBT		
e. Lever 81P : PBT		
f. MQS Retainer 40P : PBT		
g. MQS Retainer 81P : PBT		
h. Cavity Plug for MQS: PBT		
i.Cavity•Plug for JPT : SILICON	IE	

3.3 Ratings:

A. Temperature Rating: -40° C ~ 120° C

3.4 Performance Requirements and Test Descriptions:

The product shall be designed to meet the electrical, mechanical and environmental performance requirements specified in Fig.2.All tests shall be performed in the room temperature, unless otherwise specified.

3.5 Test Requirements and procedures Summary:

Para.	Test Items	Requirements	Procedures
3.5.1	Confirmation of Product	Meet requirements of product drawing and AMP Specifications	Visually, dimensionally and functionally inspected per applicable quality inspection plan.
		Electrical Requirements	
3.5.2	Termination Resistance (Low Level)	MQS: $30m \Omega$ Max.(Initial) $30m \Omega$ Max.(Final) JPT: $10m \Omega$ Max. (Initial) $10m \Omega$ Max. (Final)	Mated contacts assembled in housing with 20mV max. of open-voltage and 10mA max. of short-circuit current. See Fig.3
3.5.3	Termination Resistance (Specified Current)	MQS 10mV/A Max. (Initial) 30mV/A Max. (Final) JPT 3 mV/A Max. (Initial) 10 mV/A Max. (Final)	Mated contacts assembled in housing with 13V of open-voltage and 1A of short-circuit. See Fig.3
3.5.4	Insulation Resistance	250MΩ Min. (Initial)	Impressed voltage 500V DC. Mated connecter. As shown in Fig.4
3.5.5	Voltage Resistance	No cracking, damage, bending, thin coating coming off or rust is allowed in a terminal. No kink like a crack, solution, backlash and parts coming off or etc. is allowed in housing.	Impressed voltage 1kV AC for 1min. Mated connector. See Fig. 4
3.5.6	Current Leakage	1 μ A Max. (Initial) 10 μ A Max. (Final)	After leaveing the contact in a constant temperature of $60\pm5^{\circ}$ C and humidity 90~95% for 1hour, impressed voltage 13V DC between the terminals. See Fig.5



Para.	Test Items	Requirements	Procedures
3.5.7	Temperature Rising	Under loaded specified current MQS 25°C Max. (Initial) 30°C Max. (Final) JPT 35°C Max. (Initial) 40°C Max. (Final)	Measure temperature rising by engaged current: Current value wire size MQS: 3A 0.5sq JPT: 10A 1.25sq Current applied to every other position. See Fig.6
3.5.8	Fuse Matching Character	No melting of hiusing or no ignition of connector is permitted. Discoloration on housing and cable is possible.	on To be applied current i1 for 24hours. Next, i2 current should be applied for 1hour. However, the i1, i2 and wire size should be followed by the below. Atmosphere temperature should be 60°C. i1 i2 wire size MQS: 11A 14A 0.5sq JPT: 22A 27A 1.25sq
3.5.9	Current Cycle Resistance	Termination Resistance (Low Level): MQS $30m\Omega$ Max. JPT $10m\Omega$ Max. Termination Resistance (Specified Current): MQS 30 mV/A Max. JPT 10 mV/A Max.	Connect the pattern (shown in Fig.6)in series and apply current for 300cycles in the atmosphere. Eachcycle is 45min-ON,15min-OFFCurrent valueMQS:3A0.5sqJPT:10A1.25sq
		Physical Requirement	S
3.5.10	Contact Retention Force	(MQS) Lance only: 20N Max. Secondary lock set: 98N Max. (JPT) Lance only: 59N Max. Secondary lock set: 98N Max.	Apply the pull-off load of the contact to axial. Operation speed: 200 mm/min.
3.5.11	Locking Strength	To be 98N or more. When applying a load of 98N, confirm by the electric continuity that each terminal is perfectly connected to each other. Engaing plug/cap housing assemble with harness, in status where the lever completery connected, and pull th harness to directions(Fing.7). Measur the load values depending on th connector breaking and the lever breaking. Operation Seed: 20mm/min.	
3.5.12	Cover Holding Force	Lengthwise: 60N Max. Crosswise: 90N Max.	In status where the cover is assembled on male/female connector, apply a load to the cable outlet portion and measure the load value when the cover damaged or the cover loosing occurs.



Para.	Test Items	Requirements	Procedures
3.5.13	Lever Operating Force	60N Max.	When engaging male/female connector provided with all contact terminals by using a lever, measure the following load:(I) Necessary load till the lever is completely connected (position A) from the lever temporary connected position (position B the pre-setting is released status). (ii) Necessary load till the lever is temporarily connected (position A) in the temporary status from the lever completed connection (position B this setting is in the released status) See Fig.8
3.5.14	Lever Pre-setting Holding Force (Primary Lock)	10N Min.	When turning the lever in to the engaging direction from the status where the lever is held in the pre-setting(position A), measure the necessary load to release the lever pre-setting. See Fig.8
3.5.15	Lever Complete Setting Force	78N Min.	When turning the lever in to the releasing direction from the status where the lever is held in the complete setting (position B), measure the necessary load to release the lever complete setting. See Fig.8
3.5.16	Lever Pre-Setting Force	50N Max.	Measure the necessary loads to release the complete setting and the pre-setting of the lever.
3.5.17	Excessive Rotation Strength	98N Min.	With status where the lever is assembled on connector not being engaged, measure the load when the housing damage or loosing from the fulcrum occurs by applying the reversal directional load against the lever rotating direction from the lever rotation stop position (the rotation start/final position). See Fig.9



Para.	Test Items	Requirements	Procedures
3.5.18	Lever Fulcrum Strength	200N Min.	Pulling the lever from status where the lever is assembled to connector not being engaged, measure the load when the lever is ran out or broken. See Fig.10
3.5.19	Side Load Lever Operation	98N No falling or damage of the lever is permitted	By applying a load to the vertical direction against the lever rotation direction from the lever inside at atmosphere temp.35°C, Engage the lever the mating connector by turning the lever terminal section. See Fig.11
3.5.20	Worst Connction	All terminals should be made contact without abnormal deformation in each position	Temporarily set cap/plug housing assembled with harness, apply a tension of 80N to direction (up, down. Left and right) for harness and perform connector engaging by the lever. See Fig.12
3.5.21	Decay Resistance (Insert and Separate Repeating)	Termination Resistance(Low Level): MQS 30mΩMax. JPT 10mΩMax. Termination Resistance (Specified Current): MQS 30mV/A Max. JPT 10mV/A Max.	One side of a pair of connectors is fixed, another side is repeated in the direction of an axis, and insertion secession is performed 20times.
3.5.22	Prige Resistance	Termination Resistance (Low Level): MQS 30mΩMax. JPT 10mΩMax. Termination Resistance (Specified Current): MQS 30mV/A Max. JPT 10mV/A Max.	With connector in a fixed position apply "kojiri "around the front edge by 78N force inserting the other in axial and right angle. (Direction: backwards and forwards, right and left.)Pull it out after applying "kojiri" with 2 steps (the 1 st step being the terminals contact and the 2 nd step is when the maximum mating occurs). Repeat this cycle 5times. See Fig.15




Para.	Test Items	Requirements	Procedures
3.5.23	Vibration (High Frequency)	During the vibration, the instantaneous break down of max.1V voltage drop should not be continued 10µsec or more. Termination Resistance (Low Level), Termination Resistance (Specified Current): Same as 3.5.21 Temperature Rise: MQS 30°C Max. JPT 40°C Max.	Vibration Frequency : $10 \sim 50$ Hz/8 min. Accelerated Velocity : 66.6 m/s ² (6.8 G) Vibration Direction :, up and down, back to front, light and left Duration : up and down for 4hours: 100μ A back to front for 2hours: 100μ A light and left for 2hours: $JPT 10A$ See Fig.13. Turn on electricity to the pattern shown in Fig.6
3.5.24	Drop and Impact Resistance	Drop from the following height and to be free from harmful breakage and part loosening. 40P : 0.8m 81P : 0.6m	The plug housing assembled harness should be dropped to the concrete surface 3times in every direction. See Fig.14
3.5.25	Sealing Performance	Send 98kpa compressed and no air leakage or dripping water is allowed	Put the connector into 10cm deep water. Then send 9.8 kpa compressed air for 30seconds. If no air leakage is observed, increase the air pressure by 9.8kpa.
3.5.26	Thermal Resistance	After testing, it should be satisfied under test items. 3.5.2 Termination Resistance (Low Level) 3.5.3 Termination Resistance (Specified Current) 3.5.10 Contact Retention Force 3.5.11 Locking Strength 3.5.25 Sealing Performance	Leave the mated connector at a temperature of 120°C for 120hours.
3.5.27	Termination Current Cycling	After each testing, it should be satisfied under test items. 3.5.2 Termination Resistance (Low Level) 3.5.3 Termination Resistance (Specified Current)	 Follow testing in this order. 3.5.21 Decay Resistance (Insertion and Removal :10times) 3.5.22 Wrench Resistance 3.5.26 Temperature Life 3.5.23 Vibration(High Frequency) (Vibration Direction, Only up and down) 3.5.9 Current Cycle Resistance

Fig.2(End)




3.6 Product Qualification Test Sequence:



Deduct the resistance of "L" long wire used for termination.

Fig.3

Wrap connector with metallic foil.



Between the Adjacent Contacts



Fig.4





Fig.5








Fig.7





Fig.8










Fig.10





Vibration board

Fig.13





Fig.14








Fig.15

tyco Electronics

Part Number Description 1473244 81Pos. Plug Housing Assembly 1473247 81Pos. Lever Assembly (TYPE-A) 1473250 81Pos. Lever Assembly (TYPE-B) 368382-1 81Pos. MQS Retainer for Plug Housing 1473252 40Pos. Plug Housing Assembly 1473255 40Pos. Lever Assembly (TYPE-A) 368388-1 40Pos. MQS Retainer for Plug Housing 1241434-1 121Pos. Cap Housing Assembly 968220-1 MQS Receptacle · Contact Tinning (0.5 mm²) MQS Receptacle Contact Tinning (0.75 mm²) 968221-1 JPT Receptacle · Contact Tinning (0.5 mm²) 964282-2 JPT Receptacle Contact Tinning (0.5~1.0 mm²) 964286-2 964273-2 JPT Receptacle · Contact Tinning (>1.0~2.5 mm²) 963294-1 Wire Seal for JPT (Applicable Insulation Diameter (1.2~2.1mm) 963293-1 Wire Seal for JPT (Applicable Insulation Diameter $\varphi^2 \sim 2.7$ mm) 963292-1 Wire Seal for JPT (Applicable Insulation Diameter (2.7~3mm) 936054-1 Cavity Plug for MQS 828922-1 Cavity Plug for JPT

Appendix.1