3.2x1.6mm SMD CHIP LED LAMP

Part Number: APTL3216QBC/D Blue



ATTENTION OBSERVE PRECAUTIONS FOR HANDLING ELECTROSTATIC DISCHARGE SENSITIVE DEVICES

Features

- 3.2mmx1.6mm SMT LED, 1.1mm thickness.
- Low power consumption.
- Ideal for backlight and indicator.
- Various colors and lens types available.
- Package : 2000pcs / reel.
- Moisture sensitivity level : level 3.
- RoHS compliant.

Description


The Blue source color devices are made with InGaN Light Emitting Diode.

Static electricity and surge damage the LEDS.

It is recommended to use a wrist band or anti-electrostatic glove when handling the LEDs.

All devices, equipment and machinery must be electrically grounded.

Package Dimensions



DRAWN: F.F.Zhou

ERP: 1203006397

CHECKED: Allen Liu

APPROVED: WYNEC

Part No.	Dice	Lens Type	lv (mcd) [2] @ 20mA		Viewing Angle [1]
			Min.	Тур.	201/2
APTL3216QBC/D	Blue (InGaN)	WATER CLEAR	110	300	70°

Notes: 1. θ 1/2 is the angle from optical centerline where the luminous intensity is 1/2 of the optical peak value. 2. Luminous intensity/ luminous Flux: +/-15%.

Electrical / Optical Characteristics at TA=25°C

Symbol	Parameter	Device	Тур.	Max.	Units	Test Conditions
λpeak	Peak Wavelength	Blue	468		nm	I⊧=20mA
λD [1]	Dominant Wavelength	Blue	470		nm	I⊧=20mA
Δλ1/2	Spectral Line Half-width	Blue	25		nm	I⊧=20mA
С	Capacitance	Blue	100		pF	VF=0V;f=1MHz
Vf [2]	Forward Voltage	Blue	3.3	4	V	I⊧=20mA
IR	Reverse Current	Blue		50	uA	VR=5V

Notes: 1.Wavelength: +/-1nm. 2. Forward Voltage: +/-0.1V.


Absolute Maximum Ratings at TA=25°C					
Parameter	Blue	Units			
Power dissipation	120	mW			
DC Forward Current	30	mA			
Peak Forward Current [1]	150	mA			
Reverse Voltage	5	V			
Operating Temperature	-40°C To +85°C				
Storage Temperature	-40°C To +85°C				

Note: 1. 1/10 Duty Cycle, 0.1ms Pulse Width.

SPEC NO: DSAH3796 APPROVED: WYNEC

REV NO: V.5 CHECKED: Allen Liu DATE: MAY/21/2010 DRAWN: F.F.Zhou

PAGE: 2 OF 5 ERP: 1203006397



APTL3216QBC/D

Reflow soldering is recommended and the soldering profile is shown below. Other soldering methods are not recommended as they might cause damage to the product.



