Test Procedure for the NCP690, 1A, LDO





Test Setup:



^{*} During the tests please leave JP1 disconnected.

Figure 1

Required Equipment:

2 x Voltmeters
2 x Ampere meters
DC Power Supply – up to 6V at 1A
Electronic Load

06-MAY-09 Page 1 of 2 www.onsemi.com

Test Procedure for the NCP690, 1A, LDO





Test Procedure:

- 1. Connect the test setup as shown on Figure 1.
- 2. Set the Electronic Load to constant currant mode at 1 amp.
- 3. Apply the Input Voltage of exactly .5 volts higher than the specified output voltage on the silkscreen.
- 4. Verify that the Voltage Regulator turns on and that the output voltage is equal to the required nominal value.
- 5. Turn off the input power supply.
- 6. End of the test.

06-MAY-09 Page 2 of 2 www.onsemi.com