



# PCN - 10 114

Issue Date: April 04 2011

<b>Product Name:</b>	HPL 538, 0.5mm spacing FPC/FFC connector of SFV_S series		
	62674-xx11x1ALF, 62674-xx1121DLF, 62674-xx11x1WALF		
<b>Product Manager:</b>	Shoichi Omote		
<b>Subject:</b>	Process change Notification		
<b>Distribution:</b>	GLOBAL		
<b>Type of Change:</b>	Manufacturing Location Change		
<b>Change Description:</b>	Product Discontinuance		
<b>Reason for Change:</b>	Based on the closedown of Ishioka factory, this product series is transferred to Senai of Malaysia.		
<b>Affected Parts:</b>	See list attached.		
<b>Effective Date of Change:</b>	September	30	2011
<b>Last Time Buy Date:</b>	N/A	N/A	N/A
<b>Last Disty Return Date:</b>	N/A	N/A	N/A
<b>Datasheet Attached?</b>	N/A		
<b>Qual/Test Data Attached?</b>	N/A		
<b>Samples Availability Date:</b>	May	13	2010
<b>Available Alternatives?</b>	No		
<b>Questions?</b>	Contact your local FCI Representative, or		
	Shoichi Omote		
	81-3-5493-5232 / shoichi.omotefci.com		