



Product/Process  
Change  
Notification  
**PCN08114**

<b>Product:</b>	Mini and Maxi PV® CTW Gold Products	<b>Part Numbers Concerned:</b>	See attached list
<b>Product Manager:</b>	Missy Grubb	<b>Issue Date:</b>	August 26, 2008
		<b>Page(s):</b>	1/1
<b>Distribution:</b>	Global		

**Subject:**

Plating change on the backside of the Gold plated Mini and Maxi PV® CTW products FOR PART NUMBERS ENDING IN -000 OR -000LF ONLY (with some minor exceptions which are noted on the spreadsheet).

**Nature of Change:**

FCI will no longer plate the gold flash on the backside of our Mini and Maxi PV® contacts. The gold flash was there to provide aesthetic value. The contacts will continue to be fully plated with nickel. The gold flash will remain inside the contact box along with the appropriate gold plating amount called out of the print for the contact dimples.

**Implementation Date:**

Nov 26 2008

**Distribution:**

No returns will be accepted due to this change.

**Affected Part Numbers:**

See attached spreadsheet for part numbers

**Action Required:**

Sales and distributors to notify customers of this change.

**For questions regarding this PCN contact:**

Missy Grubb

PV® - Product Specialist

Phone: 814-542-5977

Email: [missy.grubb@fci.com](mailto:missy.grubb@fci.com)

Or contact your local FCI sales representative