

Fume Extraction

Tip Extraction Units + FE Irons

FE attachments

A range of FE attachments is availabe to fit to Weller soldering and desoldering irons to convert standard products to fume extraction versions. The attachments are supplied with all necessary fittings and hoses. The performance of the retro fitted tools is not affected.



E Attachment for LR 21, LR 82, TCPS;
E Attachinent for LK 21, LK 82, TCP3,
N 61, W 101, WSP 150 with rest AK 1
E Attachment for WSF 80D5/8
E Attachment for DS 22, DS 80 and DSX 80 desoldering iron

Accessory for FE Irons



Order No. 005 36 352 99	Description Locking clip for extraction hose
005 25 410 00	Extraction hose (spare), by metre



Universal FE attachments

For Weller soldering irons WP 80, WSP 80; WMP, MLR 21 or soldering irons with handle diameter Ø 10–13 mm. Clip will be fasten with an O-ring to the soldering iron.





Order No.	Description
005 29 186 99	FE Attachment with tube, Ø 6 mm for WSP 80, WP 80, MLR 21, MLR 80, WMP
005 29 185 99	FE Attachment with tube, Ø 4,5 mm, for WMRP and WSP 80, WP 80, MLR 21, MLR 80, WMP, for fine soldering applications
005 87 448 75	FE-Clip-Set for FE-attachment, tube Ø 4,5 mm
005 87 448 76	FE-Clip-Set for FE-attachment, tube Ø 6,0 mm
005 15 156 99 WDH 50	Safety rest for soldering iron with FE Attachment

