

RELIABILITY NOTE
OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT
SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.
PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

DRAWN BY:

вс

CHECKED BY: APPROVED BY: DATE:

5.18.04

PAGE:

SCALE:

5mm 635nm RED LED,

WATER CLEAR LENS.