





PRODUCT CHANGE NOTICE

DCS/PCN-1085

Contact Date:	Implementation Date:	Alert Category:	Alert Type:	PCN #:
November 1, 2007	February 1, 2008	Discrete Semiconductor	Potting Conversion	PCN #: 1085
TITLE				
4.0A Bridge Rectifier Conversion from Potted to Molded Construction				
IMPACT				
None Identified, molded construction must meet all High Reliability qualification requirements.				
DESCRIPTION OF CHANGE				
Current potting material is being converted to molding compound due to environmental restrictions in China. Molded construction provides improved package form factor.				
PRODUCTS AFFECTED				
PBL401, PBL403B-D1DT, PBL404, PBL404B-D2DT, PBL405, PBL406. RS401L, RS402L, RS403L, RS404L, RS405L, RS406L, RS407L.				
WEB LINKS				
Manufacturer's Notice:	http://www.diodes.com/products/PCNs.shtml			
For More Information Contact:	http://www.diodes.com/contact/			
Data Sheet:	http://www.diodes.com/index.php			
				<input type="checkbox"/> ATTACHMENTS
DISCLAIMER				
Unless a Diodes Inc. Sales representative is contacted in writing within 30 days of the posting of this notice, all changes described in this announcement are considered approved.				
PCN APPROVAL				
Signatories	Name	Signature	Date	
Signature of Sr. Vice President, Sales & Mktg.	Mark King		1 November 2007	
Signature of VP Corporate Administration	Ed Tang		1 November 2007	