



U1170A Battery Charging Adapter

Description

The Agilent U1170A battery charging adapter allows you to charge the NI-MH rechargeable battery in the Agilent U1252A and U1253A handheld digital multimeter. The NI-MH battery is a standard shipped item for these digital multimeters.
