



CONNECTOR



CONNECTOR TYPE	CABLE TYPE	TOOLS REQUIRED:
OSM STRAIGHT CABLE JACK DIRECT SOLDER ATTACHMENT	.141 SR COAXIAL CABLE	FIXTURE BASE: 2098-5206-54 (T-4567) CLAMP INSERT: 2098-5207-54 (T-4700-1) CENTER CONTACT HOLDER: 2098-5221-10 (T-4578) SOLDER GAGE: 2098-5516-02 (T-4562-5) DIE INSERT TOOL: 2098-5215-02 (T-4551) LOCATOR TOOL: 2098-5210-02 (T-4569)


1.0 PREPARATION OF CABLE.

- 1.1 INSERT SQUARED CABLE END INTO FIXTURE BASE HOLE PATTERN #2.
- 1.2 PLACE SAW IN SAW SLOT AND CUT THROUGH OUTER CONDUCTOR AND INTO DIELECTRIC WHILE ROTATING CABLE.
- 1.3 REMOVE CABLE FROM FIXTURE AND FINISH CUTTING DIELECTRIC WITH CUTTING BLADE.
- 1.4 BARE INNER CONDUCTOR BY PRYING CUT OUTER CONDUCTOR AND DIELECTRIC FROM CABLE.
- 1.5 TRIM CABLE INNER CONDUCTOR TO LENGTH.




2.0 SOLDERING OF CENTER CONTACT TO CABLE INNER CONDUCTOR

- 2.1 TIN INNER CONDUCTOR OF CABLE.
- 2.2 PLACE SOLDER GAGE ON INNER CONDUCTOR, FLUSH WITH END OF OUTER CONDUCTOR.
- 2.3 PLACE CENTER CONTACT IN HOLDER, HEAT CENTER CONTACT AND PUSH IT OVER INNER CONDUCTOR OF CABLE TO REST FIRMLY AGAINST SOLDER GAGE.
- 2.4 REMOVE SOLDER GAGE AND EXCESS SOLDER.



3.0 SOLDERING OF CABLE SUB-ASSEMBLY TO HOUSING SUB-ASSEMBLY.


- 3.1 PLACE CONNECTOR HOUSING ON END OF CABLE SUB-ASSEMBLY.
- 3.2 PLACE LOOSE ASSEMBLY IN FIXTURE BASE AS SHOWN.
 - 3.2.1 NEST CENTER CONTACT IN LOCATOR TOOL.
 - 3.2.2 TIGHTEN CLAMP SCREW TO SECURE CABLE.
 - 3.2.3 TIGHTEN LOCATOR TOOL TO SEAT CABLE FIRMLY.
- 3.3 SLIDE HOUSING OVER LOCATOR TOOL.
- 3.4 MAINTAIN POSITION OF HOUSING FIRMLY AGAINST LOCATOR TOOL AND SOLDER.



NOTE: FIXTURE SHOULD BE CLAMPED VERTICALLY TO KEEP HOUSING SEATED AGAINST LOCATOR TOOL.

4.0 PRESSING OF DIELECTRIC INTO HOUSING
SUB-ASSEMBLY

- 4.1 THREAD INSERT TOOL INTO HOUSING
SUB-ASSEMBLY
- 4.2 INSERT DIELECTRIC INTO INSERT TOOL
HOUSING.
- 4.3 PLACE INSERT TOOL PLUNGER INTO
POSITION AND PRESS UNTIL FLANGE
BOTTOMS ON TOOL HOUSING
- 4.4 ASSEMBLY IS NOW COMPLETE.



NOTES:

INTERFACE DIMENSIONS PER MIL-STD-384A-310-1