

DELTA PARTS NUMBERING SYSTEM

MODELS OTHER THAN POWER ENTRY MODULE TYPES AND P.C. BOARD MOUNTING TYPES



POWER ENTRY MODULE TYPES



DELTA PARTS NUMBERING SYSTEM

3-Phase Types

Input/Output connection:

G = lugs; W = PVC wires; S = screws; T = terminal blocks e.g.
G6 = 6 lugs
W6 = 6 wires
T2: 2 terminal blocks
T1W4: 1 terminal block / 4 wires

Series:
TD: used in "△" system
TDR: used in "△" system, vertical style
TDP: used in "△" system, vertical style
TDS: used in "△" system, vertical style
TDS: used in "△" system, screw style
TY: used in "△" system screw style
TY: used in "△" system, screw style

