



Product Discontinuance Notice - PDN 10_0028 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title: AD9218 - Discontinuation of Select Lead Bearing Models

Publication Date: 19-Mar-2010

Last Time Buy Date: 19-Mar-2011

Last Time Ship Date: 19-Mar-2012

Reason For Discontinuance

Elimination is due to decreased activity of AD9218 in select lead bearing models.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com

Europe: PDN_Europe@analog.com

Japan: PDN_Japan@analog.com

Rest of Asia: PDN_ROA@analog.com

PDN 10_0028 Discontinued Parts Material List

| Model | Product Family | Replacement Part | Pin To Pin Compatible | Comments |
|----------------|----------------|------------------|-----------------------|----------|
| AD9218BST-40 | AD9218 | AD9218BSTZ-40 | Yes | |
| AD9218BST-65 | AD9218 | AD9218BSTZ-65 | Yes | |
| AD9218BST-80 | AD9218 | AD9218BSTZ-80 | Yes | |
| AD9218BST-RL40 | AD9218 | AD9218BSTZ-RL40 | Yes | |
| AD9218BST-RL65 | AD9218 | AD9218BSTZ-RL65 | Yes | |
| AD9218BST-RL80 | AD9218 | AD9218BSTZ-RL80 | Yes | |

| Appendix A - PDN 10_0028 Revision History | | |
|---|--------------|-----------------|
| Rev | Publish Date | Rev Description |
| Rev. - | 19-Mar-2010 | Initial Release |