





Power Resistors

Assembly Method - Power Resistors / 功率电阻组合方式

► Power Resistors Assembly Method



► How to Order



- ① Product Type : DDR Type ; DCR Type
- ② Rated Power : 10W~1300W ; 100W~250W
- ③ Resistance Value (Ω) : (Ω) indicates resistance value in units of ohms.
- ④ Resistance Tolerance :

Code	Resistance Tolerance
J	($\pm 5\%$)
K	($\pm 10\%$)

⑤ Assembly Method

Code	Assembly Method
N	No mount
C	Clip mount.
G	Horizontal mount.
Z	Vertical mount

