

4½ Digit, LCD Display Digital Panel Voltmeters



#### **FEATURES**

- Scientific-grade accuracy, ±2 counts
- Low power, typically 12.5mW
- Miniature size:2.17" x 0.92" x 0.43" (55mm x 23mm x 11mm)
- Large (0.4"/10.2mm), enhanced-contrast, LCD display
- Backlit displays optional
- Epoxy-encapsulated, 12-pin DIP
- Panel or pc-board mountable
- 3 differential, dual, input voltage ranges
- Single +5V supply or 9V battery
- User-selectable decimal point placement
- Low-battery "BAT" annunciator
- 0 to +50°C temperature range
- Low Cost


Offering a unique combination of low cost, scientific-grade accuracy ( $\pm 2$  counts), component-like convenience and outstanding reliability, DMS-40LCD Series  $4\frac{1}{2}$  Digit DPM's provide the ultimate combination of price, precision and convenience. These miniature (2.17" x 0.92" x 0.43") digital voltmeters combine an advanced, autozeroing A/D converter, a precision reference circuit and a large (0.4"/10.2mm high), easy-to-read LCD display in a single, fully encapsulated, 12-pin DIP package. All models incorporate a built-in bezel and are easily mounted in either panels or pc boards.

Each DMS-40LCD meter has a dual-range, differential, input configuration ( $\pm 200\text{mV}/\pm 2\text{V}, \pm 2\text{V}/\pm 20\text{V}$  or  $\pm 20\text{V}/\pm 200\text{V}$ ) and is available with a backlit or non-backlit display. Input impedance is a minimum  $800\text{k}\Omega$ , and CMRR is typically 86dB (dc to 60Hz). CMV is  $\pm 2\text{V}$ , and all models are overvoltage protected to  $\pm 250\text{V}$  (on their non-inverting inputs).

All DMS-40LCD meters are fully functional and operate from a single +5V supply (drawing 3.5mA max.) or a single 9V supply/battery (drawing 2.5mA max.). All models feature autopolarity changeover and overrange indication. A display HOLD function is standard on all non-backlit models.

Thanks to their rugged epoxy-based encapsulation and their advanced, factory-calibrated A/D converters, DMS-40LCD meters are able to withstand the harshest environments and never require adjustment or calibration. Plug-in convenience, long-term stability and wide operating temperature range (0 to  $+50^{\circ}$ C) make DMS-40LCD meters the right solution for any high-accuracy DPM requirement.

#### SIMPLIFIED SCHEMATIC DIAGRAM







- ① R1 = 100k on  $\pm$ 200mV/ $\pm$ 2V (-0/1) models and 909k on all other models. R2 is not used on  $\pm$ 200mV/ $\pm$ 2V (-0/1) models.
  - R2 = 101k on  $\pm 2V/\pm 20V$  (-1/2) models and 9.2k on  $\pm 20V/\pm 200V$  (-2/3) models.
- ② DC/DC converter is not used on 9V-powered models, J1 is connected.
- 3 Hold function is not available on backlit models



www.murata-ps.com

Technical enquiries email: sales@murata-ps.com, tel: +1 508 339 3000



### 4½ Digit, LCD Display Digital Panel Voltmeters


#### **Performance/Functional Specifications**

Typical at  $T_A = +25^{\circ}\text{C}$  and supply voltage = +5V (using the single-ended input circuit) or +9V (using the differential input circuit), unless otherwise noted.

Analog Inputs	Min.	Тур.	Max.	Units		
Full Scale Input Range: ①						
DMS-40LCD-0/1	-	±200/±2	-	mV/V		
DMS-40LCD-1/2	-	±2/±20	-	V/V		
DMS-40LCD-2/3	-	±20/±200	-	V/V		
Input Impedence:						
DMS-40LCD-0/1	100	1000		MΩ		
DMS-40LCD-1/2	0.8	1	-	MΩ		
DMS-40LCD-2/3	0.8	1	-	MΩ		
Overvoltage Protection ②	-	-	±250	Volts		
Common Mode Voltage Range ③	-	-	±2	Volts		
CMRR (dc to 60Hz)	_	86	_	dB		
Control Inputs @						
<b>Decimal Pt. Placement</b> (Pins 4-6, 8): Functionality Logic Compatibility	Tie to pin 3 to activate TTL (on 5V-powered models)					
Hold/Backlight Functionally (Pin 9) Backlit Models Non-backlit Models	Tie to pin 1 to activate Tie to pin 3 to hold reading					
Performance						
Sampling Rate	2.5 reading per second					
Accuracy (1 minute warm-up):						
DMS-40LCD-0/1 (Vin = +0.19/1.9V)	-	±2	±3	Counts		
DMS-40LCD-1/2 (Vin = +1.9V)	-	±2	±3	Counts		
DMS-40LCD-1/2 (Vin = +19V)	-	±3	±4	Counts		
DMS-40LCD-2/3 (Vin = +19/190V)	-	±3	±4	Counts		
Zero Reading (Vin = 0 Volts)	"-001"	"000"	"001"			
<b>Temperature Drift</b> (0 = +50°C) DMS-40LCD-0/1 DMS-40LCD-1/2 DMS-40LCD-2/3	- - -	±0.4 ±0.6 ±0.6	±0.8 ±1 ±1	Cnts/°C Cnts/°C Cnts/°C		
Power Supply Requirements (	5V Mod	els)				
Supply Voltage	+4.75	+5.00	+5.25	Volts		
Supply Current:						
Standard Models	-	+2.5	+3.5	mA		
Backlit Models	-	+37	+45	mA		
Power Supply Requirements (	9V Mod	els)				
Supply Voltage	+7.5	+9.00	+14.0	Volts		
Supply Current:						
Standard Models	_	+1.5	+2.5	mA		
Backlit Models	-	+37	+45	mA		
Display						
Display Type and Size	41/2	4½ digit, 0.4"/10.2mm high LCD				
Polarity Indication	Autopolarity ("-" for negative Vin)					
Overrange Indication	"-1" for negative inputs "1" for positive inputs					

Physical/Environmental						
Operating Temperature	0	-	+50	°C		
Storage Temperature	-20	-	+75	°C		
Humidity (non-condensing)	0	-	95	%		
Case Material	Polycarbonate					
Weight	0.75 ounces (21 grams)					

- ① Each model in the DMS-40LCD Series offers two input voltage ranges that are user-selectable via pin strapping. 5V-powered models can be used to perform either differential or single-ended measurements. 9V-powered models can only be used for differential measurements.
- ② Applies for transient or continuous overvoltages applied to (+) INPUT HI (pin 11) with (-) INPUT LO (pin 12) properly connected. Pin 12 is not overvoltage protected (see Figure 1). Voltages applied to pin 12 should not exceed the supply voltage.
- ③ Listed spec applies to 5V-powered models only. For 9V-powered models, both (–) INPUT LO (pin 12) and (+) INPUT HIGH (pin 11) must always be at least 1.5V above –BATTERY (pin 3) and at least 1.5V below +BATTERY (pin 1).
- See Technical Notes.



Input Ranges: 0/1 = ±200mV/±2V 1/2 = ±2V/±20V 2/3 = ±20V/±200V Power Source: Add -C for RoHS
 Leave blank for standard models. Add **B** for

backlit models.

**5** = +5V **9** = +9V

Accessories:

DMS-30-CP Panel cutout punchDMS-BZL1-C DMS-40 bezel assembly

DMS-BZL2-C DMS-40 bezel assembly with sealing gasket

Application/evaluation board with standard

MOLEX connector, decimal point solder pads

and attenuation resistor pads.

A panel-mount retaining clip is supplied with each model.

#### **TECHNICAL NOTES**

- Input Voltage Range Selection: Each model in the DMS-40LCD Series offers two, user-selectable, input voltage ranges as indicated in the Performance/Functional Specifications Table and the Ordering Information. To select the higher range of any device (such as the ±2V range for the DMS-40LCD-0/1), connect pin 2 (RANGE SELECT) to pin 1 (+5V SUPPLY/+BATTERY). To select the lower range, leave pin 2 open.
- 2. Decimal Point Placement: The location of the decimal point is user-selectable, and the decimal point control pins (DP1-DP4) are active low functions. Select the appropriate decimal point by tying the appropriate pin (pin 4, 5, 6 or 8) to pin 3 (5V RETURN/–BATTERY). Unused decimal point location pins should be left open. For 5V-powered models, the decimal location pins are TTL compatible and may be hard wired as described above or driven with 5V TTL logic gates.



www.murata-ps.com

Technical enquiries email: sales@murata-ps.com, tel: +1 508 339 3000



### 4½ Digit, LCD Display Digital Panel Voltmeters

- 3. Low Battery Annunciator: The "BAT" annunciator in the upper left-hand corner of the display turns on when the supply voltage for 5V-powered models falls below approximately +3.75V or when the supply voltage for 9V-powered models falls below approximately 7.2V. This function can not be disabled.
- 4. HOLD/BACKLIGHT (Pin 9) Function: For non-backlit models, connecting pin 9 (HOLD/BACKLIGHT) to pin 3 (5V RETURN/-BATTERY) will hold (continuously display) the last reading. If not used, pin 9 should be left open for these models.

For backlit models, grounding pin 9 (i.e. connecting it to pin 3) turns on the backlighting LED's. 9V-powered backlit models function with supply voltages up to +14V, however, activating the backlight with voltages greater than 9.2V can damage the meter. Therefore, a 1/4 Watt series resistor must be installed between pins 3 and 9 in these situations. The value of the series resistor is determined using the following formula:

$$Rs_{eries} = \frac{+BATTERY - 9.2V}{0.035}$$
 Ohms

Example: If +BATTERY (pin 1 with respect to pin 3) is +12.6V,

Rseries = 
$$\frac{+12.6 - 9.2V}{0.035}$$
 Ohms

Rseries = 97 Ohms

In any backlit application, including those with supply voltages < 9.2V, the current drawn by the backlight (and therefore the current drawn by the meter) can be reduced by installing a 1/4 Watt resistor between pins 3 and 9. The brightness of the backlight will be reduced proportionately.

- 5. ANALOG COMMON (Pin 10): This pin is connected to an internal, low-noise, "relative" ground. It is used in certain "floating" measurements as described in the Applications section of this data sheet and Ap Note 3 of the DATEL Panel Meter Catalog. Pin 10 should not be connected to pin 3 (5V RETURN/–BATTERY) or to your system's analog ground.
- 6. REFERENCE IN/OUT (Pin 7): This pin accesses the meter's internal reference and is used during the factory calibration procedure. Pin 7 should be left open in most common applications. It can be used in certain "ratiometric" applications in which it is desireable for the meter's reference to track an external reference. See the Applications section of the DATEL Panel Meter Catalog for more details.
- 7. Gain Adjust: There is a gain-adjust potentiometer on the back of each meter. It has approximately ±150 counts of adjustment range. Since these devices essentially have no zero/offset errors, a gain adjustment is effectively an overall accuracy adjustment. Though they may be performed at any point (except zero), accuracy adjustments are most effective when performed with higher level input signals.

8. Soldering Methods: All models in the DMS-40LCD Series easily withstand most common wave soldering operations. We recommend, however, you evaluate the effects your particular soldering techniques may have on the meter's plastic case and high-precision electrical performance. We recommend the use of water-soluble solders and thorough cleaning procedures.

#### 9. Suggested Mating Connectors:

Panel mounted:

Connector housing DATEL P/N 39-2079400

Terminal type DATEL P/N 39-2099090
Crimping tool DATEL P/N 39-2099000
Wire size 22 to 26 AWG

Insulation diameter 0.062" (1.57mm) maximum Stripping length 0.100 to 0.125" (2.54 to 3.17mm)

Board mounted:

Socket DATEL P/N 39-2359625

#### **APPLICATIONS**

DMS-40LCD meters are available in either 5V-powered or 9V-powered models. 9V devices operate directly from 7.5V to 14V supplies (usually batteries) without the need for external voltage regulators. 9V devices, however, can not be used to measure voltages referenced to the negative battery terminal (pin 3) because the minus input to the meter (pin 12, (–) INPUT LO) must always be at least 1.5V above pin 3. 9V-powered meters can only be used to make differential and not single-ended measurements.

5V-powered devices operate from any well-regulated +5V supply and will accurately measure voltages both above and below pin 3 (5V RETURN) in either single-ended or differential configurations.

Single-Ended Input Configurations: True single-ended measurements can only be made with 5V-powered meters. The circuit of Figure 2 avoids problems normally associated with ground loop currents.
 Separate ground runs should be used for 5V RETURN (pin 3) and (–) INPUT LO (pin 12).




Figure 2. Single-Ended Input Configuration (5V-Powered Models)



41/2 Digit, LCD Display Digital Panel Voltmeters

#### **APPLICATIONS**

2. Differential Input Configurations: Differential measurements can be made with either 5V-powered or 9V-powered meters. Figure 3, though not a practical real-world application, uses a voltage divider to demonstrate the concept of a differential input signal. Be careful not to exceed the ±2V common mode voltage limitation for 5V-powered meters.




Figure 3. Differential Input Configuration (5V-Powered Models)

3. Engineering Scaling: For measuring voltages greater than the full scale input range of a given meter, the input signal must be attenuated. A simple voltage divider (similar to that shown in Figure 4) will scale the input to within the range of the selected meter. R1 and R2 should be precision, ±1%, metal film resistors with absolute TCR's less than 50ppm/°C. See Ap Note 4 for more information on engineering scaling.

$$50$$
k $\Omega$  < R1 + R2 <  $10$ M $\Omega$ 

R2

 $R1 + R2$ 
 x V<sub>IN</sub> = Reading




Figure 4. Input Attenuation Circuit

4. Floating Signal Source Measurements: Floating signals can be measured using the circuits shown in Figures 5 and 6. Figure 5 uses a 5V-powered meter. Figure 6 uses a 9V-powered meter. Both figures show a DMS-40LCD-0/1 with pin 2 tied to pin 1 yielding a ±2V input range. Connecting pin 10 (ANALOG COMMON) to (–) INPUT LO (pin 12) provides the reference point for the meter's input.

A "floating" input is a signal that has no galvanic connection to the meter's power supply. In the figures below, the 1.5V battery illustrates a true floating input.




Figure 5. Floating Input Measurements (5V-Powered Models)




Figure 6. Floating Input Measurements (9V-Powered Models)

### 4½ Digit, LCD Display Digital Panel Voltmeters

#### **APPLICATIONS**

5. Process Control (4-to-20mA) Measurements: In many common process-control applications, a 4-to-20mA current loop is used to transmit information. Because DMS-40LCD meters have such high input impedance, a simple shunt resistor across the meter's input can be used to convert the loop current to a voltage. See Figure 7. The value of the shunt resistor is a function of the scaling requirements of the particular application and can be calculated using the following equation:

$$R_{Shunt} = R1 = V_{Fsr}/I_{Fsr}$$

Where: V<sub>Fsr</sub> = Full scale reading (in Volts)

I<sub>Fsr</sub> = Relative full scale current (in Amps)

Example: For a meter with a 2V full scale input (1.999 full scale reading) and a desired full scale display reading of 1000 (with an input of 20mA),  $V_{Fsr} = 1.000 \text{ Volts}$ 

 $R_{Shunt} = 1.000V/(0.020 - 0.004)A$  $R_{Shunt} = 1.000V/0.016A = 62.5 Ohms$ 

To calibrate the circuit of Figure 7, perform the following:

- 1. With 4mA applied, adjust the  $50k\Omega$  potentiometer (R2) to display a reading of "0000" (assuming that is the desired reading).
- With 20mA applied, adjust the gain-adjust potentiometer on the back of the meter to display a reading of "19999".
   For different full scale readings, alter the value of Rshunt accordingly.




Figure 7. 4-to-20mA Current Loop Operation (5V-Powered Models)

6. Power Supply Monitoring: A popular application for DATEL's low-power LCD meters is monitoring the supply voltage in battery-operated portable equipment. Figure 8 demonstrates how a 9V-powered DMS-40LCD can be used to monitor its own supply. The meter used is the DMS-40LCD-0/1-9 configured for its ±2V input range (pin 2 connected to pin 1). A three-resistor voltage divider is used to attenuate the battery voltage and also to satisfy the requirement that the input voltages applied to pins 12 and 11 be at least 1.5 Volts above and below the battery voltage applied to pins 1 (+BATTERY) and 3 (-BATTERY). The divider should be designed so that 1/10th the battery voltage falls across the inputs to the meter.

$$\frac{R2}{(R1 + R2 + R3)} = 0.1$$

Therefore, the 9V battery voltage appears to the meter inputs as 0.9V. With the decimal point moved to its DP2 position (pin 5 tied to pin 3), the meter reads 9.000 Volts.

The circuit can be calibrated by first measuring the actual battery voltage with another meter and then adjusting the gain-adjust potentiometer on the back of the DMS-40LCD until a similar reading is obtained. If possible, the resistors in the divider should be  $\pm 1\%$  metal-film types with TCR's less than 50ppm/°C.




Figure 8. Power Supply Monitor (9V-Powered Models)





4½ Digit, LCD Display Digital Panel Voltmeters

#### **MECHANICAL SPECIFICATIONS**

MECHANICAL DIMENSIONS: Inches (mm) TOLERANCES: 2 PL DEC ±0.02 (±0.51) 3 PL DEC ±0.010 (±0.254) LEAD DIMENSIONS: 0.025 (0.635) x 0.025 (0.635) NOMINAL RECOMMENDED PC BOARD FINISHED HOLE DIAMETER: ASU NI EDAM 0.042 ±0.003 (1.067 ±0.076) CALIBRATION POTENTIOMETER HOLE LOCATION FRONT VIEW 12 (-) INPUT LO 11 (+) INPUT HI 10 ANALOG COMMON 9 HOLD/BACKLIGHT +5V SUPPLY/ +BATTERY RANGE SELECT 5V RETURN/-BATTERY DP3 DP2 REFERENCE IN/OUT DP1 DP3 DP4 0.125 (3.175) DIAMETER (USE ONLY WHEN PC BOARD MOUNTING) 0.430 (10.92) STANDARD 0.560 (14.22) BACKLIT 0.25 (6.4) TYF 0.040 (1.02) 1.80 (45.7)

#### BEZEL INSTALLATION AND RECOMMENDED DRILL AND PANEL CUTOUT







Murata Power Solutions. Inc.

11 Cabot Boulevard, Mansfield, MA 02048-1151 U.S.A.

Tel: (508) 339-3000 (800) 233-2765 Fax: (508) 339-6356

www.murata-ps.com email: sales@murata-ps.com ISO 9001 and 14001 REGISTERED

Murata Power Solutions, Inc. makes no representation that the use of its products in the circuits described herein, or the use of other

technical information contained herein, will not infringe upon existing or future patent rights. The descriptions contained herein do not imply the granting of licenses to make, use, or sell equipment constructed in accordance therewith. Specifications are subject to change without notice.

© 2008 Murata Power Solutions, Inc. USA: Mansfield (MA), Tel: (508) 339-3000, email: sales@murata-ps.com

Canada: Toronto, Tel: (866) 740-1232, email: toronto@murata-ps.com UK: Milton Keynes, Tel: +44 (0)1908 615232, email: mk@murata-ps.com

France: Montigny Le Bretonneux, Tel: +33 (0)1 34 60 01 01, email: france@murata-ps.com

Germany: München, Tel: +49 (0)89-544334-0, email: munich@murata-ps.com Tokyo, Tel: 3-3779-1031, email: sales\_tokyo@murata-ps.com Japan:

> Osaka, Tel: 6-6354-2025, email: sales\_osaka@murata-ps.com Shanghai, Tel: +86 215 027 3678, email: shanghai@murata-ps.com

Guangzhou, Tel: +86 208 221 8066, email: guangzhou@murata-ps.com

Singapore: Parkway Centre, Tel: +65 6348 9096, email: singapore@murata-ps.com



www.murata-ps.com

China:

Technical enquiries email: sales@murata-ps.com, tel: +1 508 339 3000